

Project No./Contract No.	Project Title / Location	Day of Report	Report No.
6389	BRC Eastside Common Areas Soils Remediation	03-Jun-09	324

Position	Name	E-Mail Address	Phone No.
BRC PROJECT MANAGER	Lee Farris	lfarris@landwellco.com	702-567-0400
BRC PROJECT MANAGER	Ranjati Sahu	sahuron@earthlink.net	702-567-0400
CONST. PROJECT MANAGER	Dan Brennecke	Dan.Brennecke@westonsolutions.com	970-260-5886
Construction Manager	Richard Laubinger	Richard.Laubinger@westonsolution.com	720-641-5666

Conditions				Temp (°F)		Wind		Add'l Readings	
AM	Sunny / Partly Cloudy	PM	Cloudy / Partly Sunny	Low	71			Precip. (in/hr)	0
				High	97	SW	18	Humidity (%)	0
Additional Weather Comments									
Wind 5 - 18 mph.									

[illegible]

Name	Position	Trade / Work Performed	Y/N
Greg Corcoran	Design Engineer	Oversight	N
Dan Street	QA Manager	Oversight	N
Jim Cox	QA/QC Supervisor	N Oversight	N
Rebecca Flynn	Engineer	Oversight	N
Stuart Irwin	QA/QC Tech	Oversight	Y
Roland Derosier	QA/QC Tech	Oversight	Y
Camron Liddell	QA/QC Tech	Oversight	Y
Victor Heredia	QA/QC Tech	Oversight	Y

Name	Position	Trade / Work Performed	Y/N
Doug Herlocker, Tetra Tech	Air Monitoring Specialist	Air Monitoring	Y
Becky Dano, Tetra Tech	Air Monitoring Specialist	Air Monitoring	N
Jerry Fauchaux, Tetra Tech	Air Monitoring Specialist	Air Monitoring	N

Name	Position	Trade / Work Performed	Y/N
Bob Meyer, ASW	Inspector	Linear Inspector,	Y
Devin Gordon, MGA	Oversight	For NDEP	Y
Deck Kim, ATC	Field Observation	For AIG	Y
Brian Rakvica	Inspector	NDEP	N
Steve Morrow, ASW	Inspector	Linear Inspector	N
PBS&J Survey	Surveyors	Survey	N

Name	Company	Trade / Work Performed	Y/N
Erik Geringer	Entact	Project Manager	Y
Jeremy Schissler	Entact	Acting Project Manager	Y
Josh Carrol	Entact	Asst Project Manager	Y
Michael Carlson	Entact	Engineer	Y
Joe Curilla, Day	Entact	Health & Safety Officer	Y
Timothy Stad, Day	Entact	Health & Safety Officer	Y
Roger Wagner, Night	Entact	Eastside, Superintendent	Y
Ed Long, Day	Entact	CAMU, Superintendent	Y
Lance Bruce, Nights	Entact	Health & Safety Officer	Y
Terry Harper, Night	Entact	CAMU, Superintendent	Y
Rick Morine	Entact	CSP, Health & Safety	Y
John Frazier, Nights	Entact	Health & Safety Officer	Y
Eli Blackburn	Entact	Asst Project Manager	Y
Scott Zattau, Day	Entact	Health & Safety Technician	Y
Jose Martinez, Night	Entact	Health & Safety Technician	Y
Dawn Breedlove, Night	Entact	Health & Safety Technician	Y
Russell Karnes	Entact	Superintendent, Additional Tasks, Southern Rib, etc.	Y
	Environmental Specialties, Inc.	Liner Crew, (1) Supt, 9 Laborers/ Seamers	Y
	ABC Survey	Eastside/CAMU	N

[illegible]

Material	Vendor	Today	UOM	Purpose	Delivery Verification			
					to date	Qty	Spec	Tags
GCL	CETCO	0	rolls	For CAMU, On site		1924		
Geocomposite	Agru	0	rolls	For CAMU, On site		2442		
Geomembrane	Agru	0	rolls	For CAMU, On site		558		

DAILY PRODUCTION & QUALITY CONTROL REPORT			
Project No./Contract No.	Project Title / Location	Day of Report	Report No.
6389	BRC Eastside Common Areas Soils Remediation	03-Jun-09	324
Description of Work Executed Today			
<u>Eastside Mixing and Drying Activity:</u>			
<u>Day Shift:</u>			
- SC-1, continued hauling wet material to HP-5 for drying.			
- N Beta Ditch, continued excavating and hauling to Beta ditch staging area.			
- Began final scrape with excavator on the east haul rd to N Beta Ditch.			
- PUC-5 & 6 dry ponds continued excavating with long stick excavator and stockpiling.			
- Dozer discing ponds drying out wet material.			
- New sewer alignment crossing installed fence posts.			
- Western Hook, continued scraping up trash and debris from ditches and stockpiling.			
- Southern Rib, continued loading out soils in OTR trucks and hauling to Phase II in CAMU.			
- SW-12 pH: 6.			
<u>Night Shift:</u>			
- Hauled material from Beta Ditch staging area and WST-4 stockpile.			
<u>CAMU Activity:</u>			
<u>Day Shift</u>			
- NE-1, NE-2, Silt trenches continued loading and hauling to Phase II for placement.			
- SW-1, Silt trench surveyed and began backfilling trench.			
- NE-2, Silt trench, finished breaking up yellow cementous material with hoe ram, also sized concrete sections of wing wall inside Phase II landfill.			
- Phase IIIA, installing interim cover on south slope.			
- Phase II, D6 dozer and vibratory roller worked on southwest slope, continued.			
- Received waste from Southern Rib and placed in Phase II.			
- GES collected water samples in monitoring well next to Phase I, also Phase II LCRS.			
- Entact did not measure or pump today.			
<u>Night Shift</u>			
- Continued placing material in Phase II and Phase IIIA.			
<u>Embankment</u>			
- Phase 1 embankment, complete.			
- Phase 1 estimated cumulative embankment placed:			
- Phase II embankment , complete.			
<u>Sump/Vadose Monitoring</u> Phase 1: LCRS Sump: Measurement taken: (N/A) Water Pumped: (NA)			
Vadose: Measurement taken: (N/A) Water Pumped: (N/A)			
Phase II: LCRS Sump: Measurement taken: (N/A) Water Pumped: (N/A)			
Vadose: Measurement taken: (NA) Water pumped: (NA)			
<u>Inspections:</u> CAMU: Weston monitored sump access. For water sampling.			
Project No.: 6389 Contract No.: 6389-0000			

Estimated Waste Placement (Estimated volumes do not account for shrinkage due to loss of moisture on wet ponds)

Phase I	
Previous Daily Cumulative =	291,200 cy
Operations layer placed (completed) for liner certification. = 21,662	0 cy
Daily Day shift waste placed today: Phase IV,V scape & Phase IIIB trench excavation. 0 loads @ 20 cy/load (0 trucks) =	0 cy
Daily Night shift placed today: 0 loads @ 18cy/load (0 trucks) =	0 cy
To Date Phase I estimated cumulative waste placed = 291,200 cy	
Phase II	
Previous Daily Cumulative =	688,926 cy
Operations layer placed (completed) for liner certification. = 37,188	0 cy
Daily Day shift waste placed today: Parcel 4B/Mohawk Drive/Southern Ribs: (70) loads @ 18 cy/load (10) trucks =	1,260 cy
Daily Day shift waste placed today: Silt Trenches, (114) loads @ 18cy/load (5) trucks =	2,052 cy
Daily Night shift placed today: (143) loads @ 18cy/load (20) trucks =	2,574 cy
To Date Phase II estimated cumulative waste placed = 694,812 cy	
Phase IIIA	
Previous Daily Cumulative =	159,804 cy
Operations layer placed directly in Phase IIIA today: (0) loads @ 18 cy/load (0) trucks =	0 cy
Operations layer placed (completed for liner certification = 21,276)	0 cy
Daily Day shift waste placed today: From Phase IIIB. (0) loads @ 18 cy/load (0) trucks =	0 cy
Daily Night shift waste placed today: (149) loads @ 18cy/load (20) trucks =	2,682 cy
To Date Phase IIIA estimated cumulative waste placed = 162,486 cy	
Phase IIIB	
Previous Daily Cumulative =	21,978 cy
Operations layer placed (completed) for liner certification. = 21,978	0 cy
Daily Day shift waste placed today: From ?? (0) loads @ 18 cy/load (0) trucks =	0 cy
Daily Night shift waste placed today: (0) loads @ 18cy/load (0) trucks =	0 cy
To Date Phase IIIA estimated cumulative waste placed = 21,978 cy	

		Estimated Waste at Completion (cy)	% Complete
Cumulative Total To Date All Phases =		1,170,476 cy	57.1%

Geosynthetics Placed

	Previous	Placed	Cummulative
Phase I (complete)			
GCL	307,372	0	307,372
Geomembrane	307,372	0	307,372
Geocomposite	307,372	0	307,372
Geotextile	69,340	0	69,340
Phase II (complete)			
GCL	498,468	0	498,468
Geomembrane	498,468	0	498,468
Geocomposite	520,592	0	520,592
Geotextile	0	0	0
Phase IIIA			
GCL	221,000	0	221,000
Geomembrane	221,000	0	221,000
Geocomposite	221,000	0	221,000
Geotextile	20,000	0	20,000
Phase IIIB			
GCL	340,535	0	340,535
Geomembrane	340,535	0	340,535
Geocomposite	340,535	0	340,535
Geotextile	50,000	0	50,000
Phase IV			
GCL	0	0	0
Geomembrane	0	0	0
Geocomposite	0	0	0
Geotextile	0	0	0
Phase V			
GCL	0	0	0

DAILY PRODUCTION & QUALITY CONTROL REPORT

Project No./Contract No.	Project Title / Location	Day of Report	Report No.
6389	BRC Eastside Common Areas Soils Remediation	03-Jun-09	324

Geomembrane	0	0	0
Geocomposite	0	0	0
Geotextile	0	0	0

BMI North

GCL	1,111,468	0	1,111,468
Geomembrane	1,111,468	0	1,111,468
Geocomposite	1,111,468	0	1,111,468

BMI South

GCL	177,000	0	177,000
Geomembrane	177,000	0	177,000
Geocomposite	177,000	0	177,000

Debris Storage Area (complete)

Geomembrane	12,000	0	12,000
-------------	--------	---	--------

CAMU Cover

GCL	0	0	0
Geomembrane	0	0	0
Geocomposite	0	0	0

		Total Geosynthetics for CAMU Basic Scope (\$)	% Complete of Basic Scope	Total Geosynthetics for CAMU Basic Scope +Option Scope	% Complete of Basic Scope + Option Scope
Geosynthetic System Cumulative Total To Date All CAMU	2,655,843	4,151,232	64.0%	6,534,075	40.6%

HEALTH & SAFETY

Description of Health & Safety Actions Taken Today / Safety Inspections Conducted	
1	1. Inspected the site for safety hazards and identified areas for improvement.
2	2. Conducted safety training for all employees on proper lifting techniques.
3	3. Reviewed the company's safety policies and procedures to ensure compliance.
4	4. Identified and addressed safety concerns raised by employees during the inspection.
5	5. Implemented corrective actions to eliminate identified safety hazards.
6	6. Scheduled a follow-up inspection to monitor progress and ensure ongoing safety.
7	7. Documented all findings and actions taken in the safety log.
8	8. Communicated the results of the inspection to all employees and management.
9	9. Provided additional safety resources and materials to employees.
10	10. Reviewed the incident report and discussed preventive measures.
11	11. Conducted a safety meeting to reinforce key safety messages.
12	12. Identified areas for further safety improvement and set goals for the future.
13	13. Ensured all safety equipment was properly maintained and calibrated.
14	14. Reviewed the safety data and trends to identify potential risks.
15	15. Implemented new safety protocols based on the inspection findings.
16	16. Provided feedback to employees on their safety performance.
17	17. Conducted a thorough review of the safety incident and its root causes.
18	18. Ensured all safety training was up-to-date and relevant.
19	19. Reviewed the safety record and identified areas for continuous improvement.
20	20. Implemented measures to prevent recurrence of the safety incident.
21	21. Conducted a safety audit to ensure compliance with all regulations.
22	22. Provided safety resources and materials to all employees.
23	23. Reviewed the safety data and trends to identify potential risks.
24	24. Implemented new safety protocols based on the inspection findings.
25	25. Provided feedback to employees on their safety performance.
26	26. Conducted a thorough review of the safety incident and its root causes.
27	27. Ensured all safety training was up-to-date and relevant.
28	28. Reviewed the safety record and identified areas for continuous improvement.
29	29. Implemented measures to prevent recurrence of the safety incident.
30	30. Conducted a safety audit to ensure compliance with all regulations.
31	31. Provided safety resources and materials to all employees.
32	32. Reviewed the safety data and trends to identify potential risks.
33	33. Implemented new safety protocols based on the inspection findings.
34	34. Provided feedback to employees on their safety performance.
35	35. Conducted a thorough review of the safety incident and its root causes.
36	36. Ensured all safety training was up-to-date and relevant.
37	37. Reviewed the safety record and identified areas for continuous improvement.
38	38. Implemented measures to prevent recurrence of the safety incident.
39	39. Conducted a safety audit to ensure compliance with all regulations.
40	40. Provided safety resources and materials to all employees.
41	41. Reviewed the safety data and trends to identify potential risks.
42	42. Implemented new safety protocols based on the inspection findings.
43	43. Provided feedback to employees on their safety performance.
44	44. Conducted a thorough review of the safety incident and its root causes.
45	45. Ensured all safety training was up-to-date and relevant.
46	46. Reviewed the safety record and identified areas for continuous improvement.
47	47. Implemented measures to prevent recurrence of the safety incident.
48	48. Conducted a safety audit to ensure compliance with all regulations.
49	49. Provided safety resources and materials to all employees.
50	50. Reviewed the safety data and trends to identify potential risks.
51	51. Implemented new safety protocols based on the inspection findings.
52	52. Provided feedback to employees on their safety performance.
53	53. Conducted a thorough review of the safety incident and its root causes.
54	54. Ensured all safety training was up-to-date and relevant.
55	55. Reviewed the safety record and identified areas for continuous improvement.
56	56. Implemented measures to prevent recurrence of the safety incident.
57	57. Conducted a safety audit to ensure compliance with all regulations.
58	58. Provided safety resources and materials to all employees.
59	59. Reviewed the safety data and trends to identify potential risks.
60	60. Implemented new safety protocols based on the inspection findings.
61	61. Provided feedback to employees on their safety performance.
62	62. Conducted a thorough review of the safety incident and its root causes.
63	63. Ensured all safety training was up-to-date and relevant.
64	64. Reviewed the safety record and identified areas for continuous improvement.
65	65. Implemented measures to prevent recurrence of the safety incident.
66	66. Conducted a safety audit to ensure compliance with all regulations.
67	67. Provided safety resources and materials to all employees.
68	68. Reviewed the safety data and trends to identify potential risks.
69	69. Implemented new safety protocols based on the inspection findings.
70	70. Provided feedback to employees on their safety performance.
71	71. Conducted a thorough review of the safety incident and its root causes.
72	72. Ensured all safety training was up-to-date and relevant.
73	73. Reviewed the safety record and identified areas for continuous improvement.
74	74. Implemented measures to prevent recurrence of the safety incident.
75	75. Conducted a safety audit to ensure compliance with all regulations.
76	76. Provided safety resources and materials to all employees.
77	77. Reviewed the safety data and trends to identify potential risks.
78	78. Implemented new safety protocols based on the inspection findings.
79	79. Provided feedback to employees on their safety performance.
80	80. Conducted a thorough review of the safety incident and its root causes.
81	81. Ensured all safety training was up-to-date and relevant.
82	82. Reviewed the safety record and identified areas for continuous improvement.
83	83. Implemented measures to prevent recurrence of the safety incident.
84	84. Conducted a safety audit to ensure compliance with all regulations.
85	85. Provided safety resources and materials to all employees.
86	86. Reviewed the safety data and trends to identify potential risks.
87	87. Implemented new safety protocols based on the inspection findings.
88	88. Provided feedback to employees on their safety performance.
89	89. Conducted a thorough review of the safety incident and its root causes.
90	90. Ensured all safety training was up-to-date and relevant.
91	91. Reviewed the safety record and identified areas for continuous improvement.
92	92. Implemented measures to prevent recurrence of the safety incident.
93	93. Conducted a safety audit to ensure compliance with all regulations.
94	94. Provided safety resources and materials to all employees.
95	95. Reviewed the safety data and trends to identify potential risks.
96	96. Implemented new safety protocols based on the inspection findings.
97	97. Provided feedback to employees on their safety performance.
98	98. Conducted a thorough review of the safety incident and its root causes.
99	99. Ensured all safety training was up-to-date and relevant.
100	100. Reviewed the safety record and identified areas for continuous improvement.

Safety Topic:

Eastside Day: Discussed Seat belts, watch out for other drivers.

CAMU Day: Discussed Seat belts, watch out for other drivers.

Night shift CAMU & Eastside: Discussed Professional radio use and proper conduct at work.

CONSTRUCTION QUALITY ASSURANCE & QUALITY CONTROL

Description of Quality Control Actions Taken Today / Quality Inspections Conducted	
<p>1. Inspected the foundation and framing of the building, ensuring all structural elements are in place and properly aligned.</p> <p>2. Checked the electrical wiring and plumbing fixtures, ensuring they are installed correctly and meet safety standards.</p> <p>3. Verified the placement and quantity of materials, ensuring they are consistent with the project specifications.</p> <p>4. Conducted a visual inspection of the exterior walls and roofline, identifying any potential issues or damage.</p> <p>5. Reviewed the construction schedule and progress, ensuring that all tasks are completed on time.</p>	

Daily CQA Summary.

Monitored waste placement into the CAMU of eastside materials on the night shift.

Monitored waste placement into the CAMU of slit trench and eastside materials on the day shift.

Monitored placement of interim cover soils at the Phase IIIA landfill on the day shift.

Monitored backfill operations in Phase IV on the day shift.

Continue updating of project documents and review of database to facilitate reporting

ISSUES AND/OR ITEMS OF DISCUSSION

Discussion of Issues / Concerns / Conversations / Topics

Contractor was reminded of dust control responsibilities and to cut down on activities if needed to control it.

SITE VISITORS

[illegible]

Report Prepared By / Title

Date Prepared

Signature _____

Richard Laubinger, Construction Manager

3-Jun-09

Weather Table

Sunny/Clear	☀
Sunny / Partly Cloudy	☂
Cloudy / Partly Sunny	☁
Cloudy	☁
Overcast	☁
Light Rain	☔
Rain	☔
Thunderstorms	⚡
Snow	❄

Basic Remediation Company

875 West Warm Springs Road
Henderson, Nevada 89011

DAILY PRODUCTION & QUALITY CONTROL REPORT

Project No./Contract No.	Project Title / Location	Day of Report	Report No.
6389 0	BRC Eastside Common Areas Soils Remediation 0	03-Jun-09	324

DAILY PHOTO LOG

Photo 1



CAMU: SW-1, Slit trench, backfilling.

Photo 2



CAMU: NE-2, Slit trench

Photo 3



CAMU: NE-2, Slit trench, yellow material being sized.

Photo 4



CAMU: NE-1, Slit trench.