Basic Remediation Company 875 West Warm Springs Road Henderson, Nevada 89011



DAILY PRODUCTION & QUALITY CONTROL REPORT

Project No./Contract No.	Project Title / Location	Day of Report	Report No.
6389	BRC Eastside Common Areas Soils Remediation	12-Dec-08	156
		12-Dec-08	156

PROJECT POINTS OF CONTACT						
Position	Name	E-Mail Address	Phone No.			
BRC PROJECT MANAGER	Lee Farris	lfarris@landwellco.com	702-567-0400			
BRC PROJECT MANAGER	Ranajit Sahu	sahuron@earthlink.net	702-567-0400			
CONST. PROJECT MANAGER	Dan Brennecke	Dan.Brennecke@westonsolutions.c	970-260-5886			
Construction Manager	Richard Laubinger	Richard.Laubinger@westonsolution	720-641-8660			

Conditions			Temp (F)		Wind		Add'l Readings	
AM Cloudy / Partly Sunny	PM Cloudy / Partly Sunny	Olavedia / Davidia Oversia	Low	40			Precip. (In/Dy.)	
		High	63	NE	7mph	Humidity (%)		

0 mph, in AM. 5 - 10 mph in PM.

Name	Position	Trade / Work Performed	Y/N
Dick Laubinger	Construction Manager	Construction Management Services.	Y
Dan Brennecke	Project Manager. CM	Construction Management Services.	N
Richard Davis	Project Engineer	Construction Management Services.	Y
Chris White	Assist. Const. Mgr	Construction Management Services.	Y
Wayne Hodgson	Assist. Const. Mgr	Construction Management Services.	Y
Kevin Cooke	Assist. Const. Mgr	Construction Management Services.	Y
June Laubinger	Admin Assistant	Construction Management Services.	Y

Name	Position	Trade / Work Performed	Y/N
Greg Corcoran	Design Engineer	Oversight	N
Dan Street	QA Manager	Oversight	Y
Jim Cox	QA/QC Supervisor	Oversight	N
Robecca Flynn	Engineer	Oversight	N
Wayne Wofford	QA/QC Tech	Oversight	Y
Roland Derosier	QA/QC Tech	Oversight	Υ
Camon Liddell	QA/QC Tech	Oversight	Υ
Jeremy Osborn	QA/QC Tech	Oversight	Y
		-	

	P :::	T 1 (W 1 D 7)	1	
Name	Position	Trade / Work Performed	Y/N	
Doug Herlocker, Tetra Tech	Air Monitoring Specialist	Air Monitoring,	N	Г
Becky Dano, Tetra Tech	Air Monitoring Specialist	Air Monitoring,	Y	
Jerry Faucheux, Tetra Tech	Air Monitoring Specialist	Air Monitoring	N	
				-

Name	Position	Trade / Work Performed	Y/N
Mark Eizman, ASW	Inspector	Liner Inspector	Y
Devin Gordon, McGinley	Oversight	For NDEP	Y
Dock Kim, ATC	Field Observation	For AIG	Y
Joe Ludlow, ASW	Inspector	Liner Inspector	N
Steve Morrow, ASW	Inspector	Liner Inspector	N
Brian Rakvica	Inspector	NDEP .	Y
PBS&J, Survey	Surveyors	Surveying, QA	N

Steve Morrow, ASW	Inspector	Liner inspector	IN I
Brian Rakvica	Inspector	NDEP .	Υ
PBS&J, Survey	Surveyors	Surveying, QA	N
ON-SITE CONTRACTO	R PERSONNEL		
Name	Company	Trade / Work Performed	Y/N
Erik Geringer	Entact	Project Manager	Y
Josh Carrol	Entact	Asst Project Manager	Y
Russ Karnes	Entact	Eastside, Superintendent	Υ
Michael Carlson	Entact	Engineer	Υ
Joe Curilla	Entact	Health & Safety Officer	Υ
Timothy Stadt	Entact	Health and Safety Technician	Υ
	Entact	26 Equipment Operators & Truck Drivers	Y
Ed Long	Entact	CAMU, Superintendent	Y
Lance Bruce	Entact	Health & Safety Officer	Y
Terry Harper	Entact	CAMU, Superintendent	Υ
Rick McIntire	Entact	CSP, Safety	N
Dale Walsh	Converse	CSP, Safety	Υ

Ver 1.1 11/07 1 of 4

DAILY PRODUCTION & QUALITY CONTROL REPORT

Project No./Contract No.	Project Title / Location	Day of Report	Report No.
6389	BRC Eastside Common Areas Soils Remediation	12-Dec-08	156
		12-060-06	130

Eli Blackburn		Asst Project Manager	Υ	
	Environmental Specialties,Inc	1 Liner Superintendent	Υ	
	Environmental Specialties,Inc	12 Laborers/ Seamers	Y	
	Kenney Survey	CAMU	N	
	ABC Survey	Eastside/CAMU	N	
			_	

Cavinment	Vendor / Tag No.	Work Performed				
Equipment	vendor / rag No.					
CAT D400E Dump Truck (10)		CAMU	-	-	-	
JD D400 Dump Trucks (9)		Eastside		-	-	
CAT 324D long stick excavator		CAMU		-	-	
CAT D8R Dozer with disc		Eastside		-	-	
CAT 345 excavator, (3)		Eastside		-	-	
CAT 330 Excavator		Eastside		-	-	
Case double pan scrapers.		Eastside		-	-	
CAT D6 LGP Dozer (1)		Eastside				
Water Trucks (2)		Eastside				
637/631 Cat Scrapers (2)		CAMU				
CAT 16H Grader		CAMU				
CAT D-10 Dozer		CAMU				
CAT Water Trucks (2)		CAMU				
CAT D-6 Dozer, (2)		CAMU				
CAT 14H Grader		CAMU				
Gradall		CAMU				
JLG		CAMU				
IR Smooth drum Roller		CAMU, Phase 1				
Tenent Street Sweeper		Eastside and CAMU				
Bomag Smooth drum Roller		CAMU, Phase 1				
Chieftain 1400 Powerscreener		Eastside, screening 1" minus				

MATERIAL HANDLING	(ON-SITE DELIVERY / REMOVA	AL)						
Material	Vendor	Today	UOM	Purpose	Delivery Verification			
waterial	Velidoi	Today	OCIVI	Purpose	to date Qty	Spec Tac		
GCL	CETCO	0	rolls	For CAMU, On site	506			
Geocomposite	Agru	0	rolls	For CAMU, On site	599			
Geomembrane	Agru	0	rolls	For CAMU, On site	192			

WORK COMPLETED

Eastside Mixing and Drying Activity:

- Day Shift:
- Continued powerscreening material from (WST-8).
- Watered PUC-3 & 4.
- Worked on tarps and rails for haul trucks.
- Night Shift:
- No Activity.

CAMU Activity:

- Day Shift:
- ESI continued installing GCL and geomembrane on North BMI Landfill.
- Completed backfilling anchor trench for Phase II.
 Continued grading North BMI Landfill.
 Prepare site for upcoming rain next week.

- Night Shift:
- No Activity.

- Phase 1 embankment, complete.
- Phase 1 estimated cummulative embankment placed: 0 cy
- Phase II embankment, complete.

Waste Placement

- Phase 1 estimated daily waste placed: 0 loads @ 20cy/load = 0 cy.

 night shift placed: 0 loads @ 18cy/load = 0 cy. (0 trucks).

 Phase 1 estimated cummulative waste placed: 223,570 cy. Western Ditch, NE Equilization, Eastside beta stockpile and PUA-4.PUB-3.

 Phase 1 Operations Layer placed. completed. Cumulative total: 21,662
- Phase 2 estimated night shift placed: 0 loads @ 18cy/load = 0 cy.
- Phase 2 Operations Layer placed. daily: 0 cy. Adjusted cy per truckload from 20cy to 18cy based on survey. Cumulative total: 37,188 cy.

Geosynthetics. Estimated cummulative installed quantity by Phase.

- Phase 1 GCL placed:0 sf daily, 307,372 sf cummulative.
- Phase 1 Geomembrane:0 sf daily, 307,372 sf cummulative

DAILY PRODUCTION & QUALITY CONTROL REPORT

Project No./Contract No.	Project Title / Location	Day of Report	Report No.
6389	BRC Eastside Common Areas Soils Remediation	12-Dec-08	156

Phase 1 Geocomposite: 0 sf daily, 307,372 sf cummulative.

Phase 1 Geotextile: (0) sf daily. 69,340 sf cummulative.

-Phase 2 GCL placed: (0) sf daily, 498,468 sf cummulative. -Phase 2 Geomenbrane: (0) sf daily, 498,468 sf cummulative.

-Phase 2 Geocomposite: (0) sf daily, 520,592 sf cummulative.

-BMI North Landfill GCL placed: 47,142 sf daily, 330,638 sf cummulative.
-BMI North Landfill Geomembrane: 47,142 sf daily, 330,638 sf cummulative.
-BMI North Landfill Geocomposite: (0) sf daily, (0) sf cummulative.

Other: Sinkhole encountered on BMI North Landfill. Proper notifications made. Entact bacfilled and compacted.

HEALTH & SAFETY

Description of Health & Safety Actions Taken Today / Safety Inspections Conducted

Entact H&S Tailgates

Safety Topic: Eastside: Discussed wearing the proper PPE around the site.

Safety Topic: CAMU, Day: Discussed wearing the proper PPE around the site.

Eastside and CAMU, Night shift: No Activity.

Safety Incidents: None.

Dust Incidents: None.

CONSTRUCTION QUALITY ASSURANCE & QUALITY CONTROL

ption of Quality Control Actions Taken Today / Quality Inspections Conducted

Daily CQA Summary..

Monitored installation of geosynthetics at the BMI North Landfill on the day shift.

Inspected BMI North Landfill subgrade for liner.
Continued review of and updating of project documents and database to facilitate reporting.

Monitored backfill compaction of sinkhole encountered on BMI North Landfill.

ISSUES AND/OR ITEMS OF DISCUSSION

Brian Rakvica, NDEP,Devin Gordon, McGinley & Associates. Lee Farris, BRC, Ron Sahu, BRC on site, inspected Phase IIIB area at CAMU.

	为是15年的15年,1953年,1964年,1964年,1964年,1964年,1964年,1964年,1964年,1964年,1964年,1964年,1964年		
Organization	Purpose of Visit		
Par Electric	CAMU site visit in regards to power pole removal.		
		-	
		_	
		-	
		1	
		-	

Report Prepared By / Title

Date Prepared

Signature

Dick Laubinger, Construction Manager

12-Dec-08

3 of 4 Ver 1.1 11/07

Basic Remediation Company 875 West Warm Springs Road Henderson, Nevada 89011

DAILY PRODUCTION & QUALITY CONTROL REPORT

Project No./Contract No.	Project Title / Location	Day of Report	Report No.
6389	BRC Eastside Common Areas Soils Remediation	10 Dec 08	156
0	0	12-Dec-08	

DAILY PHOTO LOG

Photo 1



CAMU: BMI North Landfill Cap, Sink hole found while compact rolling.

Photo 2



CAMU: BMI North Landfill Cap. Sink hole excavated.

Photo 3



Photo 4



CAMU: BMI North Landfill, southwest corner prepared for rain.

Ver 1.1 11/07 4 of 4