# Basic Remediation Company 875 West Warm Springs Road Henderson, Nevada 89011



DAILY PRODUCTION & QUALITY CONTROL REPORT					
Project No./Contract No.	Project Title / Location	Day of Report	Report No.		
6389	BRC Eastside Common Areas Soils Remediation	27-Aug-08	59		

Position	Name	E-Mail Address	Phone No.
BRC PROJECT MANAGER	Lee Farris, On Site.	lfarris@landwellco.com	702-567-0400
BRC PROJECT MANAGER	Ranajit Sahu	sahuron@earthlink.net	702-567-0400
CONST. PROJECT MANAGER	Dan Brennecke	Dan.Brennecke@westonsolutions.	970-260-5886
Construction Manager	Richard Laubinger	Richard.Laubinger@westonsolutio	720-641-8660

	Condi	itions		Tem	p (F)	Wir	nd	Add'l R	eadings
	- 10 1 01 11	DIA	0 / D- + . Oldlv	Low	79			Precip. (In/Dy.)	
AM	Sunny / Party Cloudly	PM	Sunny / Party Cloudly	High	104	ENE	3mph	Humidity (%)	

Calm to Light Wind..

Name	Position	Trade / Work Performed	Y/N
Dick Laubinger	Construction Manager	Construction Management Services.	Y
Dan Brennecke	Project Manager. CM	Construction Management Services.	Υ
Dave Gertz	Project Engineer	Construction Management Services.	Y
June Laubinger	Admin Assistant	Construction Management Services.	Y
Linda Nations	Asst Const Manager	Construction Management Services	Y

Im Cox         QA/QC Supervisor           Greg Corcoran         Engineer of Record           Robecca Flynn         Engineer           Camon Liddell         QA/QC Tech           Dan Street         QA Manager	Oversight Oversight Oversight Oversight Oversight Oversight Oversight Oversight Oversight	Y Y N N N Y N Y
Brent Barbacane         QA/QC Tech           Jim Cox         QA/QC Supervisor           Greg Corcoran         Engineer of Record           Robecca Flynn         Engineer           Camon Liddell         QA/QC Tech           Dan Street         QA Manager           ON-SITE SUPPORT PERSONNEL	Oversight Oversight Oversight Oversight Oversight	N N Y N
Greg Corcoran         Engineer of Record           Robecca Flynn         Engineer           Camon Liddell         QA/QC Tech           Dan Street         QA Manager           ON-SITE SUPPORT PERSONNEL	Oversight Oversight Oversight	N Y N
Robecca Flynn         Engineer           Camon Liddell         QA/QC Tech           Dan Street         QA Manager           ON-SITE SUPPORT PERSONNEL	Oversight Oversight	Y
Camon Liddell QA/QC Tech Dan Street QA Manager ON-SITE SUPPORT PERSONNEL	Oversight	N
Dan Street QA Manager ON-SITE SUPPORT PERSONNEL		
ON-SITE SUPPORT PERSONNEL	Oversight	Y
ON-SITE SUPPORT PERSONNEL  Name Position		
Name Position		
	Trade / Work Performed	Y/N
Doug Herlocker, Tetra Tech Air Monitoring Spec	cialist Air Monitoring,	N
Becky Dano, Tetra Tech Air Monitoring Spec	cialist Air Monitoring,	Υ
Jerry Faucheux, Tetra Tech Air Monitoring Spec	cialist Air Monitoring	Υ
OVERSITE PERSONNEL	<b>通信的 电影响 医眼睛的 医眼睛的 经</b>	
Name Position	Trade / Work Performed	Y/N
Scott McKeag, McGinley Oversight	For NDEP	N
Devin Gordon, McGinley Oversight	For NDEP	Y
Dock Kim, ATC Field Observation	For AIG	Y
Ron Perry, ASW Inspector	Liner Inspector	N
PBS&J, Survey Surveyors		N

Name	Company	Trade / Work Performed	Y/N
Erik Geringer	Entact	Project Manager	Y
Josh Carrol	Entact	Asst Project Manager	Y
Russ Karnes	Entact	Eastside, Superintendent	Y
Michael Carlson	Entact	Engineer	Y
Joe Curilla	Entact	Health & Safety Officer	Y
Michael Parker	Entact	Health and Safety Technician	Υ
A PARTY CONTRACTOR OF THE PART	Entact	22 Equipment Operators & Truck Drivers	Υ
Ed Long	Entact	CAMU, Superintendent	Y
	American Asphalt	Earthwork Superintendent	Υ
	American Asphalt	11 Equipment Operators & Truck Drivers,	Y
Rick McIntire	Entact	CSP, Safety	Y
	Environmental Specialties,Inc	Liner Superintendent	N
	Environmental Specialties,Inc	1 Liner Seamer on site.	Y
	Kenney Survey	CAMU	Y

1 of 4 Ver 1.1 11/07

DAILY PRODUCTION & QUALITY CONTROL REPORT								
Project No./Contract No.	Project Title / Location	Day of Report	Report No.					
6389	BRC Eastside Common Areas Soils Remediation	27-Aug-08	59					

ON-SITE EQUIPMENT			
Equipment	Vendor / Tag No.	Work Performed	_
CAT D400E Dump Truck (2)		CAMU	 
JD D400 Dump Trucks (6)		Eastside	
CAT 324D long stick excavator		CAMU	 
CAT D8R Dozer with disc		Eastside	
CAT 345 excavator		Eastside	
CAT 330 Excavator		Eastside	
Case double pan scrapers.		Eastside	
CAT D6 LGP Dozer (2)		Eastside	
Water Trucks (2)		Eastside	
637/631 Cat Scrapers (6)		CAMU	
CAT 16H Grader		CAMU	
CAT D-10 Dozer		CAMU	
CAT Water Wagon		CAMU	
CAT D-6 Dozer		CAMU	
CAT 14H Grader		CAMU	
Gradall		CAMU	
Bobcat Skidsteer		CAMU	
JLG		CAMU	
CAT D4 dozer		CAMU	

MATERIAL HANDLING	G (ON-SITE DELIVERY / REMOVAL	)							
		OTV	QTY UOM Purpose		Delivery Verification				
Material	Vendor	GIY	UOW	Purpose	Condtn	Qty	Spec	Tags	
GCL	CETCO	0	rolls	For CAMU					
Geocomposite	Agru	0	rolls	For CAMU					
Woven Geotextile		0	rolls	For CAMU					

### WORK COMPLETED

Description of Work Executed Toda

- Eastside Mixing and Drying Activity:
   Loading out prepared material from CTR-2 using 345 excavator. (4) haul trucks hauling to beta ditch. 188 loads, (3,760) cy.
- D6 dozer spread prepared soils at the beta ditch.

- D8 Dozer continued disking operation.

  Versatile tractor and Pans. 0 loads, (0) cy. No Activity.

  Motorgrader maintaining roads. Water truck managing dust control.
- Continued pumping water from SC-1 to SW-12.

#### CAMU Activity:

#### Excavation

- -Northwest Detention Basin excavation 631/637 scrapers (1,200) cy. -Western Ditch. Power screener screening operations layer.
- Entact maintained 12" clean soil cap over west haul rd and bypass rd.
- Continued Anchor trench backfill and compaction.

#### Embankment

- Phase 1 embankment, complete.
- Phase 1 estimated cummulative embankment placed: 0 cy

#### **Waste Placement**

- Phase 1 estimated daily waste placed: 0 cy
  Phase 1 estimated cummulative waste placed: 0 cy
  Phase 1 Operations Layer placed daily 50 loads, (900) cy

### Geosynthetics

- Phase 1. Shovel out silt and debri clean liner and install toe drain at east slope toe.
- Phase 1 GCL placed: 0 sf daily, 347,067 sf cummulative.
- Phase 1 Geomembrane:0 sf daily, 365,136 sf cummulative
- Phase 1 Geocomposite: 0 sf daily, 327,600 sf cummulative.
- Phase 1 Geotextile: (0) sf daily...

Other: Grading at Sewer realignment corridor crossroad.

Ver 1.1 11/07

2 of 4

## **DAILY PRODUCTION & QUALITY CONTROL REPORT**

Project No./Contract No.	Project Title / Location	Day of Report	Report No.
6389	<b>BRC Eastside Common Areas Soils Remediation</b>	27-Aug-08	59
		Li riag oo	

Perimeter Fence Inspection and Repair.

### **HEALTH & SAFETY**

escription of Health & Safety Actions Taken Today / Safety Inspections Conducted

Entact H&S Tailgates Morning: Slips, trip and falls. Night work.

ESI, Liner Crew: Off Site.

Afternoon: Hydration, high temperatures.

## American Asphalt Tailgates Morning: Slips, trips and falls.

Safety Incidents: No Incidents.

### QUALITY CONTROL

Description of Quality Control Actions Taken Today / Quality Inspections Conducted

#### Daily CQA Summary.

Inspected 12" capped haul roads for degradation. All areas ok.

2am start of operations layer placement on liner, halted at 11:50 am.. Wrinkles beginnning.

ESI on site to handle minor repairs.

Inspected LCRS pipe for silt, no damage. Contractor to flush out piping.

Dust: Met requirements.

**Deviations from CQA Plan** 

### ISSUES AND/OR ITEMS OF DISCUSSION

CAMU: Burrowing Owls, No sighting..

CAMU: Phase 1 night work began, 2 AM placing operations layer at cooler temperatures.

Weekly Progress Meeting held at BRC Offices.

/ISITORS			
Name	Organization	Purpose of Visit	
-			

Report Prepared By / Title

Signature

3 of 4

Dick Laubinger, Construction Manager

27-Aug-08

Ver 1.1 11/07

# **Basic Remediation Company** 875 West Warm Springs Road


Henderson, Nevada 89011

# DAILY PRODUCTION & QUALITY CONTROL REPORT

Project No./Contract No.	Project Title / Location	Day of Report	Report No.
6389	BRC Eastside Common Areas Soils Remediation	27-Aug-08	59
0	0	27 Aug 00	00

### DAILY PHOTO LOG






CAMU, Ditch on West side to stop run in to Phase 1..

Photo 2



CAMU: Ditch on South side to stop run in to Phase 2.

Photo 3



Eastside. Fence installation at crossroad sewer realignment.

Photo 4



CAMU, Phase 1 East slope coverage of operations layer.

4 of 4 Ver 1.1 11/07