

A						Basic'Re	mediat	ioi
D	AILY PRODUCTIO	N & QI	JALITY	CONTR	OL REPO	DRT		
Project No./Contract No.		Project Tit	le / Location			Day of Report	Report	No
6389	BRC Eastside	Common	mmon Areas Soils Remediation		08-Jan-09	179	179	
PROJECT POINTS OF CO	NTACT				والما وحلوله		مدرو <u>م م</u>	
Position	Name			E-Mail Adde	638	Pho	ne No.	
BRC PROJECT MANAGER	Lee Farris	Ifarris@landwellco.com			67-0400			
BRC PROJECT MANAGER CONST, PROJECT MANAGER	Ranajit Sahu, On Site. Dan Brennecke		Contraction in the local division in the loc	earthlink.ne	tonsolutions.c		67-0400 60-5886	-
Construction Manager	Richard Laubinger		and the same and some sold in the	Contract in the second s	vestonsolution		41-8660	_
WEATHER CONDITIONS								
	Conditions			Temp (F)	Wind	211 2280/02/23	Add'l Readings	
AM Sunny/Clear	PM Sur	nny/Clear		.ow 38 ligh 60	NE 5mph	Precip. (m Dy.) Humidity (%)		_
Additional Weather Comments Calm in AM to approx 5 mp	h in PM.							
ON-SITE WESTON PERS	ONNEL					The owned with the		
Name	Position	T		Trade / Wor	k Performed		Y/N	
Dick Laubinger	Construction Manager	Constr	uction Mana	agement Ser	vices.		Y	
Dan Brennecke	Project Manager. CM	Constr	uction Mana	agement Ser	vices.		N	
Richard Davis	Project Engineer			agement Ser			Y	
Chris White Wayne Hodgson	Assist. Const. Mgr Assist. Const. Mgr			agement Ser agement Ser			Y	
Wayne Hodgson Kevin Cooke	Assist. Const. Mgr Assist. Const. Mgr			agement Ser agement Ser			Y	-
June Laubinger	Admin Assistant	and the second se		agement Ser			Y	-
				0				
								_
								_
	-		-	_				_
ON-SITE GEOSYNTEC PE	- A state of the second s							
Name	Position			Trade / Wo	k Performed		Y/N	_
Greg Corcoran	Design Engineer	Oversi					N	_
Dan Street	QA Manager	Oversi					Y	_
Jim Cox Robecca Flynn	QA/QC Supervisor Engineer		Oversight				N	_
Wayne Wofford	QA/QC Tech	and the second se	Oversight					
Roland Derosier			Oversight			V		
	QA/QC Tech	Oversi	•				Y	
reason and a second to the second s	QA/QC Tech QA/QC Tech	Oversi	ight					
Camon Liddell	QA/QC Tech QA/QC Tech		ight ight				Y Y Y	_
Camon Liddell Jeremy Osborn Victor Heredia	QA/QC Tech QA/QC Tech QA/QC Tech	Oversi	ight ight ight				Y Y	
Camon Liddell Jeremy Osborn Victor Heredia	QA/QC Tech QA/QC Tech QA/QC Tech	Oversi Oversi	ight ight ight				Y Y Y	
Camon Liddell Jeremy Osborn Victor Heredia	QA/QC Tech QA/QC Tech QA/QC Tech	Oversi Oversi	ight ight ight	Trade / Wo	rk Performed		Y Y Y	
Camon Liddell Jeremy Osborn Victor Heredia ON-SITE SUPPORT PERS	QA/QC Tech QA/QC Tech QA/QC Tech SONNEL	Oversi Oversi Overs	ight ight ight	Trade / Wo	rk Performed.		Y Y Y	
Carnon Liddell Jeremy Osborn Victor Heredia ON-SITE SUPPORT PERS Name Doug Herlocker, Tetra Tech Becky Dano, Tetra Tech	QA/QC Tech QA/QC Tech QA/QC Tech SONNEL Position Air Monitoring Specialist Air Monitoring Specialist	Oversi Oversi Oversi Air Mc Air Mc	ight ight ight ight ight ight nitoring nitoring,	Trade / Wo	rk Performed		Y Y Y Y/N N Y	
Camon Liddell Jeremy Osborn Victor Heredia ON-SITE SUPPORT PERS Name Doug Herlocker, Tetra Tech	QA/QC Tech QA/QC Tech QA/QC Tech SONNEL Position Air Monitoring Specialist	Oversi Oversi Oversi Air Mc Air Mc	ight ight ight sight sight	Trade / Wo	rk Performed.		Y Y Y Y/N N	
Camon Liddell Jeremy Osborn Victor Heredia ON-SITE SUPPORT PERS Name Doug Herlocker, Tetra Tech Becky Dano, Tetra Tech	QA/QC Tech QA/QC Tech QA/QC Tech SONNEL Position Air Monitoring Specialist Air Monitoring Specialist	Oversi Oversi Oversi Air Mc Air Mc	ight ight ight ight ight ight nitoring nitoring,	Trade / Wo	rk Performed		Y Y Y Y/N N Y	
Camon Liddell Jeremy Osborn Victor Heredia ON-SITE SUPPORT PERS Name Doug Herlocker, Tetra Tech Becky Dano, Tetra Tech	QA/QC Tech QA/QC Tech QA/QC Tech SONNEL Position Air Monitoring Specialist Air Monitoring Specialist	Oversi Oversi Oversi Air Mc Air Mc	ight ight ight ight ight ight nitoring nitoring,	Trade / Wo	rk Performed		Y Y Y Y/N N Y	
Camon Liddell Jeremy Osborn Victor Heredia ON-SITE SUPPORT PERS Name Doug Herlocker, Tetra Tech Becky Dano, Tetra Tech Jerry Faucheux, Tetra Tech	QA/QC Tech QA/QC Tech QA/QC Tech SONNEL Position Air Monitoring Specialist Air Monitoring Specialist Air Monitoring Specialist	Oversi Oversi Oversi Air Mc Air Mc	ight ight ight ight ight ight nitoring nitoring,	Trade / Wo	rk Performed.		Y Y Y Y/N N Y	
Camon Liddell Jeremy Osborn Victor Heredia ON-SITE SUPPORT PERS Name Doug Herlocker, Tetra Tech Becky Dano, Tetra Tech Jerry Faucheux, Tetra Tech	QA/QC Tech QA/QC Tech QA/QC Tech SONNEL Position Air Monitoring Specialist Air Monitoring Specialist Air Monitoring Specialist	Oversi Oversi Oversi Air Mc Air Mc	ight ight ight ight ight ight nitoring nitoring,		rk Performed.		Y Y Y Y/N N Y	
Camon Liddell Jeremy Osborn Victor Heredia ON-SITE SUPPORT PERS Name Doug Herlocker, Tetra Tech Becky Dano, Tetra Tech Jerry Faucheux, Tetra Tech OVERSITE PERSONNEL Name	QA/QC Tech QA/QC Tech QA/QC Tech SONNEL Position Air Monitoring Specialist Air Monitoring Specialist Air Monitoring Specialist	Oversi Oversi Oversi Air Mc Air Mc Air Mc	ight ight ight bight nitoring nitoring, nitoring				Y Y Y Y N N N	
Carron Liddell Jeremy Osborn Victor Heredia ON-SITE SUPPORT PERS Name Doug Herlocker, Tetra Tech Becky Dano, Tetra Tech Jerry Faucheux, Tetra Tech OVERSITE PERSONNEL	QA/QC Tech QA/QC Tech QA/QC Tech SONNEL Position Air Monitoring Specialist Air Monitoring Specialist Air Monitoring Specialist Position	Oversi Oversi Oversi Air Mc Air Mc Air Mc	ight ight ight intoring onitoring, onitoring intoring				Y Y Y Y N N Y/N	
Carron Liddell Jeremy Osborn Victor Heredia ON-SITE SUPPORT PERS Name Doug Herlocker, Tetra Tech Becky Dano, Tetra Tech Jerry Faucheux, Tetra Tech OVERSITE PERSONNEL Name Mark Eizman, ASW Devin Gordon, McGinley Dock Kim, ATC	QA/QC Tech QA/QC Tech QA/QC Tech SONNEL Position Air Monitoring Specialist Air Monitoring Specialist Air Monitoring Specialist Air Monitoring Specialist Position Inspector Oversight Field Observation	Oversi Oversi Oversi Air Mc Air Mc Air Mc Liner I For NI For Al	ght ight ight ight initoring initoring, initoring inspector DEP G				Y Y Y Y Y N Y N Y Y Y Y	
Carron Liddell Jeremy Osborn Victor Heredia ON-SITE SUPPORT PERS Name Doug Herlocker, Tetra Tech Becky Dano, Tetra Tech Jerry Faucheux, Tetra Tech OVERSITE PERSONNEL Name Mark Eizman, ASW Devin Gordon, McGinley Dock Kim, ATC Joe Ludlow, ASW	QA/QC Tech QA/QC Tech QA/QC Tech SONNEL Position Air Monitoring Specialist Air Monitoring Specialist Air Monitoring Specialist Air Monitoring Specialist Dispector Dispector Oversight Field Observation Inspector	Oversi Oversi Oversi Air Mc Air Mc	ght ight ight ight intoring int				Y Y Y Y Y N Y N Y/N Y Y N Y N	
Camon Liddell Jeremy Osborn Victor Heredia ON-SITE SUPPORT PERS Name Doug Herlocker, Tetra Tech Becky Dano, Tetra Tech Jerry Faucheux, Tetra Tech Jerry Faucheux, Tetra Tech OVERSITE PERSONNEL Name Mark Eizman, ASW Devin Gordon, McGinley Dock Kim, ATC Joe Ludlow, ASW	QA/QC Tech QA/QC Tech QA/QC Tech SONNEL Position Air Monitoring Specialist Air Monitoring Specialist Air Monitoring Specialist Air Monitoring Specialist Dispector Inspector Dispector Inspector Inspector Inspector	Oversi Oversi Oversi Air Mc Air Mc	ght ight ight ight intoring mitoring, mitoring inspector DEP G Inspector Inspector Inspector				Y Y Y Y N N Y/N Y/N Y Y N N N	
Camon Liddell Jeremy Osborn Victor Heredia ON-SITE SUPPORT PERS Name Doug Herlocker, Tetra Tech Jerry Faucheux, Tetra Tech Jerry Faucheux, Tetra Tech OVERSITE PERSONNEL Name Mark Eizman, ASW Devin Gordon, McGinley Dock Kim, ATC Joe Ludiow, ASW Brian Rakvica	QA/QC Tech QA/QC Tech QA/QC Tech SONNEL Position Air Monitoring Specialist Air Monitoring Specialist Air Monitoring Specialist Air Monitoring Specialist Decision Inspector Oversight Field Observation Inspector Inspector Inspector	Oversi Oversi Oversi Air Mc Air Mc Air Mc Air Mc For NI For NI For Al Liner I Liner I	ght ght ight ight intoring onitoring, onitoring inspector DEP G Inspector Inspector				Y Y Y Y N Y N Y/N Y Y N Y N N N	
Camon Liddell Jeremy Osborn Victor Heredia ON-SITE SUPPORT PERS Name Doug Herlocker, Tetra Tech Jerry Faucheux, Tetra Tech Jerry Faucheux, Tetra Tech Name Mark Eizman, ASW Devin Gordon, McGinley Dock Kim, ATC Joe Ludlow, ASW Steve Morrow, ASW Brian Rakvica PBS&J, Survey	QA/QC Tech QA/QC Tech QA/QC Tech ONEL Position Air Monitoring Specialist Air Monitoring Specialist Air Monitoring Specialist Air Monitoring Specialist Decision Inspector Dversight Field Observation Inspector Inspector Inspector Surveyors	Oversi Oversi Oversi Air Mc Air Mc Air Mc Air Mc For NI For NI For Al Liner I Liner I	ght ight ight ight intoring mitoring, mitoring inspector DEP G Inspector Inspector Inspector				Y Y Y Y Y N N Y/N Y Y N Y N N N	
Camon Liddell Jeremy Osborn Victor Heredia ON-SITE SUPPORT PERS Name Doug Herlocker, Tetra Tech Jerry Faucheux, Tetra Tech Jerry Faucheux, Tetra Tech Name Mark Eizman, ASW Devin Gordon, McGinley Dock Kim, ATC Joe Ludlow, ASW Steve Morrow, ASW Brian Rakvica PBS&J, Survey	QA/QC Tech QA/QC Tech QA/QC Tech SONNEL Position Air Monitoring Specialist Air Monitoring Specialist Air Monitoring Specialist Air Monitoring Specialist Decision Inspector Oversight Field Observation Inspector Inspector Inspector Surveyors PERSONNEL	Oversi Oversi Oversi Air Mc Air Mc Air Mc Air Mc For NI For NI For Al Liner I Liner I	ght ght ight ight intoring onitoring, onitoring inspector DEP G Inspector Inspector	Trade / Wo	rk Performed		Y Y Y Y Y Y N Y/N Y Y N N N N N	
Camon Liddell Jeremy Osborn Victor Heredia ON-SITE SUPPORT PERS Name Doug Herlocker, Tetra Tech Jerry Faucheux, Tetra Tech Jerry Faucheux, Tetra Tech Name Mark Eizman, ASW Devin Gordon, McGinley Dock Kim, ATC Joe Ludiow, ASW Brian Rakvica PBS&J, Survey ON-SITE CONTRACTOR Name	QA/QC Tech QA/QC Tech QA/QC Tech SONNEL Position Air Monitoring Specialist Air Monitoring Specialist Air Monitoring Specialist Air Monitoring Specialist Inspector Dispector Inspector Inspector Inspector Inspector Surveyors PERSONNEL Company	Oversi Oversi Oversi Air Mc Air Mc Air Mc Air Mc Liner I Liner I Liner I NDEP Surve	ght ight ight ight initoring initoring initoring initoring inspector DEP G Inspector DEP inspector ying, QA	Trade / Wo			Y Y Y Y Y Y N Y/N Y Y/N Y/N Y/N	
Camon Liddell Jeremy Osborn Victor Heredia ON-SITE SUPPORT PERS Name Doug Herlocker, Tetra Tech Becky Dano, Tetra Tech Jerry Faucheux, Tetra Tech Jerry Faucheux, Tetra Tech Name Mark Eizman, ASW Devin Gordon, McGinley Devin Gordon, McGinley Dock Kim, ATC Joe Ludiow, ASW Steve Morrow, ASW Brian Rakvica PBS&J, Survey ON-SITE CONTRACTOR Name Erik Geringer	QA/QC Tech QA/QC Tech QA/QC Tech ONNEL Position Air Monitoring Specialist Air Monitoring Specialist Air Monitoring Specialist Air Monitoring Specialist Air Monitoring Specialist Position Inspector Oversight Field Observation Inspector Inspector Inspector Inspector Surveyors PERSONNEL Company Entact	Oversi Oversi Oversi Air Mc Air Mc Mc	ght ight ight ight ight ight initoring	Trade / Wo Trade / Wo	rk Performed		Y Y Y Y Y Y N Y/N Y Y N N N N N	
Camon Liddell Jeremy Osborn Victor Heredia ON-SITE SUPPORT PERS Name Doug Herlocker, Tetra Tech Becky Dano, Tetra Tech Jerry Faucheux, Tetra Tech Jerry Faucheux, Tetra Tech Name Mark Eizman, ASW Devin Gordon, McGinley Dock Kim, ATC Joe Ludlow, ASW Steve Morrow, ASW Brian Rakvica PBS&J, Survey ON-SITE CONTRACTOR Name Erik Geringer Josh Carrol	QA/QC Tech QA/QC Tech QA/QC Tech SONNEL Position Air Monitoring Specialist Air Monitoring Specialist Air Monitoring Specialist Air Monitoring Specialist Inspector Dispector Inspector Inspector Inspector Inspector Surveyors PERSONNEL Company	Oversi Oversi Oversi Air Mc Air Air Mc Air Air Mc Air Air Air Air Air Air Air Air Air Air	ght ight ight ight initoring initoring initoring initoring inspector DEP G Inspector DEP inspector ying, QA	Trade / Wo Trade / Wo	rk Performed		Y Y Y Y Y Y N Y/N Y Y N N N N N N N N Y/N Y	
Camon Liddell Jeremy Osborn Victor Heredia ON-SITE SUPPORT PERS Name Doug Herlocker, Tetra Tech Becky Dano, Tetra Tech Jerry Faucheux, Tetra Tech Jerry Faucheux, Tetra Tech Mark Eizman, ASW Devin Gordon, McGinley Dock Kim, ATC Joe Ludiow, ASW Steve Morrow, ASW Brian Rakvica PBS&J, Survey ON-SITE CONTRACTOR Name Erik Geringer Josh Carrol Russ Karnes	QA/QC Tech QA/QC Tech QA/QC Tech SONNEL Position Air Monitoring Specialist Air Monitoring Specialist Air Monitoring Specialist Air Monitoring Specialist Air Monitoring Specialist Position Inspector Inspector Inspector Inspector Inspector Surveyors PERSONNEL Company Entact Entact	Oversi Oversi Oversi Air Mc Air Air Mc Air Air Mc Air Air Air Air Air Air Air Air Air Air	ght ight ight ight ight intoring onitoring onitoring inspector DEP G G Inspector DEP inspector onitoring control (1) inspector inspector control (1) inspector control (1) inspe	Trade / Wo Trade / Wo	rk Performed		Y Y Y Y Y N N Y/N Y Y N N N N N N N Y/N Y Y Y	
Camon Liddell Jeremy Osborn Victor Heredia ON-SITE SUPPORT PERS Name Doug Herlocker, Tetra Tech Becky Dano, Tetra Tech Jerry Faucheux, Tetra Tech Jerry Faucheux, Tetra Tech Name Mark Eizman, ASW Devin Gordon, McGinley Dock Kim, ATC Joe Ludiow, ASW Steve Morrow, ASW Brian Rakvica PBS&J, Survey ON-SITE CONTRACTOR Name Erik Geringer Josh Carrol Russ Karnes Michael Carlson Joe Curilla	QA/QC Tech QA/QC Tech QA/QC Tech OA/QC Tech SONNEL Position Air Monitoring Specialist Air Monitoring Specialist Air Monitoring Specialist Air Monitoring Specialist Air Monitoring Specialist Air Monitoring Specialist Position Inspector Inspector Inspector Inspector Inspector Inspector Inspector Inspector Surveyors PERSONNEL Entact Entact Entact Entact	Oversi Oversi Oversi Air Mc Air Air Mc Air Air Mc Air Air Mc Air Air Mc Air Air Mc Air Air Air Mc Air Air Air Air Air Air Air Air Air Air	ght ght ight ight ight initoring initoring, initoring initoring inspector DEP G G Inspector DEP G ying, QA it Manager roject Mana ide, Superin eer h & Safety (i	Trade / Wo Trade / Wo ager tendent Dfficer	rk Performed		Y Y Y Y Y Y N Y N Y/N Y Y Y Y Y Y Y Y Y	
Camon Liddell Jeremy Osborn Victor Heredia ON-SITE SUPPORT PERS Name Doug Herlocker, Tetra Tech Jerry Faucheux, Tetra Tech Jerry Faucheux, Tetra Tech UNERSITE PERSONNEL Name Mark Eizman, ASW Devin Gordon, McGinley Dock Kim, ATC Joe Ludiow, ASW Brian Rakvica PBS&J, Survey ON-SITE CONTRACTOR Name Erik Geringer Josh Carrol Russ Karnes Michael Carlson	QA/QC Tech QA/QC Tech QA/QC Tech ONNEL Position Air Monitoring Specialist Air Monitoring Specialist Air Monitoring Specialist Air Monitoring Specialist Air Monitoring Specialist Air Monitoring Specialist Position Inspector Inspector Inspector Inspector Inspector Inspector Surveyors PERSONNEL Entact Entact Entact Entact Entact Entact Entact	Oversi Oversi Oversi Oversi Oversi Air Mc Air Mc Ai	ght ght ight ight ight intoring nitoring nitoring intoring	Trade / Wo Trade / Wo ager tendent Officer r Technician	rk Performed		Y Y Y Y Y N N Y/N Y Y N N N N N N N Y/N Y Y Y Y	
Camon LIddell Jeremy Osborn Victor Heredia ON-SITE SUPPORT PERS Name Doug Herlocker, Tetra Tech Becky Dano, Tetra Tech Jerry Faucheux, Tetra Tech Jerry Faucheux, Tetra Tech Wark Eizman, ASW Devin Gordon, McGinley Dock Kim, ATC Joe Ludlow, ASW Brian Rakvica PBS&J, Survey ON-SITE CONTRACTOR Name Erik Geringer Josh Carrol Russ Karnes Michael Carlson Joe Curilla Timothy Stadt	QA/QC Tech QA/QC Tech QA/QC Tech QA/QC Tech SONNEL Position Air Monitoring Specialist Air Monitoring Specialist Air Monitoring Specialist Air Monitoring Specialist Air Monitoring Specialist Air Monitoring Specialist Position Inspector Inspector Inspector Inspector Inspector Inspector Inspector Surveyors PERSONNEL Entact Entact Entact Entact Entact Entact Entact Entact	Oversi Oversi Oversi Oversi Air Mo Air Air Air Air Air Air Air Air Air Air Air Air Air Air Air Air Air	ght ght ight ight ight intoring nitoring nitoring inspector DEP G inspector DEP G inspector Project Mana de, Superin eer a & Safety (t) uipment Op	Trade / Wo Trade / Wo ager tendent Dificer r Technician erators & Tru	rk Performed		Y Y Y Y N N Y/N Y Y N Y/N Y Y Y Y Y Y Y	
Camon Liddell Jeremy Osborn Victor Heredia ON-SITE SUPPORT PERS Name Doug Herlocker, Tetra Tech Becky Dano, Tetra Tech Jerry Faucheux, Tetra Tech Jerry Faucheux, Tetra Tech VERSITE PERSONNEL Name Mark Eizman, ASW Devin Gordon, McGinley Dock Kim, ATC Joe Ludlow, ASW Steve Morrow, ASW Brian Rakvica PBS&J, Survey ON-SITE CONTRACTOR Name Erik Geringer Josh Carrol Russ Karnes Michael Carlson Joe Curilla Timothy Stadt	QA/QC Tech QA/QC Tech QA/QC Tech ONNEL Position Air Monitoring Specialist Air Monitoring Specialist Air Monitoring Specialist Air Monitoring Specialist Air Monitoring Specialist Decision Inspector Inspector Inspector Inspector Inspector Inspector Surveyors PERSONNEL Company Entact	Oversi Oversi Oversi Air Mc Air Mc Air Mc Air Mc Air Mc Einer I For NI For AI Liner I Liner I Liner I Liner Surve Projec Asst Engin Healt Healt Healt	ght ght ight ight ight initoring initoring initoring initoring inspector DEP G inspector DEP G inspector DEP G inspector DEP G inspector DEP G inspector DEP G inspector DEP G inspector DEP G inspector DEP G inspector DEP G inspector DEP G inspector DEP G inspector DEP G inspector DEP G inspector DEP G inspector DEP G inspector DEP J Superind eer adde, Superind eer add Safety Upment Op J, Superinte J, Superinte J, Superinte inspector DEP G inspector DEP G inspector DEP G inspector DEP G inspector DEP G inspector DEP J Superinder Superinder J, Superinte J, Superinte	Trade / Wo Trade / Wo ager tendent Officer r Technician erators & Tru ndent	rk Performed		Y Y Y Y Y Y N Y N Y Y Y Y Y Y Y Y Y Y Y	
Camon Liddell Jeremy Osborn Victor Heredia ON-SITE SUPPORT PERS Name Doug Herlocker, Tetra Tech Becky Dano, Tetra Tech Jerry Faucheux, Tetra Tech Jerry Faucheux, Tetra Tech Devin Gordon, McGinley Devin Gordon, McGinley Devin Gordon, McGinley Dock Kim, ATC Joe Ludlow, ASW Steve Morrow, ASW Brian Rakvica PBS&J, Survey ON-SITE CONTRACTOR Name Erik Geringer Josh Carrol Russ Karnes Michael Carlson Joe Curilla Timothy Stadt Ed Long Lance Bruce	QA/QC Tech QA/QC Tech QA/QC Tech QA/QC Tech SONNEL Position Air Monitoring Specialist Air Monitoring Specialist Air Monitoring Specialist Air Monitoring Specialist Air Monitoring Specialist Position Inspector Inspector Inspector Inspector Inspector Inspector Inspector Surveyors PERSONNEL Company Entact	Oversi Oversi Oversi Air Mc Air Mc Air Mc Air Mc Air Mc Einer I For NI For Al Liner I NDEP Surve Projec Asst F Eastsi Englin Health Health Health	ght ght ight ight ight intoring	Trade / Wo Trade / Wo ager tendent Officer r Techniclan erators & Tru ndent Officer	rk Performed		Y Y Y Y Y Y N Y N Y Y N Y Y Y Y Y Y Y Y	
Camon Liddell Jeremy Osborn Victor Heredia ON-SITE SUPPORT PERS Name Doug Herlocker, Tetra Tech Jerry Faucheux, Tetra Tech Jerry Faucheux, Tetra Tech Jerry Faucheux, Tetra Tech Mark Eizman, ASW Devin Gordon, McGinley Dock Kim, ATC Joe Ludiow, ASW Steve Morrow, ASW Brian Rakvica PBS&J, Survey ON-SITE CONTRACTOR Name Erik Geringer Josh Carrol Russ Karnes Michael Carlson Joe Curilla Timothy Stadt	QA/QC Tech QA/QC Tech QA/QC Tech ONNEL Position Air Monitoring Specialist Air Monitoring Specialist Air Monitoring Specialist Air Monitoring Specialist Air Monitoring Specialist Decision Inspector Inspector Inspector Inspector Inspector Inspector Surveyors PERSONNEL Company Entact	Oversi Oversi Oversi Oversi Oversi Oversi Oversi Air Mc Air Mc Mc Air Mc Air Mc	ght ght ight ight ight initoring initoring initoring initoring inspector DEP G inspector DEP G inspector DEP G inspector DEP G inspector DEP G inspector DEP G inspector DEP G inspector DEP G inspector DEP G inspector DEP G inspector DEP G inspector DEP G inspector DEP G inspector DEP G inspector DEP G inspector DEP G inspector DEP J Superind eer adde, Superind eer add Safety Upment Op J, Superinte J, Superinte J, Superinte inspector DEP G inspector DEP G inspector DEP G inspector DEP G inspector DEP G inspector DEP J Superinder Superinder J, Superinte J, Superinte	Trade / Wo Trade / Wo ager tendent Officer r Techniclan erators & Tru ndent Officer	rk Performed		Y Y Y Y Y Y N Y N Y Y Y Y Y Y Y Y Y Y Y	

DAILY PRODUCTION & QUALITY CONTROL REPORT

Project No. Contract No.	Project Tille / Location Day of Report			t Report No	
6389	BRC Eastside Common Areas Soils Remediation 08-Jan-			179	
Eli Blackburn	Entact	Asst Project Manager		Y	
	Environmental Specialties,Inc	1 Liner Superintendent		Y	
	Environmental Specialties,Inc	12 Laborers/ Seamers		Y	
	Kenney Survey	CAMU		N	
	ABC Survey	Eastside/CAMU, Mohawk Drive.		N	

Equipment	Vendor / Tag No		Work Performed					
AT D400E Dump Truc	10-17-00 TO D. 1-140 C TO D.	CAMU			-	-		
D D400 Dump Trucks (Eastside						
AT 324D long stick exc		CAMU	9			1		
CAT D8R Dozer with dis		Eastside			•			
AT 345 excavator, (3)		Eastside				-	-	
AT 330 Excavator		Eastside			-			
Case double pan scrape	are		Eastside					
AT D6 LGP Dozer (1)		and the second se	Eastside		-			_
Vater Trucks (2)			Eastside					-
37/631 Cat Scrapers (2	2)		CAMU					-
AT 16H Grader	./		CAMU					_
CAT D-10 Dozer		CAMU						
CAT Water Trucks (2)		CAMU	27 0 22 1 Tu			_		-
CAT D-6 Dozer, (2)		CAMU						
CAT 14H Grader		CAMU	170,700 %		_		-	
Gradall		CAMU						-
LG		CAMU						
R Smooth drum Roller		and the second se	CAMU, Phase 1					
Tenent Street Sweeper		the second se	Eastside and CAMU					
Bomag Smooth drum Re								-
Chieftain 1400 Powersc			CAMU, Phase 1 CAMU, screening 1*& 6* minus					
		12010024		a second second				
					_		-	_
			_					_
MATERIAL HANDLIN	G (ON-SITE DELIVERY / REMO	VAL)						
Material	Vendor	Today	UOM	Purpose			Verificatio	
GCL	CETCO	85	rolls	For CAMU, On site	to date	Qty 732	Spec	lag
Beocomposite	Agru	54	rolls	For CAMU, On site		697		
Geomembrane	Agru	44	rolls	For CAMU, On site	_	236	-	
		44	1005	TO OANO, OT allo		230		-
VORK COMPLETED								
Description of Work Execu	ted Today							
astside Mixing and D	rying Activity:							
Day Shift:								
Continued scrape on F		9 12 22 22	2.522	2 23 CN				
	A-4 a test trench was excavate			ssion below).				
	stockpiling drying material in S	W-2 and SW-4 p	oonds.					
Continue pumping wat	er from SW-7 to SW-12.							

Night Shift: - Continued hauling material from HP-3/HP-2 and PUC-3.

CAMU Activity:

- Day Shift:

ESI continued placing GCL and Geomembrane on North BMI Landfill. • Continued excavating contaminated soil from NW Detention Basin/Phase IIIB trench and placing in Phase I. Continued screening cover soils from North BMI Landfill from 200,000 cy stockpile.
Continued hauling/placing 1* and 6* minus cover soils on North BMI Landfill.
Received and off loaded additional rolls of geosynthetics.

- Night Shift: - Continued placing material in Phase II.

Embankment

- Phase 1 embankment, complete.

Phase 1 estimated cummulative embankment placed: 0 cy - Phase II embankment , complete.

Waste Placement

- Phase 1 estimated daily waste placed, Phase IIIB Trench: 98 loads @ 20 cy/load = 1,960 cy. (2 trucks). night shift placed: (0) loads @ 18cy/load = 0 cy.

Phase 1 estimated cummulative waste placed: 285,340 cy.
Phase 1 Operations Layer placed. completed. Cumulative total: 21,662
Phase 2 estimated night shift placed: 282 loads @ 18cy/load = 5,076 cy, (19 trucks).

Phase 2 operations Layer placed. daily: 0 cy. Cumulative total: 37,188 cy.
Phase 2 estimated cummulative waste placed: 55,260 cy.

DAILY PRODUCTION & QUALITY CONTROL REPORT

Project No./Contract No.	Project Title / Location	Day of Report	Report No
6389	BRC Eastside Common Areas Soils Remediation	08-Jan-09	179

Geosynthetics. Estimated cummu - Phase 1 GCL placed:0 sf daily, 3C - Phase 1 Geomembrane:0 sf daily - Phase 1 Geocomposite: 0 sf daily		θ.		
- Phase 1 GCL placed:0 sf daily, 30 - Phase 1 Geomembrane:0 sf daily		е.		
Phase 1 Geomembrane:0 sf daily	7,372 sf cummulative.			
Phase 1 Geocomposite: 0 sf daily				
Phase 1 Geotextile: (0) sf daily. 6				
Phase 2 GCL placed: (0) sf daily, 4				
Phase 2 Geomenbrane: (0) sf daily				
Phase 2 Geocomposite: (0) sf daily		- detire		
BMI North Landfill GCL placed: (50				
BMI North Landfill Geomembrane: BMI North Landfill Geocomposite:				
HEALTH & SAFETY				
Description of Health & Safety Actions	Taken Today / Salety Inspections C	Conducted		
Entact H&S Tailgates				
Safety Topic: Eastside, Day: Make	e eye contact before approachin	g equipment.		
Safety Topic: CAMU, Day: Make e	eye contact before approaching	equipment.		
Eastside and CAMU, Night: Haul ro	oad maintenance, safe driving.			
Safety Incidents: None.				
Dust Incidents: None.				
CONSTRUCTION QUALITY AS				
Description of Quality Control Actions	Faken Today / Quality Inspections (Conducted		
		н.		
Monitor installation of protective co Continue review of and updating of	ver soils at the North BMI Landf f project documents and database			
Monitor screening of 1* and 6* min Monitor installation of protective co Continue review of and updating of Inventory and monitor incoming de ISSUES AND/OR ITEMS OF DI Discussion of Issues / Concerns / Con	wer soils at the North BMI Landf f project documents and databas livery of geosynthetics. SCUSSION versations / Topics	e to facilitate reporting.		
Monitor installation of protective co Continue review of and updating of inventory and monitor incoming de SSUES AND/OR ITEMS OF DI Discussion of Issues / Concerns / Com A test trench was excavated in eaa Ron Sahu, BRC inspected the tren contamination was evident. This w of PUA-4 and approximately 2 feet supervision of the Weston represen	ver soils at the North BMI Landf project documents and database livery of geosynthetics. SCUSSION versations / Topics che sond indicated that addition fill require excavation to a depth below the design excavation de intative) to excavate the visible c		I PUB-4 where visible excavation depth in c instructed to procee	le certain areas d (under the
Monitor installation of protective co Continue review of and updating of Inventory and monitor incoming de SSUES AND/OR ITEMS OF DI Discussion of Issues / Concerns / Cont A test trench was excavated in eac Ron Sahu, BRC inspected the tren contamination was evident. This uppervision of the Weston represen- subcontractor prior to any additional	ver soils at the North BMI Landf project documents and database livery of geosynthetics. SCUSSION versations / Topics che sond indicated that addition fill require excavation to a depth below the design excavation de intative) to excavate the visible c	e to facilitate reporting. 3, PUB-4 as directed to determine if all vis al excavation was necessary in PUA-4 and of approximately 3 feet below the design e pth in certain areas of PUB-4. Entact was	I PUB-4 where visible excavation depth in c instructed to procee	le certain areas d (under the
Monitor installation of protective co Continue review of and updating of Inventory and monitor incoming de SSUES AND/OR ITEMS OF DI Discussion of Issues / Concerns / Conc A test trench was excavated in eac Ron Sahu, BRC inspected the tren contamination was evident. This w of PUA-4 and approximately 2 feet subcontractor prior to any additional subcontractor prior to any additional SITE VISITORS	ver soils at the North BMI Landf f project documents and database livery of geosynthetics. SCUSSION versations / Topics cho of these ponds (PUA-4, PUB- ches and indicated that addition fill require excavation to a depth below the design excavation de native) to excavate the visible of al material being removed.	e to facilitate reporting. 3, PUB-4 as directed to determine if all visi al excavation was necessary in PUA-4 and of approximately 3 feet below the design e pth in certain areas of PUB-4. Entact was ontamination in these ponds. PUB-3 is goin	I PUB-4 where visible excavation depth in c instructed to procee	le certain areas d (under the
Vonitor installation of protective co Continue review of and updating of inventory and monitor incoming de SSUES AND/OR ITEMS OF DI Discussion of lasues / Concerns / Cont A test trench was excavated in ear Ron Sahu, BRC inspected the tren contamination was evident. This of PUA-4 and approximately 2 feet supervision of the Weston represen- subcontractor prior to any additional	ver soils at the North BMI Landf project documents and database livery of geosynthetics. SCUSSION versations / Topics che sond indicated that addition fill require excavation to a depth below the design excavation de intative) to excavate the visible c	e to facilitate reporting. 3, PUB-4 as directed to determine if all vis al excavation was necessary in PUA-4 and of approximately 3 feet below the design e pth in certain areas of PUB-4. Entact was	I PUB-4 where visible excavation depth in c instructed to procee	le certain areas d (under the
Monitor installation of protective co Continue review of and updating of inventory and monitor incoming de SSUES AND/OR ITEMS OF DI Decussion of Issues / Concerns / Conc A test trench was excavated in eac Aon Sahu, BRC inspected the tren contamination was evident. This wo of PUA-4 and approximately 2 feet subcontractor prior to any additional subcontractor prior to any additional SITE VISITORS	ver soils at the North BMI Landf f project documents and database livery of geosynthetics. SCUSSION versations / Topics cho of these ponds (PUA-4, PUB- ches and indicated that addition fill require excavation to a depth below the design excavation de native) to excavate the visible of al material being removed.	e to facilitate reporting. 3, PUB-4 as directed to determine if all visi al excavation was necessary in PUA-4 and of approximately 3 feet below the design e pth in certain areas of PUB-4. Entact was ontamination in these ponds. PUB-3 is goin	I PUB-4 where visible excavation depth in c instructed to procee	le certain areas d (under the
Monitor installation of protective co Continue review of and updating of inventory and monitor incoming de SSUES AND/OR ITEMS OF DI Decussion of Issues / Concerns / Conc A test trench was excavated in eac Aon Sahu, BRC inspected the tren contamination was evident. This wo of PUA-4 and approximately 2 feet subcontractor prior to any additional subcontractor prior to any additional SITE VISITORS	ver soils at the North BMI Landf f project documents and database livery of geosynthetics. SCUSSION versations / Topics cho of these ponds (PUA-4, PUB- ches and indicated that addition fill require excavation to a depth below the design excavation de native) to excavate the visible of al material being removed.	e to facilitate reporting. 3, PUB-4 as directed to determine if all visi al excavation was necessary in PUA-4 and of approximately 3 feet below the design e pth in certain areas of PUB-4. Entact was ontamination in these ponds. PUB-3 is goin	I PUB-4 where visible excavation depth in c instructed to procee	le certain areas d (under the
Monitor installation of protective co Continue review of and updating of inventory and monitor incoming de SSUES AND/OR ITEMS OF DI Decussion of Issues / Concerns / Conc A test trench was excavated in eac toon Sahu, BRC inspected the tren contamination was evident. This w of PUA-4 and approximately 2 feet uppervision of the Weston represen ubcontractor prior to any additional SITE VISITORS	ver soils at the North BMI Landf f project documents and database livery of geosynthetics. SCUSSION versations / Topics cho of these ponds (PUA-4, PUB- ches and indicated that addition fill require excavation to a depth below the design excavation de native) to excavate the visible of al material being removed.	e to facilitate reporting. 3, PUB-4 as directed to determine if all visi al excavation was necessary in PUA-4 and of approximately 3 feet below the design e pth in certain areas of PUB-4. Entact was ontamination in these ponds. PUB-3 is goin	I PUB-4 where visible excavation depth in c instructed to procee	le certain areas d (under the
Monitor installation of protective co Continue review of and updating of inventory and monitor incoming de SSUES AND/OR ITEMS OF DI Decussion of Issues / Concerns / Conc A test trench was excavated in eac Aon Sahu, BRC inspected the tren contamination was evident. This wo of PUA-4 and approximately 2 feet subcontractor prior to any additional subcontractor prior to any additional SITE VISITORS	ver soils at the North BMI Landf f project documents and database livery of geosynthetics. SCUSSION versations / Topics cho of these ponds (PUA-4, PUB- ches and indicated that addition fill require excavation to a depth below the design excavation de native) to excavate the visible of al material being removed.	e to facilitate reporting. 3, PUB-4 as directed to determine if all visi al excavation was necessary in PUA-4 and of approximately 3 feet below the design e pth in certain areas of PUB-4. Entact was ontamination in these ponds. PUB-3 is goin	I PUB-4 where visible excavation depth in c instructed to procee	le certain areas d (under the
Monitor installation of protective co Continue review of and updating of inventory and monitor incoming de SSUES AND/OR ITEMS OF DI Decussion of Issues / Concerns / Conc A test trench was excavated in eac toon Sahu, BRC inspected the tren contamination was evident. This w of PUA-4 and approximately 2 feet uppervision of the Weston represen ubcontractor prior to any additional SITE VISITORS	ver soils at the North BMI Landf f project documents and database livery of geosynthetics. SCUSSION versations / Topics cho of these ponds (PUA-4, PUB- ches and indicated that addition fill require excavation to a depth below the design excavation de native) to excavate the visible of al material being removed.	e to facilitate reporting. 3, PUB-4 as directed to determine if all visi al excavation was necessary in PUA-4 and of approximately 3 feet below the design e pth in certain areas of PUB-4. Entact was ontamination in these ponds. PUB-3 is goin	I PUB-4 where visible excavation depth in c instructed to procee	le certain areas d (under the
Monitor installation of protective co Continue review of and updating of inventory and monitor incoming de SSUES AND/OR ITEMS OF DI Decussion of Issues / Concerns / Conc A test trench was excavated in eac Aon Sahu, BRC inspected the tren contamination was evident. This wo of PUA-4 and approximately 2 feet subcontractor prior to any additional subcontractor prior to any additional SITE VISITORS	ver soils at the North BMI Landf f project documents and database livery of geosynthetics. SCUSSION versations / Topics cho of these ponds (PUA-4, PUB- ches and indicated that addition fill require excavation to a depth below the design excavation de native) to excavate the visible of al material being removed.	e to facilitate reporting. 3, PUB-4 as directed to determine if all visi al excavation was necessary in PUA-4 and of approximately 3 feet below the design e pth in certain areas of PUB-4. Entact was ontamination in these ponds. PUB-3 is goin	I PUB-4 where visible excavation depth in c instructed to procee	le certain areas d (under the
Monitor installation of protective co Continue review of and updating of inventory and monitor incoming de SSUES AND/OR ITEMS OF DI Discussion of Issues / Concerns / Conc A test trench was excavated in ead Non Sahu, BRC inspected the tren contamination was evident. This wo of PUA-4 and approximately 2 feet subcontractor prior to any additional subcontractor prior to any additional SITE VISITORS	ver soils at the North BMI Landf f project documents and database livery of geosynthetics. SCUSSION versations / Topics cho of these ponds (PUA-4, PUB- ches and indicated that addition fill require excavation to a depth below the design excavation de native) to excavate the visible of al material being removed.	e to facilitate reporting. 3, PUB-4 as directed to determine if all visi al excavation was necessary in PUA-4 and of approximately 3 feet below the design e pth in certain areas of PUB-4. Entact was ontamination in these ponds. PUB-3 is goin	I PUB-4 where visible excavation depth in c instructed to procee	le certain areas d (under the
Monitor installation of protective co Continue review of and updating of Inventory and monitor incoming de SSUES AND/OR ITEMS OF DI Discussion of Issues / Concerns / Conc A test trench was excavated in eac Ron Sahu, BRC inspected the tren contamination was evident. This w of PUA-4 and approximately 2 feet subcontractor prior to any additional supervision of the Weston represen- subcontractor prior to any additional SITE VISITORS	ver soils at the North BMI Landf f project documents and database livery of geosynthetics. SCUSSION versations / Topics cho of these ponds (PUA-4, PUB- ches and indicated that addition fill require excavation to a depth below the design excavation de native) to excavate the visible of al material being removed.	e to facilitate reporting. 3, PUB-4 as directed to determine if all visi al excavation was necessary in PUA-4 and of approximately 3 feet below the design e pth in certain areas of PUB-4. Entact was ontamination in these ponds. PUB-3 is goin	I PUB-4 where visible excavation depth in c instructed to procee	le certain areas d (under the
Monitor installation of protective co Continue review of and updating of Inventory and monitor incoming de SSUES AND/OR ITEMS OF DI Discussion of Issues / Concerns / Conc A test trench was excavated in eac Ron Sahu, BRC inspected the tren contamination was evident. This w of PUA-4 and approximately 2 feet subcontractor prior to any additional supervision of the Weston represen- subcontractor prior to any additional SITE VISITORS	ver soils at the North BMI Landf f project documents and database livery of geosynthetics. SCUSSION versations / Topics cho of these ponds (PUA-4, PUB- ches and indicated that addition fill require excavation to a depth below the design excavation de native) to excavate the visible of al material being removed.	e to facilitate reporting. 3, PUB-4 as directed to determine if all visi al excavation was necessary in PUA-4 and of approximately 3 feet below the design e pth in certain areas of PUB-4. Entact was ontamination in these ponds. PUB-3 is goin	I PUB-4 where visible excavation depth in c instructed to procee	le certain areas d (under the
Monitor installation of protective co Continue review of and updating of Inventory and monitor incoming de SSUES AND/OR ITEMS OF DI Discussion of Issues / Concerns / Conc A test trench was excavated in eac Ron Sahu, BRC inspected the tren contamination was evident. This w of PUA-4 and approximately 2 feet subcontractor prior to any additional subcontractor prior to any additional SITE VISITORS	ver soils at the North BMI Landf f project documents and database livery of geosynthetics. SCUSSION versations / Topics cho of these ponds (PUA-4, PUB- ches and indicated that addition fill require excavation to a depth below the design excavation de native) to excavate the visible of al material being removed.	e to facilitate reporting. 3, PUB-4 as directed to determine if all visi al excavation was necessary in PUA-4 and of approximately 3 feet below the design e pth in certain areas of PUB-4. Entact was ontamination in these ponds. PUB-3 is goin	I PUB-4 where visible excavation depth in c instructed to procee	le certain areas d (under the
Monitor installation of protective co Continue review of and updating of Inventory and monitor incoming de SSUES AND/OR ITEMS OF DI Discussion of Issues / Concerns / Conc A test trench was excavated in eac Ron Sahu, BRC inspected the tren contamination was evident. This w of PUA-4 and approximately 2 feet subcontractor prior to any additional supervision of the Weston represen- subcontractor prior to any additional SITE VISITORS	ver soils at the North BMI Landf f project documents and database livery of geosynthetics. SCUSSION versations / Topics cho of these ponds (PUA-4, PUB- ches and indicated that addition fill require excavation to a depth below the design excavation de native) to excavate the visible of al material being removed.	e to facilitate reporting. 3, PUB-4 as directed to determine if all visi al excavation was necessary in PUA-4 and of approximately 3 feet below the design e pth in certain areas of PUB-4. Entact was ontamination in these ponds. PUB-3 is goin	I PUB-4 where visible excavation depth in c instructed to procee	le certain areas d (under the
Monitor installation of protective co Continue review of and updating of Inventory and monitor incoming de INSUES AND/OR ITEMS OF DI Discussion of Issues / Concerns / Conc A test trench was excavated in eac Ron Sahu, BRC inspected the tren contamination was evident. This w of PUA-4 and approximately 2 feet subcontractor prior to any additional SITE VISITORS	ver soils at the North BMI Landf f project documents and database livery of geosynthetics. SCUSSION versations / Topics cho of these ponds (PUA-4, PUB- ches and indicated that addition fill require excavation to a depth below the design excavation de native) to excavate the visible of al material being removed.	e to facilitate reporting. 3, PUB-4 as directed to determine if all visi al excavation was necessary in PUA-4 and of approximately 3 feet below the design e pth in certain areas of PUB-4. Entact was ontamination in these ponds. PUB-3 is goin	I PUB-4 where visible excavation depth in c instructed to procee	le certain areas d (under the
Monitor installation of protective co Continue review of and updating of Inventory and monitor incoming de INSUES AND/OR ITEMS OF DI Discussion of Issues / Concerns / Conc A test trench was excavated in eac Ron Sahu, BRC inspected the tren contamination was evident. This w of PUA-4 and approximately 2 feet subcontractor prior to any additional SITE VISITORS	ver soils at the North BMI Landf f project documents and database livery of geosynthetics. SCUSSION versations / Topics cho of these ponds (PUA-4, PUB- ches and indicated that addition fill require excavation to a depth below the design excavation de native) to excavate the visible of al material being removed.	e to facilitate reporting. 3, PUB-4 as directed to determine if all visi al excavation was necessary in PUA-4 and of approximately 3 feet below the design e pth in certain areas of PUB-4. Entact was ontamination in these ponds. PUB-3 is goin	I PUB-4 where visible excavation depth in c instructed to procee	le certain areas d (under the
Monitor installation of protective co Continue review of and updating of Inventory and monitor incoming de INSUES AND/OR ITEMS OF DI Discussion of Issues / Concerns / Conc A test trench was excavated in eac Ron Sahu, BRC inspected the tren contamination was evident. This w of PUA-4 and approximately 2 feet subcontractor prior to any additional SITE VISITORS	ver soils at the North BMI Landf f project documents and database livery of geosynthetics. SCUSSION versations / Topics cho of these ponds (PUA-4, PUB- ches and indicated that addition fill require excavation to a depth below the design excavation de native) to excavate the visible of al material being removed.	e to facilitate reporting. 3, PUB-4 as directed to determine if all visi al excavation was necessary in PUA-4 and of approximately 3 feet below the design e pth in certain areas of PUB-4. Entact was ontamination in these ponds. PUB-3 is goin	I PUB-4 where visible excavation depth in c instructed to procee	le certain areas d (under the

Richard Laubinger, Construction Manager

8-Jan-09

Basic Remediation Company 875 West Warm Springs Road Henderson, Nevada 89011

DAILY PRODUCTION & QUALITY CONTROL REPORT					
Project No./Contract No.	Project Title / Location	Day of Report	Report No		
6389	BRC Eastside Common Areas Soils Remediation	08-Jan-09	179		
0	0	00-0411-05	175		

DAILY PHOTO LOG

Photo 1



Eastside: SW-4 scraping slopes.

Photo 2



Photo 3



CAMU: North BMI Landfill. Liner deliveries.

Photo 4



CAMU: North BMI Landfill GCL Liner installation.

.