Suite 810 143 Union Boulevard Lakewood, CO. 80228



# **DAILY PRODUCTION & QUALITY CONTROL REPORT**

Project No./Contract No.	Project Title / Location	Day of Report	Report No.
Task Order	ENTACT, BRC Eastside Common Areas Soils Remediation	23-Jun-08	
13520.003.001.0004	& CAMU Construction Project	23-Juli-06	4

PROJECT POINTS OF CONTACT						
Position	Name	E-Mail Address	Phone No.			
PROJECT MANAGER	Dan Brennecke	Dan.Brennecke@westonsolutions.c	970-260-5886			
Construction Manager	Richard Laubinger	Richard.Laubinger@westonsolutio	720-641-8660			

WEATHER CONDITIONS							
	Cor	nditions		Tem	<b>p</b> (F)	Wind	Add'l Readings
AM	Sunny/Clear	PM	Sunny/Clear	Low	79		Precip. (In/Dy.)
AIVI	Sum y/Clear	Sunny/Clear PM	Suriny/Clear	High	109	Dir	Humidity (%)

Additional Weather Comments

Calm, light wind.

Name	Position	Trade / Work Performed	Hrs	Signed HASP
Dick Laubinger	Construction Manager	Attended Safety Briefings. Morning and Afternoon.	-	
The state of the s		Observed load and haul material from SW-8, Dozer discing		
	-	CAT track scraper cutting down haul rd by SC-1		
		1:30 Tronox Mtg., 3:00 pm Plan of the Day Mtg.		
		Review Submittals, Daily Report		
		Total WESTON Man-Hours	10.0	

Name	Company	Trade / Work Performed	Hrs	Signed HASP
Eric Gehringer	Entact	Project Manager,	10.0	
Russ Karnes	Entact	Superintendent	10.0	
Larry Haith	Entact	Water Truck Driver	10.0	
Terry Harper	Entact	Operator/Truck Driver.	10.0	
Michael Carlson	Entact	Engineer	10.0	
Michael Parker	Entact	Health and Safety Technician	10.0	
Ubaldo Zubia	Entact	Operator	10.0	
Brett Payne	Entact	Operator	-	
Laurie Harper	Entact	Truck Driver	10.0	
James Stinnett	Entact	Operator/Truck Driver,	10.0	
Josh Carrol	Entact	Asst Project Manager	10.0	
Devin Osborne	Entact	Operator/Truck Driver	10.0	
Mickey Lynch	Entact	Operator	10.0	
Benjamin Nichols	Entact	Truck Driver	10.0	
Dennis Meranda	Entact	Operator	10.0	
Joe Curilla	Entact	Health & Safety Officer, on site training Mike Parker and others	10.0	
Two additional Operators	Entact	Operators	20.0	
		Total SUBCONTRACTOR Man-Hours	170.0	

Total Work-Hours on Site This Day

180.0

Cumulative Total Work-Hours From Previous Report TOTAL Work-Hours from Start of Construction

180.0

### **DAILY PRODUCTION & QUALITY CONTROL REPORT**

Project No./Contract No.	Project Title / Location	Day of Report	Report No.
Task Order	ENTACT, BRC Eastside Common Areas Soils Remediation	23-Jun-08	4
13520.003.001.0004	& CAMU Construction Project	23-Juli-06	4

ON-SITE EQUIPMENT							
Equipment	Vendor / Tag No.	Work Performed	On-Site Hours				
Equipment	Equipment Vendor/ 1ag No. Work Performed		Used	ldle	Repair	Total	
CAT D400E Dump Truck (1)		No activity			-	-	
JD D400 Dump Trucks (4)	- 170,000 mm.	(3) trucks hauling. SW-8 to WST-3	30.0	-	-	30.0	
CAT 324D long stick excavator		SW-8, feeding wet soils down to loading area	10.0	-	-	10.0	
CAT D8R Dozer with disc		Disking all areas	10.0	-	-	10.0	
CAT 345 excavator		Installing GPS System		-	_	-	
CAT 330 Excavator		Loading out wet soil SW-8	10.0	-	-	10.0	
(2) Scrapers: CAT, Case		CAT cutting haul rd by SC-1	10.0	-	-	10.0	
CAT D6 LGP Dozer (2)		HP-5, wet soils, stockpiles. Grading parking lot	10.0			10.0	
Water Trucks (2)		Dust Control.	10.0			10.0	

Material ·		QTY	UOM	Divensor	l ne	livery Verificati	<u>on</u>
Militarian	Vendor	QII	OOM	Purpose	Condtn	Qty Spec	Tags
							T
					-		

#### WORK COMPLETED

Description of Work Executed Today

Safety Briefings, Morning and Afternoon,

SW-8, Load out wet soils on (3) trucks hauling to WST-5.

D6 dozer spreading wet soils at WST-5, grading stockpiles. Second D6 dozer grading trailer parking area.

D8 dozer disking all areas.

CAT track scrapers from WST-3 to stockpile. Switched over to cutting down haul rd by SC-1.

Motorgrader performed grading maintenance of haul roads. Occasionally.

CAT 345 excavator loaded out one haul truck, taking overburden from WST-2 to trailer parking area.

Second water truck ran all day supporting WST-2 excavation of overburden along with hauling to trailer parking area.

#### **HEALTH & SAFETY**

Description of Health & Safety Actions Taken Today / Safety Inspections Conducted

Site Safety Briefing, Topic: Morning: Joe Curillo, New H&S Officer addressed workers, No ball caps worn underneath hard hats.

Afternoon: Hards Hat do not have to be worn in the truck cabs unless terrain is very uneven.

#### **QUALITY CONTROL**

Description of Quality Control Actions Taken Today / Quality Inspections Conducted

Dust Control met requirements. Second water truck ran all day.

### ISSUES AND/OR ITEMS OF DISCUSSION

Discussion of Issues / Concerns / Conversations / Topics

Entact reported water discharging from a 6" HDPE line, Lee Farris, BRC notified. Timet notified and responded.

Lee Farris, Eric Gehringer, Dick Laubinger, Went on haul road tour at Tronox facility.

Kyle Hansen, GES, came to site and took samples of 6" line water discharge

## **DAILY PRODUCTION & QUALITY CONTROL REPORT**

ſ	Project No./Contract No.	Project Title / Location	Day of Report	Report No.
ſ	Task Order	ENTACT, BRC Eastside Common Areas Soils Remediation	23-Jun-08	4
١	13520.003.001.0004	& CAMU Construction Project	23-3411-06	4

SITE VISITORS					
Name	Organization	Purpose of Visit	ln	Out	Signed HASP
Lee Farris, Linda Nations	BRC	Water discharge and site tour.			
Kyle Hansen	GES	Took samples of water. From 6" discharge.			

Contractor Verification: On behalf of WESTON SOLUTIONS, INC., I certify this report is complete and correct, and all work performed and materials and equipment used during this reporting period are in compliance with the contract requirements, specifications, and standards, to the best of my knowledge, except as noted herein.

Report Prepared By / Title

Date Prepared

Signature

Dick Laubinger, Construction Manager

23-Jun-08

Ver 1.1 11/07 3 of 8

841 Bishop Street, Suite 2301 Honolulu, HI 96813 Phone: 808.275.2900 Fax: 808.585.7378



## **DAILY PRODUCTION & QUALITY CONTROL REPORT**

Project No./Contract No.	Project Title / Location	Day of Report	Report No.
Task Order	ENTACT, BRC Eastside Common Areas Soils Remediation	00 100 00	<u> </u>
13520.003.001.0004	& CAMU Construction Project	23-Jun-08	4

DAILY PHOTO LOG	
DAILT PROTO EOG	
Photo 1	Photo 2
•	
3.5-Inch Width or 2.63-Inch Height	3.5-Inch Width or 2.63-Inch Height
3.5-mon whate of 2.65-mon neight	3.5-Mor Width Or 2.05-Mor neight
Insert Picture Description	
Photo 3	Photo 4
O. C. Look Wildth ov O. CO. Look Mainte	O. F. Inah Widhla av O. CO Inah Hajaht
3.5-Inch Width or 2.63-Inch Height	. 3.5-Inch Width or 2.63-Inch Height

Ver 1.1 11/07 4 of 8

Suite 810 143 Union Boulevard Lakewood, CO 80228



#### **CONSTRUCTION QUALITY CONTROL PREPARATORY INSPECTION** Project No./Contract No. Project Title / Location Day of Report Inspection Time **Task Order ENTACT, BRC Eastside Common Areas Soils Remediation** 13520.003.001.0004 & CAMU Construction Project **DEFINABLE WORK ELEMENT** Work Description Spec Section Code Criteria **INSPECTOR** Signed Name Lic / Cert Signature Company HASP Υ PERSONNEL PRESENT [Crew Leaders for Work Element] Signed Signed Name Organization Name Organization HASP HASP INSPECTION CHECKLIST Place an "X" under YES or NO in response to the following YES NO\* 1. Review of Contract Requirements has been completed (SOW, Construction Documents, Code Criteria). Identified Х variances are noted. Verify that all materials and/or equipment has been submitted and approved, and if required, have been tested. Verify that provisions have been made to provide for required control inspection and testing. Work area has been examined to ensure that all required preliminary work has been completed and in compliance with the Contract Requirements. Required materials, equipment, and sample work have been examined or inspected to ensure that they are on-hand, conform to approved shop drawings or submitted data, and are properly stored.

9.	Verify that the portion of the plan for the work to be performed has been accepted by the Contracting Officer or official representative. [And Client has been notified at least 48 hours in advance (or other notifications as may be required by contract) of beginning any of the required activities under this Feature of Work].	
10.	The results of the Preparatory Phase Inspection (e.g., acceptable workmanship, actions required, etc.) are documented on this form, and additional sheets as necessary, and are attached to the Daily Production & Quality Control Report.	
* Exp	plain any NO responses (attach additional sheets if necessary)	

Procedures for executing this work element, including elimination of repetitive deficiencies, have been discussed with

8. Construction tolerances and workmanship standards for the phase of work being inspected have been described and

applicable field crew(s) and subcontractors.

clearly conveyed.

Ver 1.1 11/07 5 of 8

Activity Hazard Analyses have been reviewed to ensure that safety requirements are met.

Suite 810 143 Union Boulevard Lakewood, CO 80228



### **CONSTRUCTION QUALITY CONTROL INITIAL / FOLLOW-UP INSPECTION** Project No./Contract No. Project Title / Location Day of Report Inspection Time Task Order **ENTACT, BRC Eastside Common Areas Soils Remediation** 23-Jun-08 1500 13520.003.001.0004 & CAMU Construction Project DEFINABLE WORK ELEMENT Work Description Spec Section Code Criteria INSPECTOR Signed Name Lic / Cert Signature Company HASP PERSONNEL PRESENT [Crew Leaders for Work Element] Signed Name Organization Name Organization HASP HASP INSPECTION CHECKLIST Place an "X" under YES or NO in response to the following YES NO\* 1. Preliminary work is in compliance with the Contract Requirements. Χ 2. Required control inspection and testing is in compliance with the Contract Requirements. Workmanship standards established at the outset of this activity are acceptable and are in conformance with client and prime contractor expectations. Workmanship and production rates are in conformance with the established standards. 5. Any differences or conflicts in work scope or with contract specifications have been brought to the attention of the subcontractor and have been resolved. All activities are in compliance with the Safety Plan and applicable Activity Hazard Analyses. Client notified at least 48 hours in advance of beginning the initial phase of work for this Feature of Work. The Initial or Follow-Up Meeting has been conducted by the Project QA/QC Lead and was attended by the appropriate site personnel and the work leaders responsible for this Feature of Work. Initial Phase Inspection has been repeated for each new crew to work on-site or at any time specified quality standards are not being met 10. The results of the Initial or Follow-Up Phase Inspection (e.g., acceptable workmanship, actions required, etc.) are documented on this form, and additional sheets as necessary, and are attached to the Daily Production & Quality Control Report. \* Explain any NO responses (attach additional sheets if necessary)

Ver 1.1 11/07 6 of 8

Suite 810 143 Union Boulevard Lakewood, CO 80228



### DAILY FIELD TAILGATE SAFETY MEETING REPORT Project No./Contract No. Project Title / Location Day of Report **Task Order ENTACT, BRC Eastside Common Areas Soils Remediation** 23-Jun-08 13520.003.001.0004 & CAMU Construction Project **EMERGENCY LOCATIONS** Name Address Phone No. **Nearest Phone** 720-641-8660 **WORK ACTIVITIES (THIS SHIFT)** Refer to Health & Safety Plan / Activities Hazard Analysis HASP Risk Level PPE Requirement Topic Act. No Task Description Page Chem Phys Level Covered **ADDITIONAL SITE HAZARDS** Risks not identified within Health & Safety Plan / Activities Hazard Analysis HAZARDS (CHEMICAL / PHYSICAL / BIOLOGICAL) Topic Description of Potential Hazards / Risks Safety Procedures & Special Equipment/Techniques **DISCUSSION TOPICS** AHA Potential Hazards and Control Measures Discussed Today Daily Work Scope & Activity Hazards Additional Safety Topics Discussed Today Additional Comments / Special Topics (Incidents, Actions Taken, Items of Concerns, Etc.) Discussed Today

Ver 1.1 11/07 7 of 8

## DAILY FIELD TAILGATE SAFETY MEETING REPORT

Project No./Contract No. Project Title / Location



Day of Report

23-Jun-08

# Task Order ENTACT, BRC Eastside Common Areas Soils Remediation 4 CAMU Construction Project

TAILGATE SAFETY MEETING ATTENI Print Name	Organization	Sign Name
•••		
	and the state of t	
,		
	NO TO AN	
TOTAL TIME AND THE CONTRACT OF		
7.74.74.74.74.74.74.74.74.74.74.74.74.74		**************************************
MINISTRACTION		
	, , , , , , , , , , , , , , , , , , , ,	
19 1 19 1 4 19 to 19 to the second se		
		- ORBERTACIONAL -
4	·	
	·	
		· · · · · · · · · · · · · · · · · · ·

Meeting Conducted By	Phone	Signature	Start Time	Completed