Basic Remediation Company 875 West Warm Springs Road Henderson, Nevada 89011



			G REAL PROPERTY	1. S. S. S. S. 10	Set and set of the set	the second s	1.541.541.54	PANY	
	D	AILY PRODUC	CTION & QU	JALITY CO	ONTE	ROL REPO	DRT		
Project	t No./Contract No.		Project Tit	e / Location			Day of Report	Report	t No.
	6389	BRC Eas	tside Common	Areas Soils R	emedia	tion	07-Nov-08	124	4
_									
ROJEC	T POINTS OF CO	STATES STATES							
00.000	Position JECT MANAGER	Nam	10	Ifarris@landw	fail Add	0.850		ne No.	_
1.5.0. June 1. D. A	JECT MANAGER	Lee Farris, On site. Ranajit Sahu		sahuron@ear				67-0400 67-0400	
1201210104233	ROJECT MANAGER	Dan Brennecke		Dan.Brennecke@westonsolutions.c				0-5886	-
onstructi	ion Manager	Richard Laubinger		Richard.Laubi	nger@	westonsolution	720-64	1-8660	
VEATHE	R CONDITIONS			ilar 🖓 🖓 🛛					
		Conditions		Ten	1p (F)	Wind	Add'l F Precip. (h.07)	teadings	_
AM	Sunny/Clear	PM	Sunny/Clear	High	68	NE 8mph	Humidity (%)		_
	Weather Comments								
0 mph,	in AM. 10 mph, (N	INE) in the PM.							
_					_				
N-SITE	WESTON PERSO	the bill state of the second			de l'au	de Bast		14.44	
lak Law	Name	Position				rk Performed		Y/N	_
lick Laub Ian Brenr		Construction Manag Project Manager. CM		uction Managen uction Managen				YN	-
Richard D	110.2.1.1.	Project Engineer		uction Managen				Y	
hris Whit	te	Assist. Const. Mgr		uction Manager				Y	
Vayne Ho		Assist. Const. Mgr		uction Managen				Y	
Kevin Coo		Assist. Const. Mgr		uction Managen				Y	
une Laut	binger	Admin Assistant	Constr	uction Managen	nent Ser	vices.		Y	-
N.SITE	GEOSYNTEC PE	BSONNEL							
-SITE	Name	Position		Tra	de / Wo	rk Performed		Y/N	
Greg Cord	Transferra	Design Engineer	Oversi		1007 110	ar onormou		N	_
Dan Stree		QA Manager		Oversight Oversight				Y	-
lim Cox		QA/QC Supervisor		Oversight				N	
Robecca	Flynn	Engineer	Oversi					N	
Vayne W		QA/QC Tech		Oversight			Y		
Brent Bart	Charles and an	QA/QC Tech		Oversight				Y	
Camon Li		QA/QC Tech	Oversi	ght				Y	n=
JN-SITE	SUPPORT PERS								2
	Name	Position			ide/Wo	rk Performed		Y/N	_
	locker, Tetra Tech	Air Monitoring Speci		nitoring,				N	_
	no, Tetra Tech cheux, Tetra Tech	Air Monitoring Speci Air Monitoring Speci		nitoring, nitoring				Y N	
ony rau	choux, rolla room	Par Montoring open		intoring				N	
									-
OVERSI	TE PERSONNEL								
	Name	Position		Tra	ide / Wo	rk Performed		Y/N	
)evin Gor	rdon, McGinley	Oversight	For N	EP	_			Y	
Dock Kim		Field Observation	For Al					Ý	-
loe Ludio	w, ASW	Inspector		nspector				Y	
	rrow, ASW	Inspector		nspector				N	_
Brian Rak	Contraction of the Contraction o	Inspector	NDEP	1 m 0 1		_		N	
PBS&J, S	CONTRACTOR	Surveyors	Survey	ring, QA			_	Y	
SINGINE	Name	Company	6)	Te	ada / Wo	rk Performed		Y/N	
Erik Gerin	All the set	Entact		Manager				Y	-
losh Carr		Entact	the second se	roject Manager				Y	-
Russ Karr		Entact		de, Superintend	ent			Y	
Michael C	Contract of the second s	Entact	Engine	er				Y	1
loe Curill		Entact		& Safety Office				Y	_
Timothy S	Stadt	Entact		and Safety Tec		al Dat		Y	
dloce		Entact Entact		ipment Operato		ICK Drivers		Y	-
Ed Long Lance Bru	uce	Entact		 Superintender & Safety Office 				Y	-
			risalu	a ounty onloc					-
	ntire	Entact	CSP, S					N	
Rick McIn								1	
Rick McIn		American Asphalt		pment operators	5			N	
Rick McIn		American Asphalt American Asphalt Environmental Spec	1 Supe	pment operators printendent Superintenden				N N Y	_

DAILY PRODUCTION & QUALITY CONTROL REPORT

Project No./Contract No.	Project Title / Location Day of R			Report No.	
6389	BRC Eastside Co	07-Nov-08	124		
	Environmental Specialties,Inc	12 Laborers/ Seamers		Y	
	Kenney Survey	CAMU		N	
	ABC Survey	Eastside/CAMU		Y	

ON-SITE EQUIPMENT Equipment Vendor / Tag No. Work Performed CAT D400E Dump Truck (2) CAMU JD D400 Dump Trucks (8) Fastside CAT 324D long stick excavato CAMIL CAT D8R Dozer with disc Eastside CAT 345 excavator Fastside CAT 330 Excavator Eastside Case double pan scrapers. Fastside CAT D6 LGP Dozer (2) Eastside Water Trucks (2) Fastside 637/631 Cat Scrapers (6) CAMU CAT 16H Grader CAMU CAT D-10 Dozer CAMU CAT Water Wagon CAMU CAT D-6 Dozer CAMU CAT 14H Grader CAMU Gradall CAMU JLG CAMU IR Smooth drum Roller CAMU, Phase 1

Tenent Street Sweeper		Eastside and CA	AMU	
Bomag Smooth drum Roller		CAMU, Phase 1		
MATERIAL HANDLING (ON-	SITE DELIVERY / REMOVA	L)		
Material	Vendor	Today UOM	Purpose	Delivery Verification

					10 DHE LAV 4 SDEC	1 1405
GCL	CETCO	0	rolls	For CAMU, On site	207	
Geocomposite	Agru	0	rolls	For CAMU, On site	194	
Geomembrane	Agru	0	rolls	For CAMU, On site	82	

WORK COMPLETED

Description of Work Executed Today Eastside Mixing and Drying Activity:

- Day Shift:

Continued powerscreening operation in 7A. Worked on tarps and rails for haul trucks. Prepared area for night haul operations.

CAMU Activity:

Excavation

Day Shift: Continue fine grading of floor in Phase II.
 Rolled side slopes in Phase II.
 Continued excavation of NE Equilization Basin. Waste relocation.
 ESI continued placing liner in Phase II.
 Worked on as-built survey in western ditch portion of Phase II.
 Prepared area for night haul operations.

- Night Shift: No Activity.

Embankment

- Phase 1 embankment, complete.

- Phase 1 estimated cummulative embankment placed: 0 cy

Waste Placement

Phase 1 estimated	daily waste placed: 46 loads @ 20cy/load = 920 cy
	night shift placed: 0 loads @ 20cy/load = 0 cy
Phase 1 estimated	cummulative waste placed: 162,078 cy. Western Ditch, NE Equilization and Eastside beta stockpile.
Phase 1 Operation	as Layer placed. completed. Cumulative total: 21,662
	*:

- Phase 1 GCL placed:0 sf daily, 307,372 sf cummulative.

Phase 1 Geomembrane:0 sf daily, 307,372 sf cummulative

- Phase 1 Geocomposite: 0 sf daily, 307,372 sf cummulative.

- Phase 1 Geotextile: (0) sf daily. 69,340 sf cummulative.

Phase 2 GCL placed: 55,000 sf daily, 172,000 sf cummulative.

-Phase 2 Geomenbrane: 55,000 sf daily, 172,000 sf cummulative.

-Phase 2 Geocomposite: 0 sf daily, 0 sf cummulative.

-

.

.

D	AILY PRODUCTION 8	QUALITY CONTROL REP	PORT	
Project No./Contract No.	Proje	ect Title / Location	Day of Report	Report No
6389	BRC Eastside Com	mon Areas Soils Remediation	07-Nov-08	124
	<i>r</i>			
Other:				
HEALTH & SAFETY	tions Taken Today / Safety Inspection	a Pandualad		
Entact H&S Tailgates Safety Topic: Eastside: Worki		o donadado		
	cussed working around overhead	power lines.		
Night shift: No Activity.				
Safety Incidents: No				
Dust Incidents: No issues.				
				_
Description of Quality Control Act	Y ASSURANCE & QUALITY C ions Taken Today / Quality Inspection			
	on in Phase II western ditch area.	ase I associated with waste placement on	the day shift	
	ng of project documents and data		ine day shin.	
		se 1, II and IIIA. Several items noted and p	assed on to the cor	ntractor at Pl
of the Day mooning.				
				_
ISSUES AND/OR ITEMS O Discussion of Issues / Concerns	Conversations / Topics			
Dirt clog found on CAMU	haul road. Entact cleaned up imme	ediately.		
SITE VISITORS				_
Name	Organization	Purpose of Visit		
Provide Street Street		Data Deserved	Circuit	
Report Prepared By / Title Dick Laubinger, Construc		Date Prepared 7-Nov-08	Signature	

Basic Remediation Company 875 West Warm Springs Road Henderson, Nevada 89011

DAILY PRODUCTION & QUALITY CONTROL REPORT

Project No./Contract No.	Project Title / Location	Day of Report	Report No.
6389	BRC Eastside Common Areas Soils Remediation	07 Nov 08	104
0	0	07-Nov-08	124

DAILY PHOTO LOG

Photo 1







CAMU: Northeast Equalization Basin, chasing impacted soils and debris.



CAMU: Phase II Subgrade and liner installation looking East.

Photo 4



CAMU: Phase II, subgrade and liner installation also looking east.