Basic Remediation Company 875 West Warm Springs Road Henderson, Nevada 89011



DAILY PRODUCTION & QUALITY CONTROL REPORT Project No./Contract No. Project Title / Location Day of Report Report No. 6389 BRC Eastside Common Areas Soils Remediation 04-Dec-08 148

PROJECT POINTS OF CONTACT						
Position	Name	E-Mail Address	Phone No.			
BRC PROJECT MANAGER	Lee Farris	Ifarris@landwellco.com	702-567-0400			
BRC PROJECT MANAGER	Ranajit Sahu	sahuron@earthlink.net	702-567-0400			
CONST. PROJECT MANAGER	Dan Brennecke	Dan.Brennecke@westonsolutions.c	970-260-5886			
Construction Manager	Richard Laubinger	Richard.Laubinger@westonsolution	720-641-8660			

	STATE OF STA							
Conditions		Tem	Temp (F)		ind	Add'l Readings		
AM	Olevedo	PM	Claude	Low	41			Precip. (In/Dy.)
AW	Cloudy	1-151	Cloudy	High	60	ESE	7mph	Humidity (%)

0 mph, in AM. 7 mph in PM.

Name	Position	Trade / Work Performed	Y/N
Name	Position		1/14
Dick Laubinger	Construction Manager	Construction Management Services.	Y
Dan Brennecke	Project Manager. CM	Construction Management Services.	N
Richard Davis	Project Engineer	Construction Management Services.	Y
Chris White	Assist. Const. Mgr	Construction Management Services.	Y
Nayne Hodgson	Assist. Const. Mgr	Construction Management Services.	Y
Kevin Cooke	Assist. Const. Mgr	Construction Management Services.	Y
June Laubinger	Admin Assistant	Construction Management Services.	Y

Name	Position	Trade / Work Performed	Y/N
Greg Corcoran	Design Engineer	Oversight	N
Dan Street	QA Manager	Oversight	Y
Jim Cox	QA/QC Supervisor	Oversight	Y
Robecca Flynn	Engineer	Oversight	N
Wayne Wofford	QA/QC Tech	Oversight	Y
Roland Derosier	QA/QC Tech	Oversight	Y
Camon Liddell	QA/QC Tech	Oversight	Y
Jeremy Osborn	QA/QC Tech	Oversight	Y

Name	Position	Trade / Work Performed	Y/N
Doug Herlocker, Tetra Tech	Air Monitoring Specialist	Air Monitoring,	N
Becky Dano, Tetra Tech	Air Monitoring Specialist	Air Monitoring,	Y
Jerry Faucheux, Tetra Tech	Air Monitoring Specialist	Air Monitoring	N

OVERSITE PERSONNEL			
Name	Position	Trade / Work Performed	Y/N
Mark Eizman, ASW	Inspector	Liner Inspector	Y
Devin Gordon, McGinley	Oversight	For NDEP	Y
Dock Kim, ATC	Field Observation	For AIG	Y
Joe Ludlow, ASW	Inspector	Liner Inspector	N
Steve Morrow, ASW	Inspector	Liner Inspector	N
Brian Rakvica	Inspector	NDEP, Site visit	N
PBS&J, Survey	Surveyors	Surveying, QA	N
ON-SITE CONTRACTOR	PERSONNEL	Sac with the least the property of the second second second	
Name	Company	Trade / Work Performed	Y/N

Brian Rakvica	Inspector	NDEP, Site visit	N
PBS&J, Survey	Surveyors	Surveying, QA	N
ON-SITE CONTRACTO	R PERSONNEL		
Name	Company	Trade / Work Performed	Y/N
Erik Geringer	Entact	Project Manager	Y
Josh Carrol	Entact	Asst Project Manager	Y
Russ Karnes	Entact	Eastside, Superintendent	Y
Michael Carlson	Entact	Engineer	Y
Joe Curilla	Entact	Health & Safety Officer	Y
Timothy Stadt	Entact	Health and Safety Technician	Y
	Entact	26 Equipment Operators & Truck Drivers	Y
Ed Long	Entact	CAMU, Superintendent	Y
Lance Bruce	Entact	Health & Safety Officer	Y
Terry Harper	Entact	CAMU, Superintendent	Y
Rick McIntire	Entact	CSP, Safety	Y
Dale Walsh	Converse	CSP, Safety	N

Ver 1.1 11/07 1 of 4

DAILY PRODUCTION & QUALITY CONTROL REPORT

Project No./Contract No.	Project Title / Location	Day of Report	Report No.
6389	BRC Eastside Common Areas Soils Remediation	04-Dec-08	148
		04-Dec-06	140

Entact	Asst Project Manager	I Y I
Environmental Specialties,Inc	1 Liner Superintendent	Y
Environmental Specialties,Inc	12 Laborers/ Seamers	Y
Kenney Survey	CAMU	N
ABC Survey	Eastside/CAMU	Y
	Environmental Specialties,Inc Environmental Specialties,Inc Kenney Survey	Environmental Specialties,Inc Environmental Specialties,Inc Environmental Specialties,Inc I2 Laborers/ Seamers Kenney Survey CAMU

ON-SITE EQUIPMENT		e is a front of the base of the life of				
Equipment	Vendor / Tag No.	Work Performed			1	
CAT D400E Dump Truck (2)		CAMU	-	-	-	-
JD D400 Dump Trucks (8)		Eastside		-	-	-
CAT 324D long stick excavator		CAMU	-	-	-	-
CAT D8R Dozer with disc		Eastside .		-	-	-
CAT 345 excavator		Eastside		-	-	-
CAT 330 Excavator		Eastside		-	-	-
Case double pan scrapers.		Eastside		-	-	-
CAT D6 LGP Dozer (2)		Eastside				
Water Trucks (2)		Eastside				-
637/631 Cat Scrapers (6)		CAMU				-
CAT 16H Grader		CAMU				-
CAT D-10 Dozer		CAMU				-
CAT Water Wagon		CAMU				-
CAT D-6 Dozer		CAMU				-
CAT 14H Grader		CAMU				-
Gradall		CAMU				-
JLG		CAMU				-
IR Smooth drum Roller		CAMU, Phase 1				-
Tenent Street Sweeper		Eastside and CAMU				-
Bomag Smooth drum Roller		CAMU, Phase 1				-
Chieftain 1400 Powerscreener		Eastside, screening 1" minus				-
						-

MATERIAL HANDLING	(ON-SITE DELIVERY / REMOVA	L)						
Material	Vendor	Today	UOM	Purpose	Delivery Verificati		rificatio	on
Material	Velluol	Touay	OOW	Fulpose	to date (Qty	Spec	Tags
GCL	CETCO	0	rolls	For CAMU, On site	5	606		
Geocomposite	Agru	0	rolls	For CAMU, On site		99		
Geomembrane	Agru	0	rolls	For CAMU, On site	1	92		

WORK COMPLETED

Description of Work Executed Today

Eastside Mixing and Drying Activity:

- Continued screening moisture conditioned material using powerscreener, (PUB-4).
 Sprinklers watering PUC-3.
 Installed wheel wash bath for trucks by decon pad.

- Performed 3" scraping of an area 50'X50' in 4B.
- Worked on tarps and rails for haul trucks.

- Continued hauling 1* minus material to phase II for operations layer.

 Continued hauling material from beta stockpile to Phase I.

CAMU Activity:

- Day Shift:
- ESI continued installing geocomposite and woven geotextile in Phase II.
- Continued backfill and compaction of anchor trench in Phase II.
- Continued grading North BMI Landfill.
- Continued grading operations layer in Phase II.

- Continued placing 1" minus material in Phase II.
 Continued placing material from beta stockpile in Phase I.

Embankment

- Phase 1 embankment, complete.
- Phase 1 estimated cummulative embankment placed: 0 cy

Waste Placement

- Phase 1 estimated daily waste placed: 0 loads @ 20cy/load = 0 cy.
- night shift placed: 18 loads @ 20cy/load = 360 cy.

 Phase 1 estimated cummulative waste placed: 210,898 cy. Western Ditch, NE Equilization, Eastside beta stockpile and PUA-4.PUB-3.

 Phase 1 Operations Layer placed. completed. Cumulative total: 21,662
- Phase 2 estimated night shift placed: 166 loads @ 20cy/load = 3,320 cy. (13 trucks hauling). Phase 2 Operations I aver placed daily: 3,320 cy. Cumulative total: 28,020 cy.

DAILY PRODUCTION & QUALITY CONTROL REPORT

Project No./Contract No.	Project Title / Location	Day of Report	Report No.
6389	BRC Eastside Common Areas Soils Remediation	04-Dec-08	148
		04-Dec-08	140

- Phase 2 Operations Layer placed. daily: 3,320 cy. Cumulative total: 28,020 cy.

Geosynthetics. Estimated cummulative installed quantity by Phase.

- Phase 1 GCL placed:0 sf daily, 307,372 sf cummulative.
- Phase 1 Geomembrane:0 sf daily, 307,372 sf cummulative
- Phase 1 Geocomposite: 0 sf daily, 307,372 sf cummulative. Phase 1 Geotextile: (0) sf daily. 69,340 sf cummulative.
- Phase 2 GCL placed: (0) sf daily, 498,468 sf cummulative.
- Phase 2 Geomenbrane: (0) sf daily, 498,468 sf cummulative.
- -Phase 2 Geocomposite: (5,592) sf daily, 520,592 sf cummulative.

HEALTH & SAFETY

Description of Health & Safety Actions Taken Today / Safety Inspections Conducted

Entact H&S Tailgates

Safety Topic: Eastside: Wearing rings very dangerous on construction site.

Safety Topic: CAMU, Day: Wearing rings very dangerous on construction site.

Eastside and CAMU, Night shift: Importance of communication.

Safety Incidents: None.

Dust Incidents: None.

CONSTRUCTION QUALITY ASSURANCE & QUALITY CONTROL

escription of Quality Control Actions Taken Today / Quality Inspections Conducted

Daily CQA Summary...

Monitored waste material placement in Phase II as operations layer, (night shift). Monitored waste material placement in Phase I (night Shift.

Monitored installation of geosynthetics in Phase II.

Monitored BMI North subgrade preparation.

Continue review of and updating of project documents and database to facilitate reporting. Performed compaction testing of anchor trench around phase II.

Performed inspection of subgrade on BMI North Landfill. Noted areas that needed attention.

ISSUES AND/OR ITEMS OF DISCUSSION

Inspected BMI North subgrade, Noted small areas needing attention. Geosyntec, Weston, Entact.

Name	Organization	Purpose of Visit	

Report Prepared By / Title

Date Prepared

Signature

Dick Laubinger, Construction Manager

4-Dec-08

3 of 4 Ver 1.1 11/07

Basic Remediation Company 875 West Warm Springs Road Henderson, Nevada 89011

DAILY PRODUCTION & QUALITY CONTROL REPORT

Project No./Contract No.	Project Title / Location	Day of Report	Report No.
6389	BRC Eastside Common Areas Soils Remediation	04-Dec-08	148
0	0	04-Dec-06	140


DAILY PHOTO LOG

Photo 1



CAMU: Phase II looking north.

Photo 2



CAMU: Phase II, placing operations layer.

Photo 3



CAMU: Phase II Southeast corner toe drain installation.

Photo 4



CAMU: Phase II, East slope and floor, geocomposite installed.