Basic Remediation Company 875 West Warm Springs Road Henderson, Nevada 89011



DAILY PRODUCTION & QUALITY CONTROL REPORT

Project No./Contract No.	Project Title / Location	Day of Report	Report No
6389	BRC Eastside Common Areas Soils Remediation	19-Jul-08	26
		19-001-00	20

PROJECT POINTS OF CO	PROJECT POINTS OF CONTACT				
Position	Name	E-Mail Address	Phone No.		
BRC PROJECT MANAGER	Lee Farris	lfarris@landwellco.com	702-567-0400		
BRC PROJECT MANAGER	Ranajit Sahu	sahuron@earthlink.net	702-567-0400		
CONST. PROJECT MANAGER	Dan Brennecke	Dan.Brennecke@westonsolutions.	970-260-5886		
Construction Manager	Richard Laubinger	Richard.Laubinger@westonsolutio	720-641-8660		

	C	onditions		Tem	p (F)	Wind	Add'l Readings
	0	2044	Cumu / Darby Claudly	Low	83		Precip. (nO):
AM	Sunny/Clear	PM	Sunny / Party Cloudly I	High	lgh 109	Olr	Humidity (%)

Calm, to ligh wind.

Name	Position	Trade / Work Performed	Y/N
Dick Laubinger	Construction Manager	Construction Management Services.	Y
Dan Brennecke	Project Manager, CM	Construction Management Services.	N
TBD	Project Engineer	Construction Management Services.	N
TBD	Admin Assistant	Construction Management Services.	N

Hame	Position	Trade / Work Performed	Y/W
Wayne Wofford	QA/QC Tech	Oversight	Y
Brent Barbacane	QA/QC Tech	Oversight	Y
Jim Cox	QA/QC Supervisor	Oversight	N
			_
			_
			_

Name	Position	Trade / Work Performed	Y/N
Doug Herlocker	Air Monitoring Specialist	Air Monitoring	N

Name	Company	Trade / Work Performed	Y/N
Erik Geringer	Entact	Project Manager	Y
Josh Carrol	Entact	Asst Project Manager	Y
Russ Karnes	Entact	Superintendent	Y
Michael Carlson	Entact	Engineer	Y
Joe Curilla	Entact	Health & Safety Officer	Y
Michael Parker	Entact	Health and Safety Technician	Y
	Entact	13 Equipment Operators & Truck Drivers	Y
	American Asphalt	Earthwork Superintendent	Y
	American Asphalt	11 Equipment Operators & Truck Drivers,	Y
	Environmental Specialties,Inc	Liner Superintendent	Y
	Environmental Specialties,Inc	12 Liner laborers	Y

1 of 4 Ver 1.1 11/07

DAILY PRODUCTION & QUALITY CONTROL REPORT

Project Title / Location	Day of Report	Report No.
BRC Eastside Common Areas Soils Remediation	10-101-08	26

Equipment	Vendor / Tag No.	Work Performed				_
CAT D400E Dump Truck (1)		Eastside		-	- 1	
JD D400 Dump Trucks (4)		Eastside		-	-	
CAT 324D long stick excavator		No activity	-	-	-	
CAT D8R Dozer with disc		Eastside			-	
CAT 345 excavator		Eastside			-	
CAT 330 Excavator		Eastside		-	-	
Case double pan scrapers.		Eastside				
CAT D6 LGP Dozer (2)		Eastside				
Water Trucks (2)		Eastside				
637/631 Cat Scrapers (6)		CAMU				
CAT 16H Grader		CAMU				
CAT D-10 Dozer		CAMU				
CAT Water Wagon		CAMU				
CAT D-6 Dozer		CAMU				
CAT 14H Grader		CAMU				
Gradall		CAMU				
Bobcat Skidsteer		CAMU				
JLG		CAMU				
CAT D4 dozer		CAMU				
SAKAI Smooth drum roller		CAMU				
Ingersol Rand Smooth roller		CAMU				

44.4.4.4		O.T.	times		D	elivery.	Verificatio	n
Material	Vandor	613	non	Purpose	Condin	Oty	Spec	Tags
Geocomposite Clay Liner	CETCO	0	rolls	For CAMU				
Geocomposite 60 mil Liner	Agru	0	rolls	For CAMU				

WORK COMPLETED

Description of Work Executed Today

Eastside Mixing and Drying Activity:

-SW-9 Loading out wet soils on (2) trucks, hauling to HP-3. D6 dozer spreading out wet material. SW-9 substantially complete.

- D8 dozer disking all areas.
- D6 dozer grading beta ditch area for future stockpiling.
- Motorgrader grading haul roads.
- Case tractor and scrapers continued cutting down haul rd.
- Estimated dryed material hauled to stockpile: (TBD) cy daily, (TBD)cy cummulative.

CAMU Activity:

Excavation

- Phase 1, Grading East and West slopes, grading floor and hauling material to north stockpile with scrapers.
- (3) scrapers working as needed.
- Excavating Northwest Retension Pond, on hold due to discolored soils. Area has been cordoned off. Samples taken.
- Entact placed 12" clean soil cap over west haul rd and bypass haul rd. Suspect area.
- Entact began changing out caution tape for construction fence.

-Entact 330 CAT Excavator, and (3) Articulating 40 ton dump trucks, continued remediation and hauling discolored soils from top of stockpile. Construction Manager and QA/QC personnel monitored the work.

- (TBD) cy daily, (TBD) cummulative.

Embankmen

- Phase 1 estimated daily embankment placed: 0 cy
- Phase 1 estimated cummulative embankment placed: 0 cy

Waste Placement

- Phase 1 estimated daily waste placed: 0 cy
- Phase 1 estimated cummulative waste placed: 0 cy

Geosynthetics

- Phase 1 GCL placed: 0 sf daily, 0 sf cummulative
- Phase 1 Geomembrane: 0 sf daily, 0 sf cummulative
- Phase 1 Geocomposite: 0 sf daily, 0 sf cummulative
- Phase 1 Geotextile: 0 sf daily, 0 sf cummulative

Other

DAILY PRODUCTION & QUALITY CONTROL REPORT Project Title / Location Day of Report Report No. Project No./Contract No. 6389 **BRC Eastside Common Areas Soils Remediation** 19-Jul-08 26

Perimeter Fence	Inspection and Repair	

Inspection no findings.

HEALTH & SAFETY

n of Health & Safety Actions Taken Today / Safety Inspections Conducted

Entact H&S Tailgates

Morning: Hygiene, Hand to mouth.

Afternoon: Heat stress.

American Asphalt Tailgates

Morning: Stop work responsibility of all workers. Site traffic, watch for other trucks and equipment also visitors. Liner trucks delivering.

QUALITY CONTROL

l Actions Taken Today / Quality Inspections Conducted

Daily CQA Summary

Inspected GCL liner cover added sand bags to secure for weekend.. Monitored CAMU stockpile remediation/removal of discolored soils.

Deviations from CQA Plan None

ISSUES AND/OR ITEMS OF DISCUSSION

- 1. Cap haul rds with 12" clean soils, where discolored soils may continue below grade.
- 2. Change out caution tape for construction fence around discolored soils areas. In progress.

EVISITORS			
Namo	Organization	Purpose of Visit	
	11	*	
			-

Report Prepared By / Title

Date Prepared

Signature

Dick Laubinger, Construction Manager

19-Jul-08

Ver 1.1 11/07 3 of 4

Weston Solutions, Inc

841 Bishop Street, Suite 2301 Honolulu, HI 96813 Phone: 808.275.2900 Fax: 808.585.7378



DAILY PRODUCTION & QUALITY CONTROL REPORT

Project No./Contract No.	Project Title / Location	Day of Report	Report No.
6389	BRC Eastside Common Areas Soils Remediation	19-Jul-08	26
0	0		

DAILY PHOTO LOG

Photo 1



CAMU, West side haul rd. showing 12" capping. Along with construction fencing that replaced cation tape.

Photo 2



CAMU: West side haul rd. showing 12"capping

Photo 3

3.5-Inch Width or 2.63-Inch Height

Photo 4

3.5-Inch Width or 2.63-Inch Height