

| DAILY PRODUCTION & QUALITY CONTROL REPORT |   |               |            |  |  |
|---|---|---------------|------------|--|--|
| Project No./Contract No.                  | Project Title / Location                    | Day of Report | Report No. |  |  |
| 6389                                      | BRC Eastside Common Areas Soils Remediation | 25-Aug-08     | 57         |  |  |

| Position               | Name                 | E-Mail Address                  | Phone No.    |
|------------------------|----------------------|---------------------------------|--------------|
| BRC PROJECT MANAGER    | Lee Farris, On Site. | lfarris@landwellco.com          | 702-567-0400 |
| BRC PROJECT MANAGER    | Ranajit Sahu         | sahuron@earthlink.net           | 702-567-0400 |
| CONST. PROJECT MANAGER | Dan Brennecke        | Dan.Brennecke@westonsolutions.o | 970-260-5886 |
| Construction Manager   | Richard Laubinger    | Richard.Laubinger@westonsolutio | 720-641-8660 |

| WEAT       | HER CONDITIONS |                  |                      |      |      |     |                | <b>经验证证据的证据的</b> |
|------------|----------------|------------------|----------------------|------|------|-----|----------------|------------------|
| Conditions |                |                  | Temp (F)             |      | Wind |     | Add'l Readings |                  |
|            | - 101          | 211              | The same de mate man | Low  | 82   |     |                | Precip. (In/Dy.) |
| AM         | Sunny/Clear    | PM Thunderstorms | Thunderstorms        | High | 105  | ENE | 3mph           | Humidity (%)     |

Additional Weather Comments

3mph in morning. Afternoon thunderstorm, High wind for approximately twenty minutes along with heavy rain in areas. CAMU side hit more than Eastside.

| N-SITE WESTON PERSO  | NNEL                           | <b>,以及其中的人类,不是是一种人类的人类的。</b>   |     |
|--|--------------------------------|--|-----|
| Name   | Position                       | Trade / Work Performed   | Y/N |
| ick Laubinger  | Construction Manager           | Construction Management Services.  | Y   |
| an Brennecke   |                                | Construction Management Services.  | N   |
| Dave Gertz   | Project Engineer               | Construction Management Services.  | Y   |
| une Laubinger  |                                | Construction Management Services.  | Y   |
| inda Nations   |                                | Construction Management Services   | Y   |
|  |                                |  |     |
| ON-SITE GEOSYNTEC PE   | RSONNEL                        | and the state of t |     |
| Name   | Position                       | Trade / Work Performed   | Y/N |
| Vayne Wofford  | QA/QC Tech                     | Oversight  | Y   |
| Brent Barbacane  | QA/QC Tech                     | Oversight  | Y   |
| Jim Cox  | QA/QC Supervisor               | Oversight  | N   |
| Greg Corcoran  | Engineer of Record             | Oversight  | N   |
| Robecca Flynn  | Engineer                       | Oversight  | N   |
| Camon Liddell  | QA/QC Tech                     | Oversight  | Υ   |
| Dan Street   | QA Manager                     | Oversight  | Υ   |
| ON-SITE SUPPORT PERS   | ONNEL                          | A STATE OF THE STA |     |
| Name   | Position                       | Trade / Work Performed   | Y/N |
| Doug Herlocker, Tetra Tech   | Air Monitoring Specialist      | Air Monitoring, Sampling results non detect, TO- 10A.  | N   |
| Becky Dano, Tetra Tech   | Air Monitoring Specialist      | Air Monitoring,  | Y   |
| Jerry Faucheux, Tetra Tech   | Air Monitoring Specialist      | Air Monitoring   | Y   |
| ,  |                                |  |     |
|  |                                |  |     |
|  |                                |  |     |
| AND THE RESERVE OF THE PARTY OF |                                |  |     |
| OVERSITE PERSONNEL   |                                |  |     |
| Name   | Position                       | Trade / Work Performed   | Y/N |
| Scott McKeag, McGinley   | Oversight                      | For NDEP   | N   |
| Devin Gordon, McGinley   | Oversight                      | For NDEP   | Y   |
| Dock Kim, ATC  | Field Observation              | For AIG  | Y   |
| Ron Perry, ASW   | Inspector                      | For NDEP, On site for OPS layer placement beginning  | N   |
| PBS&J, Survey  | Surveyors                      | ,  | N   |
| , Boas, carry  |                                |  |     |
| ON-SITE CONTRACTOR I   | DEDSONNEL                      |  |     |
| Name   | Company                        | Trade / Work Performed   | Y/N |
|  |                                | Project Manager  | Y   |
| Erik Geringer  | Entact                         |  | Y   |
| Josh Carrol  | Entact                         | Asst Project Manager   | Y   |
| Russ Karnes  | Entact                         | Eastside, Superintendent   | Y   |
| Michael Carlson  | Entact                         | Engineer   | Y   |
| Joe Curilla  | Entact                         | Health & Safety Officer  | Y   |
| Michael Parker   | Entact                         | Health and Safety Technician   | Y   |
|  | Entact                         | 22 Equipment Operators & Truck Drivers   |     |
| Ed Long  | Entact                         | CAMU, Superintendent   | Y   |
|  | American Asphalt               | Earthwork Superintendent   | Y   |
|  | American Asphalt               | 11 Equipment Operators & Truck Drivers,  | Y   |
| Rick McIntire  | Entact                         | CSP, Safety  | Y   |
|  |                                |  |     |
|  | Environmental Specialties,Inc  | Liner Superintendent   | Y   |
|  |                                |  | Y   |
|  | Environmental Specialties,Inc  | 12 Liller laborers   |     |
|  | Environmental Specialties, Inc | CAMU   | Y   |

1 of 3 Ver 1.1 11/07

| DAILY PRODUCTION & QUALITY CONTROL REPORT |   |               |            |  |  |  |  |
|---|---|---------------|------------|--|--|--|--|
| Project No./Contract No.                  | Project Title / Location                    | Day of Report | Report No. |  |  |  |  |
| 6389                                      | BRC Eastside Common Areas Soils Remediation | 25-Aug-08     | 57         |  |  |  |  |
|   |   |               |            |  |  |  |  |
|   |   |               |            |  |  |  |  |
|   | ,   |               |            |  |  |  |  |
|   |   |               |            |  |  |  |  |

| ON-SITE EQUIPMENT             | <b>经验证的</b>      | 中华中央政策 美国人民主义 医二十二十二十二十二十二十二十二十二十二十二十二十二十二十二十二十二十二十二十 |   |   |   |   |
|-------------------------------|------------------|---|---|---|---|---|
| Equipment                     | Vendor / Tag No. | Work Performed  |   |   |   |   |
| CAT D400E Dump Truck (2)      |                  | CAMU  | - | - | - |   |
| JD D400 Dump Trucks (6)       |                  | Eastside  |   | - | - |   |
| CAT 324D long stick excavator |                  | CAMU  | - | - | - |   |
| CAT D8R Dozer with disc       |                  | Eastside  |   | - | - |   |
| CAT 345 excavator             |                  | Eastside  |   | - | - |   |
| CAT 330 Excavator             |                  | Eastside  |   | - | - |   |
| Case double pan scrapers.     |                  | Eastside  |   | - | - |   |
| CAT D6 LGP Dozer (2)          |                  | Eastside  |   |   |   |   |
| Water Trucks (2)              |                  | Eastside  |   |   |   |   |
| 637/631 Cat Scrapers (6)      |                  | CAMU  |   |   |   |   |
| CAT 16H Grader                |                  | CAMU  |   |   |   |   |
| CAT D-10 Dozer                |                  | CAMU  |   |   |   |   |
| CAT Water Wagon               |                  | CAMU  |   |   |   |   |
| CAT D-6 Dozer                 |                  | CAMU  |   |   |   |   |
| CAT 14H Grader                |                  | CAMU  |   |   |   |   |
| Gradall                       |                  | CAMU  |   |   |   |   |
| Bobcat Skidsteer              |                  | CAMU  |   |   |   |   |
| JLG                           |                  | CAMU  |   |   |   |   |
| CAT D4 dozer                  |                  | CAMU  |   |   |   |   |
|                               |                  |   |   |   |   |   |
|                               |                  |   |   |   |   |   |
|                               |                  |   |   |   |   |   |
|                               |                  |   |   |   |   |   |
|                               |                  |   |   |   |   | - |
|                               |                  |   |   |   |   |   |

| MATERIAL HANDLIN | <b>G</b> (ON-SITE DELIVERY / REMOVAL) |     |       |          |                       |     |      |      |  |
|------------------|---------------------------------------|-----|-------|----------|-----------------------|-----|------|------|--|
|                  |                                       | OTM | 11011 | Purpose  | Delivery Verification |     |      |      |  |
| Material         | Vendor                                | GIY | MOU   |          | Condtn                | Qty | Spec | Tags |  |
| GCL              | CETCO                                 | 0   | rolls | For CAMU |                       |     |      |      |  |
| Geocomposite     | Agru                                  | 0   | rolls | For CAMU |                       |     |      |      |  |
| Woven Geotextile |                                       | 0   | rolls | For CAMU |                       |     |      |      |  |

## WORK COMPLETED

## Eastside Mixing and Drying Activity:

- Loading out wet material from SW-4 using 345 excavator. (4) haul trucks hauling to dry ponds. 155 loads, (3,100) cy.
   D6 dozer spread wet soils at the dry ponds and spread prepared soils at the beta ditch.
   D8 Dozer continued disking operation.

- Us uozer continued disking operation.

  Loading out, final scrapings (SW-6) haul to Sewer Realignment crossroad and beta ditch. 65 loads 22cy/load = 1,430 cy 2 trucks Versatile tractor and Pans. 0 loads, (0) cy. No Activity.

  Motorgrader maintaining roads. Water truck managing dust control.

  Continued installing Crossover Road at Sewer Realignment corridor.

  Continued pumping water from SC-1 to SW-12.

#### CAMU Activity:

- Northwest Detention Basin excavation 631/637 scrapers (1,200) cy.
  Western Ditch. Power screener screening operations layer.
  Entact maintained 12" clean soil cap over west haul rd and bypass rd.
- Continued Anchor trench backfill.

- Phase 1 embankment, complete.
- Phase 1 estimated cummulative embankment placed: 0 cy

## Waste Placement

- Phase 1 estimated daily waste placed: 0 cy
  Phase 1 estimated cummulative waste placed: 0 cy
- Phase 1 Operations Layer placed daily 41 loads, (738) cy

## Geosynthetics

- Phase 1 Liner crew installed caps on LCRS Pipe.
- Phase 1 GCL placed: 0 sf daily, 347,067 sf cummulative.
- Phase 1 Geomembrane:0 sf daily, 365,136 sf cummulative
- Phase 1 Geocomposite: 0 sf daily, 327,600 sf cummulative.
- Phase 1 Geotextile: (0) sf daily..

Other: Continued installing Crossover road at Sewer realignment corridor.

2 of 3 Ver 1.1 11/07

#### DAILY PRODUCTION & QUALITY CONTROL REPORT Project Title / Location Day of Report Report No. Project No./Contract No. **BRC Eastside Common Areas Soils Remediation** 57 25-Aug-08

Perimeter Fence Inspection and Repair.

#### **HEALTH & SAFETY**

Description of Health & Safety Actions Taken Today / Safety Inspections Conducted

#### Entact H&S Tailgates

Morning: BBS and Defensive Driver Training, Saturday for Employees interested.

ESI. Liner Crew: Off Site.

Afternoon: Entact BBS safety.

<u>American Asphalt Tailgates</u> Morning: Stockpile safety with scrapers.

Safety Incidents: No Incidents.

## QUALITY CONTROL

Daily CQA Summary.
Inspected 12\* capped haul roads for degradation. All areas ok.
Operations layer placement on liner halted at 11:45. Wrinkles beginning.
Compaction testing phase 1 anchor trenches.

<u>Dust</u>: Met requirements.

#### **Deviations from CQA Plan**

## ISSUES AND/OR ITEMS OF DISCUSSION

CAMU: Burrowing Owls still on site.(4).

CAMU: Thunderstorm impact to be determined more tomorrow.

|   |              | Develope of Well | - 1 |
|---|--------------|------------------|-----|
| Name  | Organization | Purpose of Visit |     |
|   |              |                  |     |
|   |              |                  |     |
|   |              |                  |     |
|   |              |                  |     |
| AAAPA TII TII TAA AAA AA A |              |                  |     |
|   |              |                  |     |
|   |              |                  |     |
|   |              |                  | -   |
|   |              |                  |     |
|   |              |                  |     |
|   |              |                  |     |
|   |              |                  |     |
|   |              |                  | -   |

Report Prepared By / Title

Date Prepared

Signature

3 of 3

Dick Laubinger, Construction Manager

25-Aug-08

# Basic Remediation Company 875 West Warm Springs Road Henderson, Nevada 89011

# **DAILY PRODUCTION & QUALITY CONTROL REPORT**

| Project No./Contract No. | Project Title / Location                    | Day of Report | Report No. |
|--------------------------|---|---------------|------------|
| 6389                     | BRC Eastside Common Areas Soils Remediation | 25-Aug-08     | 57         |
| 0                        | 0   | 20 / lag 00   | 0,         |

# DAILY PHOTO LOG




Photo 2 Eastside: SW-12 Pond. Water storage.

Photo 3




Photo 4 CAMU, Phase 1 after thunderstorm.

1 of 1 Ver 1.1 11/07