

N Y

Ν

DAILY PRODUCTION & QUALITY CONTROL REPORT Day of Report Report No. Project No./Contract No. Project Title / Location 6389 **BRC Eastside Common Areas Soils Remediation** 64 01-Sep-08

PROJECT POINTS OF CONTACT					
Position	Name	E ₁ Mail Address	Phone No.		
BRC PROJECT MANAGER	Lee Farris,	lfarris@landwellco.com	702-567-0400		
BRC PROJECT MANAGER	Ranajit Sahu,	sahuron@earthlink.net	702-567-0400		
CONST. PROJECT MANAGER	Dan Brennecke	Dan.Brennecke@westonsolutions.	970-260-5886		
Construction Manager	Richard Laubinger	Richard.Laubinger@westonsolutio	720-641-8660		

Conditions		Temp (F)		Wind		Add'l Readings			
			OlI	Low	68			Precip. (In/Dy.)	
AM	Cloudy	PM	Cloudy	High	92	WNW	17mph	Humidity (%)	

Additional Weather Comments			
Wind in morning. Light wind	in afternoon.		
			or the amorphism are a superior school of
N-SITE WESTON PERSO	NNEL		
Name	Position	Trade / Work Performed	Y/N
ick Laubinger	Construction Manager	Construction Management Services.	Y
an Brennecke	Project Manager. CM	Construction Management Services.	N
Dave Gertz	Project Engineer	Construction Management Services.	N
une Laubinger	Admin Assistant	Construction Management Services.	N
inda Nations	Asst Const Manager	Construction Management Services	Y
ON-SITE GEOSYNTEC PE	RSONNEL	10. 12. P. C. C. E. L. C.	
Name	Position	Trade / Work Performed	Y/N
Vayne Wofford	QA/QC Tech	Oversight	N
Brent Barbacane	QA/QC Tech	Oversight	Υ
Jim Cox	QA/QC Supervisor	Oversight	N
Greg Corcoran	Engineer of Record	Oversight	N
Robecca Flynn	Engineer	Oversight	N
Camon Liddell	QA/QC Tech	Oversight	N
Dan Street	QA Manager	Oversight	Y
ON-SITE SUPPORT PERS			
Name	Position	Trade / Work Performed	Y/N
Doug Herlocker, Tetra Tech	Air Monitoring Specialist	Air Monitoring,	N
Becky Dano, Tetra Tech	Air Monitoring Specialist	Air Monitoring,	Y
Jerry Faucheux, Tetra Tech	Air Monitoring Specialist	Air Monitoring,	Ÿ
	J		
OVERSITE PERSONNEL			
Name	Position	Trade / Work Performed	Y/N
Scott McKeag, McGinley	Oversight	For NDEP	N
Devin Gordon, McGinley	Oversight	For NDEP	N
Dock Kim, ATC	Field Observation	For AIG	N
Ron Perry, ASW	Inspector	Liner Inspector	N
PBS&J, Survey	Surveyors		N
ON-SITE CONTRACTOR	PERSONNEL		SANCE AND A SERVICE
Name	Company	Trade / Work Performed	Y/N
Erik Geringer	Entact	Project Manager	N
Josh Carrol	Entact	Asst Project Manager	N
Russ Karnes	Entact	Eastside, Superintendent	N
Michael Carlson	Entact	Engineer	N
Joe Curilla	Entact	Health & Safety Officer	Y
Timothy Stadt	Entact	Health and Safety Technician	Y
	Entact	22 Equipment Operators & Truck Drivers	Y
Ed Long	Entact	CAMU, Superintendent	Y
	American Asphalt	Earthwork Superintendent	Y
	American Asphalt	11 Equipment Operators & Truck Drivers,	Y
Rick McIntire	Entact	CSP, Safety	N

1 of 4 Ver 1.1 11/07

Kenney Survey

Environmental Specialties,Inc Liner Superintendent Environmental Specialties,Inc 1 Liner Seamer on site.

DAILY PRODUCTION & QUALITY CONTROL REPORT

Project No./Contract No.	Project Title / Location	Day of Report	Report No	
6389	BRC Eastside Common Areas Soils Remediation	01-Sep-08	64	

ON-SITE EQUIPMENT			
Equipment	Vendor / Tag No.	Work Performed	
CAT D400E Dump Truck (2)		CAMU	
JD D400 Dump Trucks (6)		Eastside	
CAT 324D long stick excavator		CAMU	
CAT D8R Dozer with disc		Eastside	
CAT 345 excavator		Eastside	
CAT 330 Excavator		Eastside	
Case double pan scrapers.		Eastside	
CAT D6 LGP Dozer (2)		Eastside	
Water Trucks (2)		Eastside	
637/631 Cat Scrapers (6)		CAMU	
CAT 16H Grader		CAMU	
CAT D-10 Dozer		CAMU	
CAT Water Wagon		CAMU	
CAT D-6 Dozer		CAMU	
CAT 14H Grader		CAMU	
Gradall		CAMU	
Bobcat Skidsteer		CAMU	
JLG		CAMU	
CAT D4 dozer		CAMU	

MATERIAL HANDLING	G (ON-SITE DELIVERY / REMOVAL)							
Material	Vendor	QTY	UOM	Purpose	Condtn	Qtv	Verification	n Tags
GCL	CETCO	0	rolls	For CAMU	00110111			
Geocomposite	Agru	0	rolls	For CAMU				
Woven Geotextile		0	rolls	For CAMU				

WORK COMPLETED

Eastside Mixing and Drying Activity:

No Work Activity on Eastside over Holiday weekend.

CAMU Activity:

Excavation

- Northwest Detention Basin excavation - 631/637 scrapers - (0) cy. No Activity

Western Ditch. Power screener screening operations layer. Two (AAG) workers assisting in screening operation.

Entact maintained 12" clean soil cap over west haul rd and bypass rd.

Dewatered last 18" of water. Silt approx. 6" - 8" at bottom of sump. Drying out will shovel out 9/2/08.

Continued shoveling off runon silt from liner, west slope toe area.

Covered portion of Eastslope with Geotextile to meet spec.

Embankment

Phase 1 embankment, complete.

Phase 1 estimated cummulative embankment placed: 0 cy

Waste Placement

Phase 1 estimated daily waste placed: 0 cy

Phase 1 estimated cummulative waste placed: 0 cy
Phase 1 Operations Layer placed daily 64 loads, (1,152) cy,

Geosynthetics.

- Phase 1 GCL placed: 0 sf daily, 347,067 sf cummulative.

- Phase 1 Geomembrane:0 sf daily, 365,136 sf cummulative

Phase 1 Geocomposite: 0 sf daily, 327,600 sf cummulative.

Phase 1 Geotextile: (0) sf daily..

Other: Sewer realignment corridor crossroad. No Activity.

DAILY PRODUCTION & QUALITY CONTROL REPORT

Project No./Contract No.	Project Title / Location	Day of Report	Report No.
6389	BRC Eastside Common Areas Soils Remediation	01-Sep-08	64
		01-06p-00	0-1

Perimeter Fence Inspection and Repair.

No Issues..

HEALTH & SAFETY

Description of Health & Safety Actions Taken Today / Safety Inspections Conducted

Entact H&S Tailgates
Morning: Site location in the event of Emergency.

ESI, Liner Crew: One seamer on site. Repairing as needed. All weekend.

Afternoon: Hydrate.

<u>American Asphalt Tailgates</u> Morning: Two workers part of Entact safety briefing.

Safety Incidents: No Incidents.

QUALITY CONTROL

Description of Quality Control Actions Taken Today / Quality Inspections Conducted

Daily CQA Summary.

Inspected 12" capped haul roads for degradation. All areas ok.

Operations layer placement on liner. Placed until 7:30 pm. Majority of floor covered will need another day to complete. Inspected shoveling cleanup activitiy at west slope area. Much better approved floor for ops layer in cleaned areas.

ESI on site to handle minor repairs. Sewed in place temporary geotextile on east slope to meet spec.

Dust: Met requirements. Less wind.

Deviations from CQA Plan

ISSUES AND/OR ITEMS OF DISCUSSION

CAMU: Burrowing Owls, One Owl sighted.

CAMU: Operation layer until 7;30 pm.

Continued cleaning floor of silt..

VISITORS				
Name	Organization	Purpose of Visit		
				L
				 L
				 H
				 H
			-	H
			-	 r
		1		r
				L
				L
,				L
				 ŀ
				L

Report Prepared By / Title

Signature

Dick Laubinger, Construction Manager

1-Sep-08

Basic Remediation Company 875 West Warm Springs Road Henderson, Nevada 89011

DAILY PRODUCTION & QUALITY CONTROL REPORT

Project No./Contract No.	Project Title / Location	Day of Report	Report No.
6389	BRC Eastside Common Areas Soils Remediation	01-Sep-08	64
0	0	01-Оер-00	04

DAILY PHOTO LOG

Photo 1




CAMU, Phase 1, operations layer placement.

Photo 2



CAMU: Phase 1 operations layer placement progressing Northeast.

Photo 3



CAMU: operations layer placement progressing North from west side..

Photo 4



CAMU, Phase 1, Operations layer progressing west.