Basic Remediation Company 875 West Warm Springs Road Henderson, Nevada 89011



DAILY PRODUCTION & QUALITY CONTROL REPORT

| Project No./Contract No. | Project Title / Location | Day of Report | Report No |
|--------------------------|--|---------------|-----------|
| 6389 | BRC Eastside Common Areas Soils Remediation | 16-Oct-08 | 103 |
| | | 16-Oct-08 | 103 |

| PROJECT POINTS OF CO | NTACT | | |
|------------------------|-------------------|----------------------------------|--------------|
| Position | Name | E-Mail Address | Phone No. |
| BRC PROJECT MANAGER | Lee Farris, | Ifarris@landwellco.com | 702-567-0400 |
| BRC PROJECT MANAGER | Ranajit Sahu | sahuron@earthlink.net | 702-567-0400 |
| CONST. PROJECT MANAGER | Dan Brennecke | Dan.Brennecke@westonsolutions.c | 970-260-5886 |
| Construction Manager | Richard Laubinger | Richard.Laubinger@westonsolution | 720-641-8660 |

| | C | conditions | | Tem | P.(P) | Vi | /ind | Add'l Readings |
|------|-------------|------------|-------------|------|-------|----|------|-----------------|
| AM | 0 | PM | Owner/Olean | Low | 54 | | | Precip. ((n.D)) |
| 2500 | Sunny/Clear | 15.00 | Sunny/Clear | High | 84 | S | 3mph | Humidity (a) |

Calm in AM, 3 mph from the South in PM.

| Name | Position | Trade / Work Performed | Y/N |
|----------------|----------------------|-----------------------------------|-----|
| Dick Laubinger | Construction Manager | Construction Management Services. | Y |
| Dan Brennecke | Project Manager. CM | Construction Management Services. | Y |
| Dave Goertz | Project Engineer | Construction Management Services. | N |
| Richard Davis | Project Engineer | Construction Management Services. | Y |
| Chris White | Assist. Const. Mgr | Construction Management Services. | Y |
| | Assist. Const. Mgr | Construction Management Services. | |
| June Laubinger | Admin Assistant | Construction Management Services. | Y |
| | | | _ |
| | | | |
| | | | |

| RSONNEL | | |
|--|--|--|
| Position | Trade / Work Performed | Y/N |
| Design Engineer | Oversight | N |
| QA Manager | Oversight | Y |
| QA/QC Supervisor | Oversight | N |
| Engineer | Oversight | N |
| QA/QC Tech | Oversight | Y |
| QA/QC Tech | Oversight | Υ |
| QA/QC Tech | Oversight | Y |
| ONNEL | | |
| Position | Trade / Work Performed | Y/N |
| Air Monitoring Specialist | Air Monitoring, | N |
| Air Monitoring Specialist | Air Monitoring, | Y |
| Air Monitoring Specialist | Air Monitoring | N |
| | | |
| | | |
| | | |
| | | |
| Position | Trade / Work Performed | Y/N |
| Oversight | For NDEP | N |
| Oversight | For NDEP | Υ |
| Field Observation | For AIG | Y |
| Inspector | Liner Inspector | N |
| Surveyors | Surveying, Set points at North BMI landfill Northwest corner. | Y |
| Inspector | NDEP | N |
| | | |
| | | |
| A CONTRACTOR OF THE CONTRACTOR | APPLY PARAMETERS DATE DATE DATE. | Y/N |
| | | Y |
| | | Y |
| Entact | Eastside, Superintendent | Y |
| Entact | Engineer | Y |
| The state of the s | | N |
| 77277777 | | Y |
| Entact | 26 Equipment Operators & Truck Drivers | Υ |
| Entact | | Y |
| Entact | Health & Safety Officer | Y |
| Entact | CSP Safety | Y |
| TOTAL TOTAL CONTROL OF THE PARTY OF THE PART | | Ý |
| | The state of the s | Y |
| | Liner Superintendent | N |
| | Design Engineer QA Manager QA/QC Supervisor Engineer QA/QC Tech QA/QC Tech QA/QC Tech QA/QC Tech ONNEL Position Air Monitoring Specialist Air Monitoring Specialist Air Monitoring Specialist Air Monitoring Specialist Oversight Oversight Oversight Oversight Oversight Company Entact | Design Engineer QA Manager QA Manager QA/QC Supervisor Engineer QA/QC Tech QA/QC QA/QC |

Ver 1.1 11/07 1 of 4

DAILY PRODUCTION & QUALITY CONTROL REPORT

| Project No./Contract No. | Project Title / Location | Day of Report | Report No. |
|--------------------------|--|---------------|------------|
| 6389 | BRC Eastside Common Areas Soils Remediation | 16 Oct 09 | 102 |
| | | 16-Oct-08 | 103 |

| Environmental Specialties,Inc | Laborers/ Seamers | N |
|-------------------------------|-------------------|---|
| Kenney Survey | CAMU | N |
| | Eastside/CAMU | N |
| | | |
| | - 4 | |
| | | |

| Equipment | Vendor / Tag No. | Work Performed | - | _ | | _ |
|-------------------------------|--------------------|-------------------|---|-----|-----|---|
| CAT D400E Dump Truck (2) | 33,012,301,300,000 | CAMU | - | | | |
| JD D400 Dump Trucks (8) | | Eastside | | - | | |
| CAT 324D long stick excavator | | CAMU | - | - | | |
| CAT D8R Dozer with disc | | Eastside | | - 2 | | |
| CAT 345 excavator | | Eastside | | - | - 4 | |
| CAT 330 Excavator | | Eastside | | 2 | 5 9 | |
| Case double pan scrapers. | | Eastside | | - | - | |
| CAT D6 LGP Dozer (2) | | Eastside | | | | |
| Water Trucks (2) | | Eastside | | | | |
| 637/631 Cat Scrapers (6) | | CAMU | | | | |
| CAT 16H Grader | | CAMU | | | | |
| CAT D-10 Dozer | | CAMU | | | | |
| CAT Water Wagon | | CAMU | | | | |
| CAT D-6 Dozer | | CAMU | | | | |
| CAT 14H Grader | | CAMU | | | | |
| Gradall | | CAMU | | | | |
| JLG | | CAMU | | | | |
| IR Smooth drum Roller | | CAMU, Phase 1 | | | | - |
| Tenent Street Sweeper | | Eastside and CAMU | | | | |
| Bomag Smooth drum Roller | | CAMU, Phase 1 | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |

| MATERIAL HANDLING | (ON-SITE DELIVERY / REMOVA | IL) | | | | |
|-------------------|----------------------------|-------|-------|-------------------|---------------------|------|
| Material | Vendor | Today | UOM | Purpose | Delivery Verifica | tion |
| material. | Vendor | romay | OOM | ruipose | to date Qty Spe | Tags |
| GCL | CETCO | 0 | rolls | For CAMU, On site | 207 | |
| Geocomposite | Agru | 0 | rolls | For CAMU, On site | 194 | |
| Geomembrane | Agru | 0 | rolls | For CAMU, On site | 37 | |

WORK COMPLETED

Eastside Mixing and Drying Activity:

- D6 dozer spread wet material over dry ponds
- Continued pumping water from SC-1 to SW-12.
- 324 CAT excavator mixing dry soils with wet soils in dry ponds.
- Conducted dust monitoring.
- Performed decontamination of equipment.
- Spread rock at trailers.

CAMU Activity:

Excavation

- Phase II continued screening soils and placing lifts on floor. Continued working on east and south slopes.

 -Continue construction of ramp in Phase 1. Hauled prepared 1* minus screened soils, placed as operations layer on slopes.
- -Western ditch soils hauled into Phase 1. Day Shift: 220 loads @ 22 cy/loads = 4,840 cy (5) trucks.
- -Western ditch soils hauled into Phase 1. Night Shift: 126 loads @ 22 cy/loads = 2,872 cy (4) trucks. -Western ditch soils stockpile of 1" minus material loaded and placed in Phase 1. 82 loads @ 22cy/loads = 1.804 cy, (2) trucks.
- (2) D6 dozers placed western ditch soils in 12* lift. Followed by (2) vibratory rollers compacting (3) complete passes in Phase 1.
- Continued placing operations layer on West slope of Phase 1 (1" minus solls). CAT 330 excavator used to remove Woven Geotextile.
- -Conducted dust monitoring.

Embankment

- Phase 1 embankment, complete.
- Phase 1 estimated cummulative embankment placed: 0 cy

Waste Placement

000 11

- Phase 1 estimated daily waste placed: 220 loads @ 22cy/load = 4,840 cy night shift placed: 126 loads @ 22cy/load = 2,872 cy
- Phase 1 estimated cummulative waste placed: 94,614 cy. Western Ditch Soils
- Phase 1 Operations Layer placed. completed. Cumulative total: 21,662

Geosynthetics. Estimated cummulative installed quantity by Phase.

P DI 4 101 P

- Phase 1 GCL placed: 0 sf daily, 307,372 sf cummulative.
- Phase 1 Geomembrane:0 sf daily, 307,372 sf cummulative
- Phase 1 Geocomposite: 0 sf daily, 307,372 sf cummulative.
- Phase 1 Geotextile: (0) sf daily. 69,340 sf cummulative.

DAILY PRODUCTION & QUALITY CONTROL REPORT Report No. Project No./Contract No. Project Title / Location Day of Report **BRC Eastside Common Areas Soils Remediation** 6389 16-Oct-08 103 Other: GES, drill sampling Phase 4 and Phase 5 areas.

| 180 | |
|-----|--|
| | |
| | |
| | |

HEALTH & SAFETY

tion of Health & Safety Actions Taken Today / Safety Inspections Conducted

Entact H&S Tailgates

Safety Topic Eastside: Crushing Injuries.

Safety Topic CAMU: Discussed not modifying PPE in the field...

Rick McIntire, CSP on site covering for Joe Curila.

Safety Incidents: None.

Dust Incidents: None.

CONSTRUCTION QUALITY ASSURANCE & QUALITY CONTROL

Daily CQA Summary...

Monitored site haul road maintenance and construction of new 12° capped haul roads,
Monitored waste relocation and placement from the western ditch into Phase 1. Monitored proof rolling, Day and Night shifts.

Monitored phase 1 slopes as woven geotextile was removed and replaced with 1" minus operations layer soils. West and Northeast slope. Monitor screening and placement as well as slope regrading of native soils in Phase II.

Continue updating project documents and database to facilitate reporting.

Discussion of Issues / Concerns / Conversations / Topics

| SITE VISITORS | | | | |
|---------------|--------------|----------------------------|---------------|----|
| Name | Organization | Purpose of Visit | | |
| Monty Melhorn | GES | Test drilling at CAMU site | | |
| | | | \rightarrow | + |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | -4 |
| | | | | |
| | | | | - |
| | | | | |

| Report Prepared | By/ | Title |
|-----------------|-----|-------|
|-----------------|-----|-------|

Signature

...

Dick Laubinger, Construction Manager

16-Oct-08

Ver 1.1 11/07 3 of 4

Basic Remediation Company 875 West Warm Springs Road Henderson, Nevada 89011

DAILY PRODUCTION & QUALITY CONTROL REPORT

| Project No./Contract No. | Project Title / Location | Day of Report | Report No |
|--------------------------|---|---------------|-----------|
| 6389 | BRC Eastside Common Areas Soils Remediation | 16 Oct 09 | 103 |
| 0 | 0 | 16-Oct-08 | |


DAILY PHOTO LOG

Photo 1



CAMU: Phase 1 West slope operations layer placed.

Photo 2




CAMU: Phase 1 Ramp in production.

Photo 3



CAMU: Phase 1, Wast floor, looking down ramp.

Photo 4



CAMU: Phase 1. looking east at Ramp.