

										Basic'Re	PANY
	DA	AILY PF	RODU	CTION & Q	UALIT	YCC	ONTF	OL	REPO	DRT	
Proje	ct No./Contract No.	1		Project Til	tle / Locat	ion				Day of Report	Report #
	6389	BRC Eastside Common Areas Soils Remediation				15-Jan-09	186				
PROJEC	CT POINTS OF COM	NTACT									
	Position		Ne	ime	1	E-M	ail Addr	035		Phor	ie No.
BRC PRO	JECT MANAGER	Lee Farris	L.		Ifarris@	landwe	llco.co	m		702-56	7-0400
BRC PRO	JECT MANAGER	Ranajit Sa	hu		sahuro	n@eart	nlink.ne	et		the second se	57-0400
CONST. F	ONST. PROJECT MANAGER Dan Brennecke			Dan.Brennecke@westonsolutions.c			lutions.c	c 970-260-5886			
Construc	tion Manager	Richard La	aubinger		Richard	d.Laubir	nger@v	veston	solution	720-64	1-8660
AM	Sunny/Clear	3	PM	Sunny/Clear		Low	37 67			Precip. (mDy.)	
101010	Content of the Article States		0.00								
	Weather Comments					High	67	W	5mph	Humidity (%)	
Calm to	light wind in PM. E WESTON PERSO	INNEL	Positio				67			Humidity (%)	V/N
Calm to	light wind in PM. E WESTON PERSO Name	and Constant		2	ruction M	Trac	le / Wor	k Perfo		Humidity <sub>(5)</sub>	Y/N
Calm to ON-SITE Dick Lau	light wind in PM. E WESTON PERSO Name binger	Constructi	ion Mana	iger Consti	ruction Ma	Trac	le / Wor	k Perfo		Humidity <sub>(5)</sub>	Y
Calm to	light wind in PM. E WESTON PERSO Name binger nnecke	Constructi Project Ma	ion Mana anager. C	iger Constr CM Constr	ruction Ma	Trac anagem anagem	le / Wor ent Ser	k Perfo vices.		Humidity <sub>(5)</sub>	(3.92
Calm to ON-SITE Dick Lau Dan Brer	light wind in PM. WESTON PERSO Name binger necke Davis	Constructi Project Ma Project En	ion Mana anager. C ngineer	iger Constr CM Constr Constr	ruction Ma ruction Ma	Trac anagem anagem anagem	le / Wor ent Ser ent Ser ent Ser	k Perto vices. vices.		Humidity <sub>25</sub>	Y N
Calm to ON-SITE Dick Lau Dan Brer Richard I Chris Wh	light wind in PM. WESTON PERSO Name binger nnecke Davis site	Constructi Project Ma	ion Mana anager. C ngineer onst. Mgr	iger Constr CM Constr Constr Constr	ruction Ma	Trac anagem anagem anagem anagem	le / Wor ent Ser ent Ser ent Ser	k Perto vices. vices. vices.		Humidityesi	Y N Y
ON-SITE Dick Lau Dan Brer Richard I	light wind in PM. EWESTON PERSO Name binger nnecke Davis lite lodgson	Constructi Project Ma Project En Assist. Co	ion Mana anager. C ngineer inst. Mgr inst. Mgr	iger Constr CM Constr Constr Constr Constr Constr	ruction Ma ruction Ma ruction Ma	Trac anagem anagem anagem anagem anagem	la / Wor ent Sen ent Ser ent Ser ent Ser ent Ser	k Perto vices. vices. vices. vices. vices.		Humidityes	Y N Y Y

on-arre decomment	C PERSONNEL		
Name	Position	Trade / Work Performed	Y/N
Greg Corcoran	Design Engineer	Oversight	N
Dan Street	QA Manager	Oversight	Y
Jim Cox	QA/QC Supervisor	Oversight	N
Robecca Flynn	Engineer	Oversight	N
Wayne Wofford	QA/QC Tech	Oversight	N
Roland Derosier	QA/QC Tech	Oversight	Y
Camon Liddell	QA/QC Tech	Oversight	Y
Jeremy Osborn	QA/QC Tech	Oversight	Y
Victor Heredia	QA/QC Tech	Oversight	Y

Doug Herlocker, Tetra Tech	Air Monitoring Specialist	Air Monitoring	N
Becky Dano, Tetra Tech	Air Monitoring Specialist	Air Monitoring,	Y
Jerry Faucheux, Tetra Tech	Air Monitoring Specialist	Air Monitoring	N
OVERSITE PERSONNEL			الجليشي وشروها ومتازج

Name	Position	Trade / Work Performed	Y/N
Mark Eizman, ASW	Inspector	Liner Inspector	Y
Devin Gordon, McGinley	Oversight	For NDEP	Y
Dock Kim, ATC	Field Observation	For AIG	Y
Joe Ludlow, ASW	Inspector	Liner Inspector	N
Steve Morrow, ASW	Inspector	Liner Inspector	N
Brian Rakvica	Inspector	NDEP	N
PBS&J, Survey	Surveyors	Surveying, QA	N

Name	Company	Trade / Work Performed	Y/N
Erik Geringer	Entact	Project Manager	Y
Josh Carrol	Entact	Asst Project Manager	Y
Russ Karnes	Entact	Eastside, Superintendent	Y
Michael Carlson	Entact	Engineer	Y
Joe Curilla	Entact	Health & Safety Officer	Y
Timothy Stadt	Entact	Health and Safety Technician	Y
	Entact	26 Equipment Operators & Truck Drivers	Y
Ed Long	Entact	CAMU, Superintendent	Y
Lance Bruce	Entact	Health & Safety Officer	Y
Terry Harper	Entact	CAMU, Superintendent	Y
Rick McIntire	Entact	CSP, Safety	Y
Dale Walsh	Converse	CSP, Safety	Y

## DAILY PRODUCTION & QUALITY CONTROL REPORT

Project No./Contract No.	Project Title / Location Day of Report			Report No.	
6389	BRC Eastside Common Areas Soils Remediation 15-Jan-09				
Eli Blackburn	Entact	Asst Project Manager		Y	
	Environmental Specialties,Inc	1 Liner Superintendent		Y	
	Environmental Specialties,Inc	12 Laborers/ Seamers		Y	
	Kenney Survey	CAMU		N	
	ABC Survey	Eastside/CAMU, Mohawk Drive.		Y	
	_				

## ON-SITE FOURPMENT

ON-SITE EQUIPMENT	1			and the second se				
Equipment	Vendor / Tag No.			Work Performed	-		-	-
CAT D400E Dump Truck (10)	1	CAMU				-		-
JD D400 Dump Trucks (9)		Eastside	Э			-		
CAT 324D long stick excavate	n	CAMU				-	-	
CAT D8R Dozer with disc		Eastside	Э			-	-	
CAT 345 excavator, (3)		Eastsid	Э				-	
CAT 330 Excavator		Eastsid	Э				*	
Case double pan scrapers.		Eastsid	e, demo	obilized.				
CAT D6 LGP Dozer (1)		Eastsid	Ð					
Water Trucks (2)		Eastsid	э					
637/631 Cat Scrapers (2)		CAMU						
CAT 16H Grader		CAMU						
CAT D-10 Dozer		CAMU						1
CAT Water Trucks (2)		CAMU						
CAT D-6 Dozer, (2)		CAMU						
CAT 14H Grader		CAMU						
Gradall		CAMU						
JLG		CAMU						-
IR Smooth drum Roller		CAMU,	Phase	1				
Tenent Street Sweeper		Eastsid	e and C	CAMU				
Bomag Smooth drum Roller		CAMU,	Phase	1				
Chieftain 1400 Powerscreene	ar	CAMU,	screen	ing 1"& 6" minus				9
						_		
MATERIAL HANDLING (0	N-SITE DELIVERY / REMOVAL	)						
Material	Vendor	Today	UOM	Purpose	to date	Oty	Verification	Tags
GCL	CETCO	0	rolls	For CAMU, On site	TO DALE	830	0,020	1 443
Geocomposite	Agru	54	rolls	For CAMU, On site	-	886	-	
Geomembrane	Agru	0	rolls	For CAMU, On site		258		

## WORK COMPLETED

Eastside Mixing and Drying Activity:

### Day Shift:

- Continued pushing up/stockpiling/drying material in SW Ponds.

 Continued pumping water from SW-7 to SW-72.
 Continued xcavation in PUB-5 below the design grade. Inspected by Weston, inspector observed additional contamination. Entact directed to continue removing up to 3 ' of material only as needed.

- Continue hauling dry material from PUB-5 to SW ponds for mixing.

Night Shift:

Continue hauling material from HP-3/HP-2 and PUA-4.

#### CAMU Activity:

- Day Shift:

- ESI continued placing geosynthetics on N. BMI Landfill.
- Continued excavating contaminated soil from NW basin/Phase IIIB and placing in Phase I & II.
  Continued screening cover soils for N. BMI Landfill from 200,000 cy stockpile.
  Continued hauling/placing 1\* and 6\* minus cover soils on N. BMI Landfill.

- Continued grading in Phase IIIA. Working south slope.
  Continued scrape of Phase IIIB, IV, and V. and haul material to Phase II.

Night Shift: - Continue placing material in Phase II.

#### Embankment

#### - Phase 1 embankment, complete.

Phase 1 estimated cummulative embankment placed: 0 cy Phase II embankment , complete.

#### Waste Placement

Phase 1 estimated daily waste placed, (Phase IIIB Trench): 31 loads @ 20 cy/load = 620 cy. (2 trucks).
 night shift placed: (0) loads @ 18cy/load = 0 cy.

Phase 1 estimated cummulative waste placed: 292,780 cy.

- Phase 1 Operations Layer placed. completed. Cumulative total: 21,662 Phase 2 estimated night shift placed: 266 loads @ 18cy/load = 5,148 cy, (19 trucks). Phase 2 estimated day shift placed: 49 loads @ 20 cy/load = 980 cy (Phase IV & V Scrape). (2 trucks). Phase 2 estimated day shift placed: dblk-0 cy. Cumulative total: 27,198 cy.

	ILY PRODUCTION & QUALITY CONT	ROL REPO	онг	
Project No./Contract No.	Project Title / Location		Day of Report	Report No
6389	BRC Eastside Common Areas Soils Remed	lation	15-Jan-09	186
	ced. daily: 0 cy. Cumulative total: 37,188 cy. ve waste placed: 87,094 cy.			
Phase 1 GCL placed:0 sf daily Phase 1 Geomembrane:0 sf d Phase 1 Geocomposite: 0 sf Phase 1 Geotextile: (0) sf dai hase 2 GCL placed: (0) sf da hase 2 Geomenbrane: (0) sf	ally, 307,372 sf cummulative daily, 3,372 sf cummulative. Iy, 69,340 sf cummulative. ily, 498,468 sf cummulative. daily, 498,468 sf cummulative. daily, 520,592 sf cummulative.			
EALTH & SAFETY				
tact H&S Tallgates	ions Taken Today / Sulety Inspections Conducted			
	Varmer temperatures and biological hazards. armer temperatures and biological hazards.			
	on't feed wild animals on the jobsite.			
fety Incidents: None.	no en anter contrata de la contra de la contra de la contra de la contrata de la contra de la contra de la contr			
ist Incidents: None.				
ONSTRUCTION QUALITY	ASSURANCE & QUALITY CONTROL			
onitor screening operations a onitor the installation of cove onitor subgrade preparation a ontinue review of and updatir onitored the inventory and de	r soil at the N. BMI Landfill. at Phase IIIA. ng of project documents and database to facilitate reporting.			
SUES AND/OR ITEMS OF scussion of Issues / Concerns /				
TE VISITORS				
TE VISITORS Name	Organization Purpose	of Visit		
A CONTRACTOR OF THE OWNER OWNE	Organization Purpose	of Viait		
A CONTRACTOR OF THE OWNER OF THE	Organization Purpose	of Viait		
A CONTRACTOR OF THE OWNER OF THE	Organization Purpose	of Visit		
A CONTRACTOR OF THE OWNER OF THE	Organization Purpose	of Viait		
Constant of the local data of	Organization Purpose	of Visit		
ITE VISITORS Name	Organization Purpose	of Visit		
Contraction of the local data in the local data	Organization Purpose	of Visit		

Ver 1.1 11/07

# Basic Remediation Company 875 West Warm Springs Road Henderson, Nevada 89011

DAILY PRODUCTION & QUALITY CONTROL REPORT					
Project No./Contract No.	Project Title / Location	Day of Report	Report No.		
<b>6389</b> 0	BRC Eastside Common Areas Soils Remediation 0	15-Jan-09	186		

## DAILY PHOTO LOG

Photo 1



CAMU: NW Basin/Phase IIIB trench excavation, looking Northwest.

Photo 2



Photo 3



CAMU: North BMI Landfill liner installation.

Photo 4



Eastside: PUB-5 additional excavation.

.