

DAILY PRODUCTION & QUALITY CONTROL REPORT

Project No./Contract No.	Project Title / Location	Day of Report	Report No.
6389	BRC Eastside Common Areas Soils Remediation	08-Dec-09	509

- Work was shut down approx. 10:30 pm, due to weather.

CAMU Activity:

Day Shift:

- Graded waste in Phase I, Phase II, Phase III and Phase IV.
- Placed interim cover on Phase I and Phase II.

Night Shift:

- Placed material in Phase III, Phase IV, Phase V.
- Work was shut down approx. 10:30 pm, due to weather.

Embankment:

- Phase I embankment, complete.
- Phase 1 estimated cumulative embankment placed:
- Phase II embankment, complete.

Sump/Vadose Monitoring:

Phase I: LCRS Sump: Measurement taken: (N/A) Water Pumped: (N/A)
 Vadose: Measurement taken: (N/A) Water Pumped: (N/A).

Phase II: LCRS Sump: Measurement taken: (N/A) Water Pumped: (N/A).
 Vadose: Measurement taken: (N/A) Water Pumped: (N/A).

Phase III: LCRS Sump: Measurement taken: (N/A) Water Pumped: (N/A).
 Vadose: Measurement taken: (N/A) Water Pumped: (N/A).

Phase V: LCRS Sump: Measurement taken: (N/A) Water Pumped: (N/A).
 Vadose: Measurement taken: (N/A) Water Pumped: (N/A).

Inspections: CAMU: N/A.

Eastside: Fence perimeter inspected, all secure.

Estimated Waste Placement (Estimated volumes do not account for shrinkage due to loss of moisture on wet ponds)

Phase I	Previous Daily Cumulative =	372,886	cy
	Operations layer placed (completed) for liner certification. = 21,662	0	cy
	Daily Day shift waste placed today: Galleria/Eastside, (0) loads @ 17 cy/load (0) trucks =		cy
	Daily Night shift placed today: (0) loads @ 21cy/load (0) trucks =		cy
	To Date Phase I estimated cumulative waste placed =	372,886	cy
Phase II	Previous Daily Cumulative =	958,365	cy
	Operations layer placed (completed) for liner certification. = 37,188		cy
	Daily Day shift waste placed today: Galleria Scrape, (0) loads @ 17 cy/load (0) trucks =		cy
	Daily Day shift waste placed today: Eastside Waste, (0) loads @ 17cy/load (0) trucks =		cy
	Daily Night shift placed today: (0) loads @ 21 cy/load (0) trucks =		cy
	To Date Phase II estimated cumulative waste placed =	958,365	cy
Phase IIIA	Previous Daily Cumulative =	222,174	cy
	Operations layer placed directly in Phase IIIA today: (0) loads @ 18 cy/load (0) trucks =		cy
	Operations layer placed (completed for liner certification = 21,276)		cy
	Daily Day shift waste placed today: (0) loads @ 17 cy/load (0) trucks =		cy
	Daily Night shift waste placed today: (0) loads @ 21cy/load (0) trucks =		cy
	To Date Phase IIIA estimated cumulative waste placed =	222,174	cy
Phase IIIB	Previous Daily Cumulative =	377,366	cy
	Operations layer placed (completed) for liner certification. = 21,978		cy
	Daily Day shift waste placed from: Galleria/Eastside (0) loads @ 17 cy/load (0) trucks =		cy
	Daily Night shift waste placed today: (27) loads @ 21cy/load (8) trucks =	567	cy
	To Date Phase IIIB estimated cumulative waste placed =	377,933	cy
Phase IV	Previous Daily Cumulative =	289,262	cy
	Operations layer placed (completed) for liner certification = 37,314		cy
	Daily Day shift waste placed today: (0) loads @ 17 cy/load (0) trucks =		cy
	Daily Night shift waste placed today: (92) loads @ 21cy/load (17) trucks =	1,932	cy
	To Date Phase IV estimated cumulative waste placed =	291,194	cy
Phase V	Previous Daily Cumulative =	197,785	cy
	Operations layer placed (completed) for liner certification = 40,284		cy
	Daily Day shift waste placed from: Galleria/Eastside (0) loads @ 17 cy/load (0) trucks =		cy
	Daily Night shift waste placed today: (2) loads @ 21cy/load (1) trucks =	42	cy
	To Date Phase V estimated cumulative waste placed =	197,827	cy
10/31/09 Volume Adjustment to Correlate with Eastside Excavation Survey		261,799	cy

Cumulative Total To Date All Phases =	2,682,178	cy
	Estimated Waste at Completion (cy)	2,800,000
		% Complete 95.8%

Geosynthetics Placed

Phase I (complete)	Previous	Placed	Cumulative Placed
GCL	307,372	0	307,372
Geomembrane	307,372	0	307,372
Geocomposite	307,372	0	307,372
Geotextile	69,340	0	69,340
Phase II (complete)			
GCL	498,468	0	498,468
Geomembrane	498,468	0	498,468
Geocomposite	520,592	0	520,592
Geotextile	0	0	0
Phase IIIA			
GCL	221,000	0	221,000
Geomembrane	221,000	0	221,000
Geocomposite	221,000	0	221,000
Geotextile	20,000	0	20,000
Phase IIIB			
GCL	340,535	0	340,535
Geomembrane	340,535	0	340,535
Geocomposite	340,535	0	340,535
Geotextile	50,000	0	50,000
Phase IV			
GCL	459,942	0	459,942
Geomembrane	459,942	0	459,942
Geocomposite	459,952	0	459,952
Geotextile	12,390	0	12,390
Phase V			
GCL	558,653	0	558,653

Basic Remediation Company

875 West Warm Springs Road
Henderson, Nevada 89011

DAILY PRODUCTION & QUALITY CONTROL REPORT

Project No./Contract No.	Project Title / Location	Day of Report	Report No.
6389 0	BRC Eastside Common Areas Soils Remediation 0	08-Dec-09	509

DAILY PHOTO LOG

Photo 1



Eastside: Galleria scrape, Parcel 2.

Photo 2



CAMU: Phase IIIB, interim cover.

Photo 3



CAMU: Phase IV, north slope, interim cover placement.

Photo 4



Eastside: SW-12.