

DAILY PRODUCTION & QUALITY CONTROL REPORT

| | | | |
|--------------------------|---|---------------|------------|
| Project No./Contract No. | Project Title / Location | Day of Report | Report No. |
| 6389 | BRC Eastside Common Areas Soils Remediation | 28-Dec-09 | 526 |

- Hauled material from CTR-1 and Beta Ditch stockpiles.

CAMU Activity:

- Day Shift
 - Phase IIIB, continued interim cover placement.
 - Galleria scrape, continued placing material in Phase V.
 - Phase I, Phase II and Phase IIIB, continued finish grading interim cover.
 - Began crushing rock for side slopes.

- Night Shift:
 - Placed material in Phase IIIB and Phase IV.

Embankment
 - Phase I embankment, complete.
 - Phase I estimated cumulative embankment placed:
 - Phase II embankment, complete.

Sump/Vadose Monitoring:

Phase I: LCRS Sump: Measurement taken: (N/A) Water Pumped: (N/A).
 Vadose: Measurement taken: (N/A) Water Pumped: (N/A).

Phase II: LCRS Sump: Measurement taken: (N/A) Water Pumped: (N/A).
 Vadose: Measurement taken: (N/A) Water Pumped: (N/A).

Phase IIIB: LCRS Sump: Measurement taken: (N/A) Water Pumped: (N/A).
 Vadose: Measurement taken: (N/A) Water Pumped: (N/A).

Phase V: LCRS Sump: Measurement taken: (N/A) Water Pumped: (N/A).
 Vadose: Measurement taken: (N/A) Water Pumped: (N/A).

Inspections: CAMU: N/A.

Eastside: Inspected eastside perimeter fence line, All secure.

Estimated Waste Placement (Estimated volumes do not account for shrinkage due to loss of moisture on wet ponds)

| | | | |
|---|--|------------------|-----------|
| Phase I | Previous Daily Cumulative = | 372,886 | cy |
| | Operations layer placed (completed) for liner certification. = 21,662 | 0 | cy |
| | Daily Day shift waste placed today: Galleria/Eastside, (0) loads @ 17 cy/load (0) trucks = | | cy |
| | Daily Night shift placed today: (0) loads @ 21cy/load (0) trucks = | | cy |
| | To Date Phase I estimated cumulative waste placed = | 372,886 | cy |
| Phase II | Previous Daily Cumulative = | 1,072,405 | cy |
| | Operations layer placed (completed) for liner certification. = 37,188 | | cy |
| | Daily Day shift waste placed today: Galleria Scrape, (0) loads @ 17 cy/load (0) trucks = | | cy |
| | Daily Day shift waste placed today: Eastside Waste, (0) loads @ 17cy/load (0) trucks = | | cy |
| | Daily Night shift placed today: (0) loads @ 21 cy/load (0) trucks = | | cy |
| | To Date Phase II estimated cumulative waste placed = | 1,072,405 | cy |
| Phase IIIA | Previous Daily Cumulative = | 222,174 | cy |
| | Operations layer placed directly in Phase IIIA today: (0) loads @ 18 cy/load (0) trucks = | | cy |
| | Operations layer placed (completed for liner certification = 21,276) | | cy |
| | Daily Day shift waste placed today: (0) loads @ 17 cy/load (0) trucks = | | cy |
| | Daily Night shift waste placed today: (0) loads @ 21cy/load (0) trucks = | | cy |
| | To Date Phase IIIA estimated cumulative waste placed = | 222,174 | cy |
| Phase IIIB | Previous Daily Cumulative = | 438,371 | cy |
| | Operations layer placed (completed) for liner certification. = 21,978 | | cy |
| | Daily Day shift waste placed from: Galleria/Eastside (0) loads @ 17 cy/load (0) trucks = | | cy |
| | Daily Night shift waste placed today: (3) loads @ 21cy/load (1) trucks = | 63 | cy |
| | To Date Phase IIIB estimated cumulative waste placed = | 438,434 | cy |
| Phase IV | Previous Daily Cumulative = | 344,450 | cy |
| | Operations layer placed (completed) for liner certification = 37,314 | | cy |
| | Daily Day shift waste placed today: (0) loads @ 17 cy/load (0) trucks = | | cy |
| | Daily Night shift waste placed today: (374) loads @ 21cy/load (19) trucks = | 7,854 | cy |
| | To Date Phase IV estimated cumulative waste placed = | 352,304 | cy |
| Phase V | Previous Daily Cumulative = | 272,477 | cy |
| | Operations layer placed (completed) for liner certification = 40,284 | | cy |
| | Daily Day shift waste placed from: Galleria/Eastside (27) loads @ 17 cy/load (2) trucks = | 459 | cy |
| | Daily Night shift waste placed today: (0) loads @ 21cy/load (0) trucks = | | cy |
| | To Date Phase V estimated cumulative waste placed = | 272,936 | cy |
| 11/01/09 Volume Adjustment to Correlate with CAMU Placement Survey | | 123,750 | cy |

| | | | |
|--|------------------------------------|-----------|------------------|
| Cumulative Total To Date All Phases = | 2,854,889 | cy | |
| | Estimated Waste at Completion (cy) | 2,900,000 | % Complete 98.4% |

Geosynthetics Placed

| Phase I (complete) | Previous | Placed | Cumulative Placed |
|----------------------------|----------|--------|-------------------|
| GCL | 307,372 | 0 | 307,372 |
| Geomembrane | 307,372 | 0 | 307,372 |
| Geocomposite | 307,372 | 0 | 307,372 |
| Geotextile | 69,340 | 0 | 69,340 |
| Phase II (complete) | | | |
| GCL | 498,468 | 0 | 498,468 |
| Geomembrane | 498,468 | 0 | 498,468 |
| Geocomposite | 520,592 | 0 | 520,592 |
| Geotextile | 0 | 0 | 0 |
| Phase IIIA | | | |
| GCL | 221,000 | 0 | 221,000 |
| Geomembrane | 221,000 | 0 | 221,000 |
| Geocomposite | 221,000 | 0 | 221,000 |
| Geotextile | 20,000 | 0 | 20,000 |
| Phase IIIB | | | |
| GCL | 340,535 | 0 | 340,535 |
| Geomembrane | 340,535 | 0 | 340,535 |
| Geocomposite | 340,535 | 0 | 340,535 |
| Geotextile | 50,000 | 0 | 50,000 |
| Phase IV | | | |
| GCL | 459,942 | 0 | 459,942 |
| Geomembrane | 459,942 | 0 | 459,942 |
| Geocomposite | 459,952 | 0 | 459,952 |
| Geotextile | 12,390 | 0 | 12,390 |
| Phase V | | | |
| GCL | 558,653 | 0 | 558,653 |

Basic Remediation Company


875 West Warm Springs Road
Henderson, Nevada 89011

DAILY PRODUCTION & QUALITY CONTROL REPORT

| Project No./Contract No. | Project Title / Location | Day of Report | Report No. |
|--------------------------|--|---------------|------------|
| 6389 0 | BRC Eastside Common Areas Soils Remediation 0 | 28-Dec-09 | 526 |

DAILY PHOTO LOG

Photo 1



CAMU: Phase I, east slope.

Photo 2



Phase I, east slope.

Photo 3



CAMU: Phase IIIB.

Photo 4



Galleria Scrape, Parcel 7.