

### DAILY PRODUCTION & QUALITY CONTROL REPORT

Project No./Contract No.	Project Title / Location	Day of Report	Report No.
6389	<b>BRC Eastside Common Areas Soils Remediation</b>	24-Nov-08	<b>141</b>

#### PROJECT POINTS OF CONTACT

Position	Name	E-Mail Address	Phone No.
BRC PROJECT MANAGER	Lee Farris	<a href="mailto:lfarris@landwellco.com">lfarris@landwellco.com</a>	702-567-0400
BRC PROJECT MANAGER	Ranjit Sahu	<a href="mailto:sahuron@earthlink.net">sahuron@earthlink.net</a>	702-567-0400
CONST. PROJECT MANAGER	Dan Brennecke	<a href="mailto:Dan.Brennecke@westonsolutions.com">Dan.Brennecke@westonsolutions.com</a>	970-260-5886
Construction Manager	Richard Laubinger	<a href="mailto:Richard.Laubinger@westonsolution.com">Richard.Laubinger@westonsolution.com</a>	720-641-8660

#### WEATHER CONDITIONS

Conditions				Temp (°F)		Wind		Add'l Readings	
AM	Sunny / Party Cloudy	PM	Sunny / Party Cloudy	Low	45	SW	3mph	Precip. (in.)(%)	Humidity (%)
				High	69				

*Additional Weather Comments*

0 mph, in AM. Light Winds in PM.

#### ON-SITE WESTON PERSONNEL

Name	Position	Trade / Work Performed	Y/N
Dick Laubinger	Construction Manager	Construction Management Services.	Y
Dan Brennecke	Project Manager, CM	Construction Management Services.	N
Richard Davis	Project Engineer	Construction Management Services.	Y
Chris White	Assist. Const. Mgr	Construction Management Services.	Y
Wayne Hodgson	Assist. Const. Mgr	Construction Management Services.	Y
Kevin Cooke	Assist. Const. Mgr	Construction Management Services.	Y
June Laubinger	Admin Assistant	Construction Management Services.	Y

#### ON-SITE GEOSYNTEC PERSONNEL

Name	Position	Trade / Work Performed	Y/N
Greg Corcoran	Design Engineer	Oversight	N
Dan Street	QA Manager	Oversight	Y
Jim Cox	QA/QC Supervisor	Oversight	Y
Robecca Flynn	Engineer	Oversight	N
Wayne Wofford	QA/QC Tech	Oversight	N
Brent Barbacane	QA/QC Tech	Oversight	Y
Camon Liddell	QA/QC Tech	Oversight	Y
Jeremy Osborn	QA/QC Tech	Oversight	Y
Roland Derosier	QA/QC Tech	Oversight	N

#### ON-SITE SUPPORT PERSONNEL

Name	Position	Trade / Work Performed	Y/N
Doug Herlocker, Tetra Tech	Air Monitoring Specialist	Air Monitoring.	N
Becky Dano, Tetra Tech	Air Monitoring Specialist	Air Monitoring.	Y
Jerry Faucheux, Tetra Tech	Air Monitoring Specialist	Air Monitoring	N

#### OVERSITE PERSONNEL

Name	Position	Trade / Work Performed	Y/N
Mark Eizman, ASW	Inspector	Liner Inspector	Y
Devin Gordon, McGinley	Oversight	For NDEP	Y
Dock Kim, ATC	Field Observation	For AIG	Y
Joe Ludlow, ASW	Inspector	Liner Inspector	N
Steve Morrow, ASW	Inspector	Liner Inspector	N
Brian Rakvica	Inspector	NDEP, Site visit	N
PBS&J, Survey	Surveyors	Surveying, QA	Y

#### ON-SITE CONTRACTOR PERSONNEL

Name	Company	Trade / Work Performed	Y/N
Erik Geringer	Entact	Project Manager	Y
Josh Carrol	Entact	Asst Project Manager	Y
Russ Karnes	Entact	Eastside, Superintendent	Y
Michael Carlson	Entact	Engineer	Y
Joe Curilla	Entact	Health & Safety Officer	Y
Timothy Stadt	Entact	Health and Safety Technician	Y
		14 Equipment Operators & Truck Drivers	Y
Ed Long	Entact	CAMU, Superintendent	N
Lance Bruce	Entact	Health & Safety Officer	Y
Terry Harper	Entact	CAMU, Superintendent	Y
Rick McIntire	Entact	CSP, Safety	N
Dale Walsh	Converse	CSP, Safety	N

## DAILY PRODUCTION & QUALITY CONTROL REPORT

Project No./Contract No.	Project Title / Location	Day of Report	Report No.
6389	<b>BRC Eastside Common Areas Soils Remediation</b>	24-Nov-08	<b>141</b>

Equipment	Vendor / Tag No.	Work Performed	Y	N
	Environmental Specialties, Inc	1 Liner Superintendent	Y	
	Environmental Specialties, Inc	12 Laborers/ Seamers	Y	
	Kenney Survey	CAMU		N
	ABC Survey	Eastside/CAMU	Y	

### ON-SITE EQUIPMENT

Equipment	Vendor / Tag No.	Work Performed	Y	N
CAT D400E Dump Truck (2)		CAMU	-	-
JD D400 Dump Trucks (8)		Eastside	-	-
CAT 324D long stick excavator		CAMU	-	-
CAT D8R Dozer with disc		Eastside	-	-
CAT 345 excavator		Eastside	-	-
CAT 330 Excavator		Eastside	-	-
Case double pan scrapers.		Eastside	-	-
CAT D6 LGP Dozer (2)		Eastside	-	-
Water Trucks (2)		Eastside	-	-
637/631 Cat Scrapers (6)		CAMU	-	-
CAT 16H Grader		CAMU	-	-
CAT D-10 Dozer		CAMU	-	-
CAT Water Wagon		CAMU	-	-
CAT D-6 Dozer		CAMU	-	-
CAT 14H Grader		CAMU	-	-
Gradall		CAMU	-	-
JLG		CAMU	-	-
IR Smooth drum Roller		CAMU, Phase 1	-	-
Tenent Street Sweeper		Eastside and CAMU	-	-
Bomag Smooth drum Roller		CAMU, Phase 1	-	-

### MATERIAL HANDLING (ON-SITE DELIVERY / REMOVAL)

Material	Vendor	Today	UOM	Purpose	Delivery Verification			
					to date	Qty	Spec	Tags
GCL	CETCO	0	rolls	For CAMU, On site		495		
Geocomposite	Agru	54	rolls	For CAMU, On site		518		
Geomembrane	Agru	0	rolls	For CAMU, On site		192		

### WORK COMPLETED

*Description of Work Executed Today*

**Eastside Mixing and Drying Activity:**

- Day Shift:
  - Continued screening moisture conditioned material using powerscreen (PUB-3)
  - Worked on tarps and rails for haul trucks
  - Prepared areas for night haul operations.
- Night Shift:
  - Continued hauling 1" minus screened material to Phase II.

**CAMU Activity:**

**Excavation .**

- Day Shift:
  - ESI continued placing geocomposite and GCL in Phase II.
  - Continued backfill of anchor trench in Phase II.
  - Spread operations layer in Phase II.
  - Continued working on LCRS pipe and rock installation.
  - Unloaded geosynthetics.
  - Prepared for night haul operations.
- Night Shift:
  - Continued placing operations layer in Phase II.
  - Continued deploying liner on east slope in Phase II until 12 AM.

**Embankment**

- Phase 1 embankment, complete.
- Phase 1 estimated cumulative embankment placed: 0 cy

**Waste Placement**

- Phase 1 estimated daily waste placed: 0 loads @ 20cy/load = 0 cy.
- night shift placed: 0 loads @ 20cy/load = 0 cy.
- Phase 1 estimated cumulative waste placed: 199,838 cy. Western Ditch, NE Equilization, Eastside beta stockpile and PUA-4.PUB-3.
- Phase 1 Operations Layer placed. completed. Cumulative total: 21,662
- Phase 2 estimated night shift placed: 188 loads @ 20cy/load = 3,760 cy. (12 trucks hauling).
- Phase 2 Operations Layer placed. daily: 3,760 cy. Cumulative total: 15,760 cy.



# Basic Remediation Company

875 West Warm Springs Road  
Henderson, Nevada 89011

## DAILY PRODUCTION & QUALITY CONTROL REPORT

Project No./Contract No.	Project Title / Location	Day of Report	Report No.
6389 0	BRC Eastside Common Areas Soils Remediation 0	24-Nov-08	141

### DAILY PHOTO LOG

Photo 1



CAMU: Phase II, Geocomposite installation and operations layer grading.

Photo 2



Eastside: 1" minus stockpile on level area.

Photo 3



CAMU: Phase II operation layer grading for night shift.

Photo 4



CAMU: Operation Layer pushing out east parallel with LCRS pipe system. Watching oversight is Entact, Geosyntec and Weston.