



**DAILY PRODUCTION & QUALITY CONTROL REPORT**

Project No./Contract No.	Project Title / Location	Day of Report	Report No.
6389	BRC Eastside Common Areas Soils Remediation	19-Jul-09	369

**CAMU Activity:**

**- Day Shift**  
- No Activity.

**- Night Shift**  
- Continued placing operations material in Phase IV.

**Embankment**  
- Phase I embankment, complete.  
- Phase I estimated cumulative embankment placed:  
- Phase II embankment, complete.

**Sump/Vadose Monitoring:** Phase I: LCRS Sump: Measurement taken: (NA) Water Pumped: (NA).  
Vadose: Measurement taken: (NA) Water Pumped: (NA).  
Phase II: LCRS Sump: Measurement taken: (NA) Water Pumped: (NA).  
Vadose: Measurement taken: (NA) Water Pumped: (NA).  
Phase IIIB: LCRS Sump: Measurement taken: (NA) Water Pumped: (NA).  
Vadose: Measurement taken: (NA) Water Pumped: (NA).

**Inspections:** CAMU: Weston monitored sump access. N/A.  
Eastside: Inspected perimeter fence. N/A.

**Estimated Waste Placement (Estimated volumes do not account for shrinkage due to loss of moisture on wet ponds)**

<b>Phase I</b>	Previous Daily Cumulative =	291,200 cy
	Operations layer placed (completed) for liner certification. = 21,662	0 cy
	Daily Day shift waste placed today: Phase IV,V scape & Phase IIIB trench excavation. 0 loads @ 20 cy/load (0 trucks) =	0 cy
	Daily Night shift placed today: 0 loads @ 18cy/load (0 trucks) =	0 cy
	<b>To Date Phase I estimated cumulative waste placed =</b>	<b>291,200 cy</b>
<b>Phase II</b>	Previous Daily Cumulative =	812,872 cy
	Operations layer placed (completed) for liner certification. = 37,188	0 cy
	Daily Day shift waste placed today: ( ) loads @ 18 cy/load ( ) trucks =	0 cy
	Daily Day shift waste placed today: Slit Trenches, (0) loads @ 18cy/load (0) trucks =	0 cy
	Daily Night shift placed today: (0) loads @ 18cy/load (0) trucks =	0 cy
	<b>To Date Phase II estimated cumulative waste placed =</b>	<b>812,872 cy</b>
<b>Phase IIIA</b>	Previous Daily Cumulative =	217,188 cy
	Operations layer placed directly in Phase IIIA today: (0) loads @ 18 cy/load (0) trucks =	0 cy
	Operations layer placed (completed for liner certification = 21,276)	0 cy
	Daily Day shift waste placed today: From Phase IIIB. (0) loads @ 18 cy/load (0) trucks =	0 cy
	Daily Night shift waste placed today: (0) loads @ 18cy/load (0) trucks =	0 cy
	<b>To Date Phase IIIA estimated cumulative waste placed =</b>	<b>217,188 cy</b>
<b>Phase IIIB</b>	Previous Daily Cumulative =	90,126 cy
	Operations layer placed (completed) for liner certification. = 21,978	0 cy
	Daily Day shift waste placed today: From, Western Hook, (69) loads @ 18 cy/load (10) trucks =	0 cy
	Daily Night shift waste placed today: (0) loads @ 18cy/load (0) trucks =	0 cy
	<b>To Date Phase IIIB estimated cumulative waste placed =</b>	<b>90,126 cy</b>
<b>Phase IV</b>	Previous Daily Cumulative =	27,612 cy
	Operations layer placed directly in Phase IV today: (191) loads @ 18 cy/load (14) trucks =	3,438 cy
	Daily Day shift waste placed today: From ??, (0) loads @ 18 cy/load (0) trucks =	0 cy
	Daily Night shift waste placed today: (0) loads @ 18cy/load (0) trucks =	0 cy
	<b>To Date Phase IV estimated cumulative waste placed =</b>	<b>31,050 cy</b>
<b>Phase V</b>	Previous Daily Cumulative =	0 cy
	Operations layer placed (completed) for liner certification. = ?	0 cy
	Daily Day shift waste placed today: From ??, (0) loads @ 18 cy/load (0) trucks =	0 cy
	Daily Night shift waste placed today: (0) loads @ 18cy/load (0) trucks =	0 cy
	<b>To Date Phase V estimated cumulative waste placed =</b>	<b>0 cy</b>

<b>Cumulative Total To Date All Phases =</b>	<b>1,442,436 cy</b>	<b>Estimated Waste at Completion (cy)</b>	<b>2,050,000</b>	<b>% Complete</b>	<b>70.4%</b>
--	---------------------	---	------------------	-------------------	--------------

**Geosynthetics Placed**

	Previous	Placed	Cumulative Placed
<b>Phase I (complete)</b>			
GCL	307,372	0	307,372
Geomembrane	307,372	0	307,372
Geocomposite	307,372	0	307,372
Geotextile	69,340	0	69,340
<b>Phase II (complete)</b>			
GCL	498,468	0	498,468
Geomembrane	498,468	0	498,468
Geocomposite	520,592	0	520,592
Geotextile	0	0	0
<b>Phase IIIA</b>			
GCL	221,000	0	221,000
Geomembrane	221,000	0	221,000
Geocomposite	221,000	0	221,000
Geotextile	20,000	0	20,000
<b>Phase IIIB</b>			
GCL	340,535	0	340,535
Geomembrane	340,535	0	340,535
Geocomposite	340,535	0	340,535
Geotextile	50,000	0	50,000
<b>Phase IV</b>			
GCL	459,942	0	459,942
Geomembrane	459,942	0	459,942
Geocomposite	459,952	0	459,952
Geotextile	12,390	0	12,390
<b>Phase V</b>			
GCL	0	0	0
Geomembrane	0	0	0
Geocomposite	0	0	0
Geotextile	0	0	0



# Basic Remediation Company

875 West Warm Springs Road  
Henderson, Nevada 89011

## DAILY PRODUCTION & QUALITY CONTROL REPORT

Project No./Contract No.	Project Title / Location	Day of Report	Report No.
<b>6389</b> 0	<b>BRC Eastside Common Areas Soils Remediation</b> 0	19-Jul-09	<b>369</b>

## DAILY PHOTO LOG

Photo 1



Photo 2



Photo 3



Photo 4

