

Project No./Contract No.	Project Title / Location	Day of Report	Report No.
6389	BRC Eastside Common Areas Soils Remediation	06-Aug-09	387

Position	Name	E-Mail Address	Phone No.
BRC PROJECT MANAGER	Lee Farris	lfarris@landwellco.com	702-567-0400
BRC PROJECT MANAGER	Ranjit Sahu	sahuron@earthlink.net	702-567-0400
CONST. PROJECT MANAGER	Dan Brennecke	Dan.Brennecke@westonsolutions.com	970-260-8586
Construction Manager	Richard Laubinger	Richard.Laubinger@westonsolution.com	720-641-5866

Conditions				Temp (°F)	Wind	Add'l Readings	
AM	Sunny / Partly Cloudy		PM	Sunny / Partly Cloudy		Low 76	Precip. (in/hr) 0
				High 106	SW 13 mph		Humidity (%) 0
Additional Weather Comments							
Wind 13 mph in morning, to 24 mph in afternoon and early evening.							

[illegible]

Name	Position	Trade / Work Performed	Y/N
Greg Corcoran	Design Engineer	Oversight	Y
Dan Street	QA Manager	Oversight	Y
Jim Cox	QA/QC Supervisor	Oversight	N
Rebecca Pynn	Engineer	Oversight	N
Stuart Irwin	QA/QC Tech	Oversight	Y
Roland Derosier	QA/QC Tech	Oversight	N
Camron Liddell	QA/QC Tech	Oversight	Y
Victor Heredia	QA/QC Tech	Oversight	Y
Keith Schratte	QA/QC Tech	Oversight	Y

[illegible]

Name	Position	Trade / Work Performed	Y/N
Bob Meyer, ASW	Inspector	Liner Inspector,	Y
Devin Gordon, MGA	Oversight	For NDEP	Y
Dock Kim, ATC	Field Observation	For AIG	Y
Brian Rakiva	Inspector	NDEP	N
Steve Morrow, ASW	Inspector	Liner Inspector	N
PBS&J, Survey	Surveyors	Survey	N

[illegible][illegible]

Material	Vendor	Today	UOM	Purpose	Delivery Verification			
					to date	Qty	Spec	Tags
GCL	CETCO	0	rolls	For CAMU, On site		2271		
Geocomposite	Agru	0	rolls	For CAMU, On site		2448		
Geomembrane	Agru	0	rolls	For CAMU, On site		552		

Eastside Mixing and Drying Activity:

Day Shift:

- PUG-6, PUG-6, PUB-7 ponds, continued excavating, loading and hauling to Beta stockpile.
- 28 cubic, discharging/pushing up dried material and stockpiling.
- PUG-6 ponds, excavating and stockpiling.
- Mobilized shredder and small excavator to Western hook.
- Western Hook continued excavating/scraping and stockpiling contaminated material.
- SW-12 and H-6

DAILY PRODUCTION & QUALITY CONTROL REPORT			
Project No./Contract No.	Project Title / Location	Day of Report	Report No.
6389	BRC Eastside Common Areas Soils Remediation	06-Aug-09	387
<div><div>- Night Shift:</div><div>- Hauled material from Beta Ditch stockpile and HP-3 stockpiles.</div><div>CAMU Activity:</div><div>- Day Shift</div><div>- 42 " Storm drain pipe, continued digging out and preparing floor for manholes #1, 2, and 3 for forming.</div><div>- Jansen, concrete subcontractor on site to begin manholes.</div><div>- Phase II, grading waste on east sideslope.</div><div>- BMI South installing 6" minus cover.</div><div>- Phase V, continue grading cell floor and slopes.</div><div>- Hargis Associates on site testing new well in CAMU south of Phase V.</div><div>- Night Shift:</div><div>- Placed material in Phase II and Phase IIIB.</div><div>Embankment</div><div>- Phase I embankment, complete.</div><div>- Phase 1 estimated cumulative embankment placed:</div><div>- Phase II embankment , complete.</div><div>Sump/Vadose Monitoring</div><div>Phase I: LCRS Sump: Measurement taken: (N/A) Water Pumped : (N/A).</div><div>Vadose: Measurement taken: (N/A) Water Pumped: (N/A).</div><div>Phase II: LCRS Sump: Measurement taken: (N/A) Water Pumped: (N/A).</div><div>Vadose: Measurement taken: (N/A) Water pumped: (N/A).</div><div>Phase IIIB: LCRS Sump: Measurement taken: (NA) Water Pumped: (N/A)</div><div>Vadose: Measurement taken: (NA) Water Pumped: (N/A)</div><div>Inspections:</div><div>CAMU: Weston monitored sump access. N/A.</div><div>Eastside: Inspected perimeter fence. All secure.</div></div>			

Estimated Waste Placement (Estimated volumes do not account for shrinkage due to loss of moisture on wet ponds)

Phase I		
Previous Daily Cumulative =	291,200	cy
Operations layer placed (completed) for liner certification. = 21,662	0	cy
Daily Day shift waste placed today: Phase IV,V scape & Phase IIIB trench excavation. 0 loads @ 20		
cy/load (0 trucks) =	0	cy
Daily Night shift placed today: 0 loads @ 18cy/load (0 trucks) =	0	cy
To Date Phase I estimated cumulative waste placed =	291,200	cy
Phase II		
Previous Daily Cumulative =	828,190	cy
Operations layer placed (completed) for liner certification. = 37,188		cy
Daily Day shift waste placed today: From Western Hook (0) loads @ 18 cy/load (0) trucks =		cy
Daily Day shift waste placed today: Slit Trenches, (0) loads @ 18cy/load (0) trucks =		cy
Daily Night shift placed today: (4) loads @ 18cy/load (3) trucks =	72	cy
To Date Phase II estimated cumulative waste placed =	828,262	cy
Phase IIIA		
Previous Daily Cumulative =	222,174	cy
Operations layer placed directly in Phase IIIA today: (0) loads @ 18 cy/load (0) trucks =		cy
Operations layer placed (completed for liner certification = 21,276)		cy
Daily Day shift waste placed today: From Phase IIIB. (0) loads @ 18 cy/load (0) trucks =		cy
Daily Night shift waste placed today: (0) loads @ 18cy/load (0) trucks =		cy
To Date Phase IIIA estimated cumulative waste placed =	222,174	cy
Phase IIIB		
Previous Daily Cumulative =	154,512	cy
Operations layer placed (completed) for liner certification. = 21,978		cy
Daily Day shift waste placed today: (0) loads @ 18 cy/load (0) trucks =		cy
Daily Night shift waste placed today: (327) loads @ 18cy/load (19) trucks =	5,886	cy
To Date Phase IIIB estimated cumulative waste placed =	160,398	cy
Phase IV		
Previous Daily Cumulative =	37,314	cy
Operations layer placed (completed) for liner certification = 37,314		cy
Daily Day shift waste placed today: From ?? (0) loads @ 18 cy/load (0) trucks =		cy
Daily Night shift waste placed today: (0) loads @ 18cy/load (0) trucks =		cy
To Date Phase IV estimated cumulative waste placed =	37,314	cy
Phase V		
Previous Daily Cumulative =		cy
Operations layer placed (completed) for liner certification. = ?		cy
Daily Day shift waste placed today: From ?? (0) loads @ 18 cy/load (0) trucks =		cy
Daily Night shift waste placed today: (0) loads @ 18cy/load (0) trucks =		cy
To Date Phase V estimated cumulative waste placed =	0	cy

		Estimated Waste at	
		Completion	
		(cy)	% Complete
Cumulative Total To Date All Phases =	1,539,348	2,050,000	75.1%

Geosynthetics Placed

	Previous	Placed	Cumulative Placed
Phase I (complete)			
GCL	307,372	0	307,372
Geomembrane	307,372	0	307,372
Geocomposite	307,372	0	307,372
Geotextile	69,340	0	69,340
Phase II (complete)			
GCL	498,468	0	498,468
Geomembrane	498,468	0	498,468
Geocomposite	520,592	0	520,592
Geotextile	0	0	0
Phase IIIA			
GCL	221,000	0	221,000
Geomembrane	221,000	0	221,000
Geocomposite	221,000	0	221,000
Geotextile	20,000	0	20,000
Phase IIIB			
GCL	340,535	0	340,535
Geomembrane	340,535	0	340,535
Geocomposite	340,535	0	340,535
Geotextile	50,000	0	50,000
Phase IV			
GCL	459,942	0	459,942
Geomembrane	459,942	0	459,942
Geocomposite	459,952	0	459,952
Geotextile	12,390	0	12,390
Phase V			
GCL	0	0	0
Geomembrane	0	0	0
Geocomposite	0	0	0
Geotextile	0	0	0

DAILY PRODUCTION & QUALITY CONTROL REPORT

Project No./Contract No.	Project Title / Location	Day of Report	Report No.
6389	BRC Eastside Common Areas Soils Remediation	06-Aug-09	387

BMI North

GCL	1,111,468	0	1,111,468
Geomembrane	1,111,468	0	1,111,468
Geocomposite	1,111,468	0	1,111,468

BMI South

GCL	177,000	0	177,000
Geomembrane	177,000	0	177,000
Geocomposite	177,000	0	177,000

Debris Storage Area (complete)

Geomembrane	12,000	0	12,000
-------------	--------	---	--------

CAMU Cover

GCL	0	0	0
Geomembrane	0	0	0
Geocomposite	0	0	0

		Total Geosynthetics for CAMU Basic Scope (sf)	% Complete of Basic Scope	Total Geosynthetics for CAMU Basic Scope +Option Scope	% Complete of Basic Scope + Option Scope
Geosynthetic System Cumulative Total To Date All CAMU Phases	3,115,785	4,151,232	75.1%	6,534,075	47.7%

HEALTH & SAFETY

Description of Health & Safety Actions Taken Today / Safety Inspections Conducted

Safety Topic:

Eastside Day: Discussed behavior based safety and eye protection during windy conditions.
CAMU Day: Discussed behavior based safety and eye protection during windy conditions.
Night shift CAMU & Eastside: High wind warning, watch speed on haul roads to control dust

CONSTRUCTION QUALITY ASSURANCE & QUALITY CONTROL

Description of Quality Control Actions Taken Today / Quality Inspections Conducted

Daily CQA Summary

Monitor waste placement from the eastside into Phase II and Phase IIIB on the night shift.
Monitor construction of sideslopes and subgrade preparation in Phase V.
Monitor the installation of 6" minus cover soils on BMI South landfill.
Monitor 42" storm drain pipe backfilling and manhole preparation.

ISSUES AND/OR ITEMS OF DISCUSSION

Discussion of Issues / Concerns / Conversations / Topics

SITE VISITORS

[illegible]

Report Prepared By / Title

Richard Laubinger, Construction Manager

Date Prepared

Signature _____

6-Aug-09

Weather Table

Sunny/Clear	☀
Sunny / Party Cloudy	☀☁
Cloudy / Partly Sunny	☁☀
Cloudy	☁
Overcast	☁☁☁
Light Rain	☔
Rain	☔☔☔
Thunderstorms	⚡
Snow	❄

Basic Remediation Company

875 West Warm Springs Road
Henderson, Nevada 89011

DAILY PRODUCTION & QUALITY CONTROL REPORT

Project No./Contract No.	Project Title / Location	Day of Report	Report No.
6389 0	BRC Eastside Common Areas Soils Remediation 0	06-Aug-09	387

DAILY PHOTO LOG

Photo 1



CAMU: Phase V, South slope..

Photo 2



CAMU: Phase V, South slope.

Photo 3



CAMU: Phase IIIA.

Photo 4



CAMU: Phase IIIA.