

DAILY PRODUCTION & QUALITY CONTROL REPORT

Project No./Contract No.	Project Title / Location	Day of Report	Report No.
6389	BRC Eastside Common Areas Soils Remediation	15-Nov-09	487

CAMU Activity:
- Day Shift
 - No Activity.
- Night Shift:
 - Placed material in Phase I, Phase II, Phase IIIB, Phase IV and Phase V.
Embankment
 - Phase I embankment, complete.
 - Phase I estimated cumulative embankment placed:
 - Phase II embankment, complete.
Sump/Vadose Monitoring:
 Phase I: LCRS Sump: Measurement taken: (N/A) Water Pumped: (N/A).
 Vadose: Measurement taken: (N/A) Water Pumped: (N/A).
 Phase II: LCRS Sump: Measurement taken: (N/A) Water Pumped: (N/A).
 Vadose: Measurement taken: (N/A) Water Pumped: (N/A).
 Phase IIIB: LCRS Sump: Measurement taken: (N/A) Water Pumped: (N/A).
 Vadose: Measurement taken: (N/A) Water Pumped: (N/A).
 Phase V: LCRS Sump: Measurement taken: (N/A) Water Pumped: (N/A).
 Vadose: Measurement taken: (N/A) Water Pumped: (N/A).
Inspections: CAMU: N/A.
 Eastside: N/A.

Estimated Waste Placement (Estimated volumes do not account for shrinkage due to loss of moisture on wet ponds)

Phase I	Previous Daily Cumulative =	372,844 cy
	Operations layer placed (completed) for liner certification. = 21,662	0 cy
	Daily Day shift waste placed today: Galleria/Eastside, (0) loads @ 17 cy/load (0) trucks =	0 cy
	Daily Night shift placed today: (2) loads @ 21cy/load (1) trucks =	42 cy
	To Date Phase I estimated cumulative waste placed =	372,886 cy
Phase II	Previous Daily Cumulative =	1,071,460 cy
	Operations layer placed (completed) for liner certification. = 37,188	0 cy
	Daily Day shift waste placed today: Galleria Scrape, (0) loads @ 17 cy/load (0) trucks =	0 cy
	Daily Day shift waste placed today: Eastside Waste, (0) loads @ 17cy/load (0) trucks =	0 cy
	Daily Night shift placed today: (29) loads @ 21 cy/load (3) trucks =	609 cy
	To Date Phase II estimated cumulative waste placed =	1,072,069 cy
Phase IIIA	Previous Daily Cumulative =	222,174 cy
	Operations layer placed directly in Phase IIIA today: (0) loads @ 18 cy/load (0) trucks =	0 cy
	Operations layer placed (completed for liner certification = 21,276)	0 cy
	Daily Day shift waste placed today: (0) loads @ 17 cy/load (0) trucks =	0 cy
	Daily Night shift waste placed today: (0) loads @ 21cy/load (0) trucks =	0 cy
	To Date Phase IIIA estimated cumulative waste placed =	222,174 cy
Phase IIIB	Previous Daily Cumulative =	341,141 cy
	Operations layer placed (completed) for liner certification. = 21,978	0 cy
	Daily Day shift waste placed from: Galleria/Eastside (0) loads @ 17 cy/load (0) trucks =	0 cy
	Daily Night shift waste placed today: (119) loads @ 21cy/load (15) trucks =	2,499 cy
	To Date Phase IIIB estimated cumulative waste placed =	343,640 cy
Phase IV	Previous Daily Cumulative =	220,380 cy
	Operations layer placed (completed) for liner certification = 37,314	0 cy
	Daily Day shift waste placed today: (0) loads @ 17 cy/load (0) trucks =	0 cy
	Daily Night shift waste placed today: (180) loads @ 21cy/load (17) trucks =	3,780 cy
	To Date Phase IV estimated cumulative waste placed =	224,160 cy
Phase V	Previous Daily Cumulative =	93,016 cy
	Operations layer placed (completed) for liner certification = 40,284	0 cy
	Daily Day shift waste placed from: Galleria/Eastside (0) loads @ 17 cy/load (0) trucks =	0 cy
	Daily Night shift waste placed today: (51) loads @ 21cy/load (8) trucks =	1,071 cy
	To Date Phase V estimated cumulative waste placed =	94,087 cy

Cumulative Total To Date All Phases =	2,329,016 cy	Estimated Waste at Completion (cy)	2,700,000	% Complete	86.3%
--	---------------------	---	------------------	-------------------	--------------

Geosynthetics Placed

	Previous	Placed	Cumulative Placed
Phase I (complete)			
GCL	307,372	0	307,372
Geomembrane	307,372	0	307,372
Geocomposite	307,372	0	307,372
Geotextile	69,340	0	69,340
Phase II (complete)			
GCL	498,468	0	498,468
Geomembrane	498,468	0	498,468
Geocomposite	520,592	0	520,592
Geotextile	0	0	0
Phase IIIA			
GCL	221,000	0	221,000
Geomembrane	221,000	0	221,000
Geocomposite	221,000	0	221,000
Geotextile	20,000	0	20,000
Phase IIIB			
GCL	340,535	0	340,535
Geomembrane	340,535	0	340,535
Geocomposite	340,535	0	340,535
Geotextile	50,000	0	50,000
Phase IV			
GCL	459,942	0	459,942
Geomembrane	459,942	0	459,942
Geocomposite	459,952	0	459,952
Geotextile	12,390	0	12,390
Phase V			
GCL	558,653	0	558,653
Geomembrane	558,653	0	558,653
Geocomposite	558,653	0	558,653
Geotextile	15,925	0	15,925

Basic Remediation Company

875 West Warm Springs Road
Henderson, Nevada 89011

DAILY PRODUCTION & QUALITY CONTROL REPORT

Project No./Contract No.	Project Title / Location	Day of Report	Report No.
6389 0	BRC Eastside Common Areas Soils Remediation 0	15-Nov-09	487

DAILY PHOTO LOG

Photo 1



Photo 2



Photo 3



Photo 4

