

DAILY PRODUCTION & QUALITY CONTROL REPORT

Project No./Contract No.	Project Title / Location	Day of Report	Report No.
6389	BRC Eastside Common Areas Soils Remediation	20-Feb-10	578

CAMU Activity:

- Day Shift

- Continued power screening 1" and 6" minus soils.
- ESI continued installing geocomposite on Phase I, Phase II and Phase III ramp and west slope.
- Phase IV, continued grading and rolling north and south slope.
- Continued finish grading final cover on Phase I and Phase III.
- Continued placing 1" and 6" final cover on west slope.
- Installing CFS with drainage aggregate on ramp.
- Entact monitored sumps.

- Night Shift

No Activity.

Embankment

- Phase I embankment, complete.
- Phase I estimated cumulative embankment placed:
- Phase II embankment, complete.

Sump/Vadose Monitoring:

Phase I:	LCRS Sump: Measurement taken: (1.433)	Water Pumped: (N/A).
	Vadose: Measurement taken: (0.583)	Water Pumped: (N/A).
Phase II:	LCRS Sump: Measurement taken: (2.175)	Water Pumped: (N/A).
	Vadose: Measurement taken: (N/A)	Water pumped: (N/A).
Phase III:	LCRS Sump: Measurement taken: (N/A)	Water Pumped: (N/A).
	Vadose: Measurement taken: (N/A)	Water Pumped: (N/A).
Phase V:	LCRS Sump: Measurement taken: (1.825)	Water pumped: (450 gal).
	Vadose: Measurement taken: (N/A)	Water Pumped: (N/A).

Inspections: CAMU: N/A.

Faithrite: Fence perimeter inspected. All secure.

Estimated Waste Placement (Estimated volumes do not account for shrinkage due to loss of moisture on wet ponds)

Phase I

Previous Daily Cumulative =	372,886 cy
Operations layer placed (completed) for liner certification. = 21,662	0 cy
Daily Day shift waste placed today: Galleria/Eastside, (0) loads @ 17 cy/load (0) trucks =	cy
Daily Night shift placed today: (0) loads @ 21cy/load (0) trucks =	cy
To Date Phase I estimated cumulative waste placed =	372,886 cy

Phase II

Previous Daily Cumulative =	1,072,405 cy
Operations layer placed (completed) for liner certification. = 37,188	cy
Daily Day shift waste placed today: Galleria Scrape, (0) loads @ 17 cy/load (0) trucks =	cy
Daily Day shift waste placed today: Eastside Waste, (0) loads @ 17cy/load (0) trucks =	cy
Daily Night shift placed today: (0) loads @ 21 cy/load (0) trucks =	cy
To Date Phase II estimated cumulative waste placed =	1,072,405 cy

Phase IIIA

Previous Daily Cumulative =	222,174 cy
Operations layer placed directly in Phase IIIA today: (0) loads @ 18 cy/load (0) trucks =	cy
Operations layer placed (completed for liner certification = 21,276)	cy
Daily Day shift waste placed today: (0) loads @ 17 cy/load (0) trucks =	cy
Daily Night shift waste placed today: (0) loads @ 21cy/load (0) trucks =	cy
To Date Phase IIIA estimated cumulative waste placed =	222,174 cy

Phase IIIB

Previous Daily Cumulative =	439,547 cy
Operations layer placed (completed) for liner certification. = 21,978	cy
Daily Day shift waste placed from: Galleria/Eastside (0) loads @ 17 cy/load (0) trucks =	cy
Daily Night shift waste placed today: (0) loads @ 21cy/load (0) trucks =	cy
To Date Phase IIIB estimated cumulative waste placed =	439,547 cy

Phase IV

Previous Daily Cumulative =	482,168 cy
Operations layer placed (completed) for liner certification = 37,314	cy
Daily Day shift waste placed today: (0) loads @ 17 cy/load (0) trucks =	cy
Daily Night shift waste placed today: (0) loads @ 21cy/load (0) trucks =	cy
To Date Phase IV estimated cumulative waste placed =	482,168 cy

Phase V

Previous Daily Cumulative =	496,786 cy
Operations layer placed (completed) for liner certification = 40,284	cy
Daily Day shift waste placed from: Eastside, (0) loads @ 17 cy/load (0) trucks =	cy
Daily Night shift waste placed today: (0) loads @ 21cy/load (0) trucks =	cy
To Date Phase V estimated cumulative waste placed =	496,786 cy

11/01/09 Volume Adjustment to Correlate with CAMU Placement Survey	123,750 cy
12/31/09 Volume Adjustment to Correlate with CAMU Placement Survey	56,834 cy

Cumulative Total To Date All Phases =	3,266,550 cy	Estimated Waste at Completion (cy)	2,900,000	% Complete	112.6%
--	---------------------	---	------------------	-------------------	---------------

Geosynthetics Placed

Phase I (complete)	Previous	Placed	Cumulative Placed
GCL	307,372	0	307,372
Geomembrane	307,372	0	307,372
Geocomposite	307,372	0	307,372
Geotextile	69,340	0	69,340
Phase II (complete)			
GCL	498,468	0	498,468
Geomembrane	498,468	0	498,468
Geocomposite	520,592	0	520,592
Geotextile	0	0	0
Phase IIIA			
GCL	221,000	0	221,000
Geomembrane	221,000	0	221,000
Geocomposite	221,000	0	221,000
Geotextile	20,000	0	20,000
Phase IIIB			
GCL	340,535	0	340,535
Geomembrane	340,535	0	340,535
Geocomposite	340,535	0	340,535
Geotextile	50,000	0	50,000
Phase IV			
GCL	459,942	0	459,942
Geomembrane	459,942	0	459,942
Geocomposite	459,952	0	459,952
Geotextile	12,390	0	12,390
Phase V			

Basic Remediation Company

875 West Warm Springs Road
Henderson, Nevada 89011

DAILY PRODUCTION & QUALITY CONTROL REPORT

Project No./Contract No.	Project Title / Location	Day of Report	Report No.
6389 0	BRC Eastside Common Areas Soils Remediation 0	20-Feb-10	578

DAILY PHOTO LOG

Photo 1



CAMU: North slope.

Photo 2



CAMU: North slope.

Photo 3



CAMU: Phase IIIB, west ramp.

Photo 4



CAMU: West slope. Geocomposite.